



status report

customer:	BCA Autoauktionen GmbH
report Number:	0000001258969-EN18

vehicle data			
Peugeot 308 GT			
Vehicle identification number	VR3FPHNSTPY622977	mileage read:	23001 km
First Registration / construction year:	03.06.2024 / 2023	Visit Date / place of birth:	11.08.2025 Neuss
Bodywork:	cars	Re - import:	unknown
Body type:	small car	KBA no. :	1889//ADO
Fuel / emission class:	gasoline / € 6	transmission type:	automatic
Displacement / power:	1199 ccm / 96 kW (131 PS)	Engine:	front-wheel drive
paint:	LACKIERUNG OLIVGRÜN/TYP AUSSERVERKLEIDUNG METALLIC-LACKIERUNG	Number of previous owners:	-
Doors / seats:	5 / 5	number keys:	1
Next HU / AU:	- / -	cushion type:	Imitation leather / fabric
Service book available:	no	Interior Color:	-
smoking vehicle:	yes	Last service km / on the:	- / -
Vehicle roadworthy:	yes	Vehicle roadworthy:	no
Submitted vehicle	-	state outside:	3 - Average
documents:		condition inside:	3 - Average
visit condition:	-		
state general:	3 - Average		

Accessories (presented to the visiting time)			
GPS sat nav disk:	Fzg.Schlüssel:	Service book provided / maintained:	Last service at / on:
Hard Disk Drive	1	no / -	- / -
☒ AHK key	☒ AHK removable	☒ AHK fixed	☒ AHK swivel
☒ Fernbed . entertainment	☒ Fernbed . Auxiliary heating	☒ headphone	☒ LED headlights
☒ Load compartment cover	☒ navigation system	☒ Persenning	☒ partition net
☒ Wind Deflector	☒ Xenon headlights		

☒ **available**

☒ **not available**

Hüsges GmbH
Gießerallee 23
47877 Willich
Tel.: 02154 / 9534 0
E-Mail: gutachten@huesges-group.eu

The status report was created impartially and to the best of my knowledge. The images listed in the status report are part of the vehicle description regarding the equipment and the vehicle condition.



Hüsges Gruppe®
Die Gutachter



mounted tires

Tyre / wheel type:	summer tires	polished aluminum
1st axis - Left / states .	Metzeler	225/40/R18/92Y 3 mm
1st axis - right / states .	Metzeler	225/40/R18/92Y 3 mm
2nd axis - Left / states .	Metzeler	225/40/R18/92Y 4 mm
2nd axis - right / states .	Metzeler	225/40/R18/92Y 4 mm
traffic Safety:	roadworthy	
spare wheel:	-	
state spare wheel:	-	

standard equipment

- | | |
|--|--|
| <ul style="list-style-type: none"> • Airbag switched off • Ambient lighting LED • Anti -Slip Regulation (ASR) • Audio controls on steering wheel • Power side mirrors . anklappbar • Exterior mirror and mirror base in Perla Nera black • board computer • Drive-Assist-Paket Plus
 <i>Adaptive Geschwindigkeitsregelanlage (ACC), Fahrassistenz-System: Aktiver Notbrems-Assistent (Active Safety Brake Plus), Fahrassistenz-System: Querverkehrs-Assistent Heck (Rear Cross Traffic Alert, RCTA), Fahrassistenz-System: Totwinkel-Assistent (SAM)</i> • Off switch for headlights • Electron. Stability Program (ESP, Bosch) • Driving Assistance System hill start assist • Fahrassistenz-System Kollisionswarnsystem • Driver assistance system Fatigue detection sensor • Driver assistance system Traffic sign recognition • handsfree Bluetooth • • Illuminated glove compartment • heated rear window • Interior decor inlays in aluminium • Frameless interior mirror with automatic dimming
 <i>Innenspiegel mit Abblendautomatik</i> • Body 5-door • Parental control electrically • Head airbag system • Steering wheel (leather) • Steering wheel with shift paddles / buttons | <ul style="list-style-type: none"> • Airbag Driver / passenger side • Anti- lock braking system (ABS) • Drive Front Wheel Drive • Autom. Accompaniment function of the illumination • Power side mirrors . adjustable and heated, both • Indicator integrated into mirrors • Headliner black • Parking aid front and rear including rear view camera
 <i>Einparkhilfe hinten, Einparkhilfe vorn</i> • Electr . Brakeforce Distribution • Driver assistance system active lane assistant (steering assistance) • • Fahrassistenz-System Multikollisionsbremse (Multi Collision Brake) • Driving Assistance System Brake Assist • Electric windows front + rear with comfort control • Windscreen laminated glass • Cupholders at the front • LED Taillights
 <i>Heckleuchten LED (Beleuchtung dynamisch)</i> • Rear apron, glossy black • Interior decorative stitching colored • Isofix admissions for child seat • Map pocket on front seats • Climate control, separately adjustable driver's / passenger's side • Lumbar support front left seat , adjustable • Steering wheel with multifunction • LM rims |
|--|--|

• Matrix LED headlights <i>Leuchtweitenregelung automatisch</i> • Front center armrest • Engine 1.2 ltr. - 96 kW 12V e - THP • Navigationssystem i-Connect Advanced <i>Peugeot Connect-Box / SOS-Taste (Notruf für Lokalisierung Fahrzeug) Version 3R</i> • Parking brake electrically • Pyrotechnic belt tensioner • • Tire Pressure Monitoring System • Rear seat folding 1 / 3-2 / 3 • Windscreen wipers with rain sensor • Rear side windows and rear window tinted dark • Front left seat height adjustment • Seats, front height adjustable • Sun visors with mirrors (illuminated) • LED daytime running lights • Central / start system Keyless System • Central locking with remote control	• Rear center armrest • • Multifunctional display with color display (DGT10CHD) • • aluminum pedals • Digital radio reception (DAB +) • Tire repair kit • Rear view camera with 180 ° ambient view • Low pollutant according to the Euro 6d emissions standard • Front Side Airbags • Electric Power Steering • Seat relation / upholstery cloth / leatherette • Special paint Olivine green metallic • Start / Stop system • Warning system for safety • Central incl. Door lock automatically
--	--

special Features	
•	• Heated front seats

We remind you that the data provided were taken from the DAT database. No liability can be assumed for the completeness and correctness.

General examination	
Mileage plausible:	not testable not testable
reference:	
Note Road Safe:	Reifen beschädigt.

Accident injury assessment	
Rep. Predamages / -height gross:	no detectable As part of a paint film thickness measuring the body outer skin no previous damage could be detected .
Layers of paint thickness measurement:	Within the tolerances At the vehicle , a resist layer thickness measurement was carried out on the body outer skin. The measured values ??were within the tolerances of original finishes . Evidence that points to a repaired accident damage or repainting carried out , were

identified.

Existing collision damage:

-

-

reference:

Overview conducted technology audit					
coupling:	✓	examined limited	engine running:	✗	Out of order
transmission:	✓	examined limited			

Performed testing technology	
coupling:	The clutch could be tested only limited within the test drive / pull test .
engine running:	A field test of the engine had to acoustic or visual defects for visiting time . **Fluid levels are outside the norm.
transmission:	The transmission could be examined in the context of limited test drive / pull test .
reference:	*Das Fahrzeug hat Laufleistungs und Altersbedingte Gebrauchsspuren. Kosten und Schadenserweiterung sind möglich. Die Fahrzeugfront hat Steinschläge. Schäden sind nicht ausgeschlossen.

damage



component	Damage	Rep kind
1. maintenance	Due	Replace
2. proof of maintenance	Missing	Replace
3. Key with remote control	Missing	Replace
4. warning light	Error message	Carry out a fault diagnosis
5.	Odour	Ozone treatment
6. warning light	Error message	Carry out a fault diagnosis
7. Kühlmittel		Fill Up
8. Sidewall - Rear - Left	Damaged	Refurbish and paint
9. Outside Door Handle Rear - Left	Scratch(es)	Paint
10.	Scratch(es)	Replace
11. Türeinstieg Hinten - Links	Damaged	Refurbish and paint
12. Front door - left	Scratch(es)	Paint
13. Windshield	Chipping from stones in field of view	Replace
14.	Scratch(es)	Replace
15. Front bumper	Scrape	Refurbish and paint
16. spoiler	Scrape	Replace
17. hood	Deformed	Refurbish and paint
18.	Scratch(es)	Replace
19. Front door - right	Damaged	Refurbish and paint
20.	Damaged	Replace
21. side skirt - right	Damaged	Refurbish and paint
22. Door Rear - right	Scratch(es)	Paint
23. Sidewall - Rear - right	Scratch(es)	Paint
24.	Scratch(es)	Replace
25. Türeinstieg Hinten - Rechts	Damaged	Refurbish and paint
26.	Dirty	
27. Roof frame - right	Scratch(es)	Paint
28.	Scrape	Replace
29. Roof frame - left	Scratch(es)	Paint
30. roof	Scratch(es)	Paint
31. exterior body	Surface scratch(es)	
32. Rear door - left	Scratch(es)	Paint
33. warning light	Error message	Carry out a fault diagnosis
34. tire front - right	Damaged	Replace
35. tire rear - right	Damaged	Replace
36. tire rear - left	Damaged	Replace
37. Rear bumper	Scratch(es)	Paint
38. side skirt - left	Damaged	Refurbish and paint

39.

Scrape

Replace

The expert points out that the vehicle in addition to the age- damage listed in the report and may have a high mileage -related wear , as in normal use are inevitable (small bumps , dents , scratches) .

There shall be no liability for any defect and / or remained hidden damage in terms of electronics and mechanics accepted , and for fraudulent misrepresentation and concealed defects .

photographic record



front Left



front Right



rear Left



rear Right



inside



trunk



instrument cluster



mileage



filler cap



rims




rims



rims




rims



VIN



service book



Others



interior rear



Navigation system



Drivers side + Steering Wheel + center console



4. warning light

Error message



6. warning light

Error message




7. Kühlmittel



8. Sidewall - Rear - Left

Damaged



8. Sidewall - Rear - Left

Damaged



8. Sidewall - Rear - Left

Damaged



9. Outside Door Handle Rear - Left

Scratch(es)



10.

Scratch(es)



10.

Scratch(es)



10.

Scratch(es)



11. Türeinstieg Hinten - Links

Damaged



11. Türeinstieg Hinten - Links

Damaged



11. Türeinstieg Hinten - Links

Damaged



12. Front door - left

Scratch(es)



12. Front door - left

Scratch(es)



13. Windshield

Chipping from stones in field of view



13. Windshield

Chipping from stones in field of view



14. Scratch(es)



14. Scratch(es)



15. Front bumper Scrape



15. Front bumper Scrape



16. spoiler Scrape




16. spoiler Scrape



17. hood

Deformed



17. hood

Deformed



18.

Scratch(es)



18.

Scratch(es)




18.

Scratch(es)



19. Front door - right

Damaged



19. Front door - right

Damaged



19. Front door - right

Damaged



20.

Damaged



20.

Damaged



20.

Damaged



21. side skirt - right

Damaged



21. side skirt - right

Damaged



21. side skirt - right

Damaged




22. Door Rear - right

Scratch(es)



22. Door Rear - right

Scratch(es)



22. Door Rear - right

Scratch(es)



23. Sidewall - Rear - right

Scratch(es)



23. Sidewall - Rear - right

Scratch(es)



23. Sidewall - Rear - right

Scratch(es)



24.

Scratch(es)




24.

Scratch(es)



25. Türeinstieg Hinten - Rechts

Damaged



25. Türeinstieg Hinten - Rechts

Damaged



26.

Dirty



26.

Dirty




26.

Dirty



26.

Dirty



27. Roof frame - right

Scratch(es)



27. Roof frame - right

Scratch(es)



28.

Scrape



28.

Scrape



29. Roof frame - left

Scratch(es)



29. Roof frame - left

Scratch(es)



30. roof

Scratch(es)



30. roof

Scratch(es)



31. exterior body

Surface scratch(es)



32. Rear door - left

Scratch(es)



32. Rear door - left

Scratch(es)



32. Rear door - left

Scratch(es)



33. warning light

Error message



34. tire front - right

Damaged



34. tire front - right

Damaged



35. tire rear - right

Damaged



35. tire rear - right

Damaged



36. tire rear - left

Damaged



36. tire rear - left

Damaged



37. Rear bumper

Scratch(es)



37. Rear bumper

Scratch(es)



37. Rear bumper

Scratch(es)



37. Rear bumper

Scratch(es)



38. side skirt - left

Damaged



38. side skirt - left

Damaged



38. side skirt - left

Damaged



39.

Scrape