



PEUGEOT 208

208 Hybrid 100 e-DCS6 Allure

VIN NO VR3UPHPX5S4051647
Registration Number HC552BM



MOT Date	Number of Owners	Number of Keys	Odometer Reading
-	-	1	18750 km
Last Service	Last Service Mileage	First Registration Date	Country First Registered
-	-	2025-02-25	-

Inspection Report Summary

Customer	BCAuto Encheres	Report Number	P20250821103958
Inspection Date / Place	2025-08-21 / BCA COIGNIERES	Cosmetic Grade	5

Vehicle Summary

Vehicle Condition	Not Movable	VAT Type	Qualified - Normal Rate
Fuel Type	Petrol	Gearbox Type	Auto clutch
Colour	Red	Engine Size (cc)	1199
Engine Size	1.2	No of Doors	5
Body Type	Hatchback	Drive Train	Front
Seat Colour		No of Seats	5
Charging Cables		WLTP CO2 Emissions	

Vehicle History & Documents

Service Book Available	-	Next Service Mileage	km
Previous Usage	Normal Use	Imported	
Manufacturer Warrenty			







Equipment


Central locking	Radio	Alloys wheels	Cruise control
Power assisted steering	Electrically folding wing mirrors	Rear parking sensors	Stability control
Front fog lamps	Satellite navigation		

Equipment Details


Seat Heating	No	Air Conditioning	No
Sunroof Type	Tilt/Slide Steel		

Cosmetic Damage

20 Dommages



4 Dommages




Component		Damage	Comments
1	Floor Carpet	Interior / Missing	
2	Floor Carpet	Interior / Missing	
3	Floor Carpet	Interior / Missing	
4	Floor Carpet	Interior / Missing	
5	Corner Bumper / Front Left	Paint / Scratch / Line	
6	Corner Bumper / Front Left	Paint / Scratch / Line	
7	Corner Bumper / Front Left	Paint / Scratch / Line	
8	Fender / Front Left	Paint / Scratch / Line	
9	Door / Front Left	Paint / Scratch / Line	
10	Door / Front Left	Paint / Scratch / Line	
11	Fender / Back Left	Bodywork / Dent / Deformation	
12	Fender / Back Left	Paint / Scratch / Line	
13	Door / Back Left	Paint / Scratch / Line	

14	Corner Bumper / Back Left	Bodywork / Dent / Deformation
15	Corner Bumper / Back Right	Bodywork / Dent / Deformation
16	Fender / Back Right	Bodywork / Dent / Deformation
17	Door / Back Right	Paint / Scratch / Line
18	Door / Back Right	Paint / Scratch / Line
19	Door / Front Right	Paint / Scratch / Line
20	Door / Front Right	Paint / Scratch / Line
21	Door / Front Right	Paint / Scratch / Line
22	Fender / Front Right	Bodywork / Dent / Deformation
23	Fender / Front Right	Paint / Scratch / Line
24	Corner Bumper / Front Right	Paint / Scratch / Line



1. Floor Carpet
Interior / Missing -



2. Floor Carpet
Interior / Missing -



3. Floor Carpet
Interior / Missing -



4. Floor Carpet
Interior / Missing -



5. Corner Bumper / Front Left
Paint / Scratch / Line -



6. Corner Bumper / Front Left
Paint / Scratch / Line -



7. Corner Bumper / Front Left
Paint / Scratch / Line -



8. Fender / Front Left
Paint / Scratch / Line -



9. Door / Front Left
Paint / Scratch / Line -



10. Door / Front Left
Paint / Scratch / Line -



11. Fender / Back Left
Bodywork / Dent / Deformation -



12. Fender / Back Left
Paint / Scratch / Line -



13. Door / Back Left
Paint / Scratch / Line -




14. Corner Bumper / Back Left
Bodywork / Dent / Deformation -




15. Corner Bumper / Back Right
Bodywork / Dent / Deformation -



16. Fender / Back Right
Bodywork / Dent / Deformation -



17. Door / Back Right
Paint / Scratch / Line -




18. Door / Back Right
Paint / Scratch / Line -



19. Door / Front Right
Paint / Scratch / Line -



20. Door / Front Right
Paint / Scratch / Line -



21. Door / Front Right
Paint / Scratch / Line -



22. Fender / Front Right
Bodywork / Dent / Deformation -



23. Fender / Front Right
Paint / Scratch / Line -



24. Corner Bumper / Front Right
Paint / Scratch / Line -

Mechanical Condition

Tyres

Presence Anti-Theft Lock Nut ✔

✔ *No troubles detected, good condition or correct tests, according to vehicle age and mileage*

❗ *Damages or malfunction detected that requires repairs by the buyer*

NA *Not applicable*

☐ *Not tested*

Disclaimer Section

The test drive is done on a flat surface and lasts about 2 minutes. The driven distance is a minimum of 300 meters, including a u-turn, an acceleration and a braking phase. The highest speed achieved during this test is 50km/h. The mechanical check is a visual and dynamic diagnosis without any disassembly. We cannot guarantee any mechanical wear part.