

Vehicle details

VIN	VR7ACYHZR KL070467	Brand	Citroën	Maintenance date	-
Licence Plate	ZN-55-0B	Model	C5 Aircross BlueHdi 130 S;S Business EAT8 5d	Maintenance mileage	-
Registration date	28/06/2019	Year	2019	Exterior Color	Grey Metallic
Odometer	204 612 km	Engine size	1499	interior Color	Grey
Fuel	Diesel	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Automatic	CO2	-
Doors	5	Gears	-		

Inspection Details

Inspection date	15/05/2025	Inspection loc.	Dekra Ayvens
-----------------	------------	-----------------	--------------



Generic equipment

Automated air-conditioning	✓
Cruise control	✓
GPS system	✓
Alloy wheel rims	✓
Automatic Gearbox	✓
Tow	✓
Metallic paint	✓
Central locking	✓
Electric windows	✓
Side rails	✓
Park Distance Control	✓
Audio System	✓

Removable element

Rear parcel shelf	✓
-------------------	---


Technical Document

User manual	✓
Warranty booklet	✓
Spare key	✓
Remote key	✓

Tyres

Winter kit

Michelin 235/55/18 Winter 6.5 mm



Michelin 235/55/18 Winter 6.5 mm



Michelin 235/55/18 Winter 8.0 mm

Michelin 235/55/18 Winter 7.5 mm

Exterior

2



Part

Alloy wheel 18"

Position

Front left

Damages

Scratched

Severity

-

Repair mode

Lumpsum repair

●

●

4



Part

Wing

Position

Back left

Damages

Scratched

Severity

Length (cm) > 10

Repair mode

Repair

●

●

●

6



Part

Exterior door mirror shell

Position

Right

Damages

Scratched

Severity

Length (cm) > 10

Repair mode

Repair

●

●

9



Part

Roof

Position

-

Damages

Dented

Severity

Diameter (mm) > 20

Repair mode

Smart Repair

●

●

●

3



Part

Door

Position

Back left

Damages

Scratched

Severity

Length (cm) > 10

Repair mode

Repair

●

●

5



Part

Door

Position

Back right

Damages

Dented

Severity

Diameter (mm) > 20

Repair mode

Smart Repair

●

●

7



Part

Wing

Position

Front right

Damages

Dented

Severity

Diameter (mm) > 20

Repair mode

Repair

●

●

●

●

●

Interior damage

1



Part	Interior roof lining
Position	-
Damages	Perforated
Severity	-
Repair mode	Smart Repair

Others

8



Part

Position

Damages

Severity

Repair mode

Damage appraisal

Front

Stone impact

-

For info