



SEAT LEON

Leon 1.6 TDI 105 FAP CR Style E-Ecomotive

VIN NO VSSZZZ1PZBR032941
Registration Number BH289LN



MOT Date



Last Service



Number of Owners



Last Service Mileage



Number of Keys



First Registration Date



Odometer Reading



Country First Registered



Inspection Report Summary

Customer	BCA Auto Encheres	Report Number	P20251007085132
Inspection Date / Place	2025-10-07 / BCA GARONS	Cosmetic Grade	5

Vehicle Summary

Vehicle Condition	Non-Runner	VAT Type	Exempt Rate
Fuel Type	Diesel	Gearbox Type	Manual
Colour	Grey	Engine Size (cc)	1598
Engine Size	1.6	No of Doors	5
Body Type	Hatchback	Drive Train	Front
Seat Colour		No of Seats	5
Charging Cables		NEDC CO2 Rating (q/km)	99
Engine Rating CV	5	Metalic Colour	Yes
Accident Damage	No	Euro Emission	

Vehicle History & Documents

Service Book Available	Present	Next Service Mileage	km
Previous Usage	Normal Use	Imported	No
Manufacturer Warrenty			






Equipment

Central locking	Rear parking sensors	Cruise control	Power assisted steering
Radio	Alloys wheels	Front fog lamps	


Equipment Details

Seat Heating	No	Air Conditioning	Yes
--------------	----	------------------	-----

20 Dommages



1 Dommages



5/11 - Report Number P20251007085132

13	Rocker Panel / Center Right	Bodywork / Dent / Deformation
14	Door / Front Left	Bodywork / Dent / Deformation
15	Mirror / Front Right	Paint / Scratch / Line
16	Door / Front Right	Bodywork / Dent / Deformation
17	Door / Back Left	Bodywork / Dent / Deformation
18	Fender / Back Left	Bodywork / Dent / Deformation
19	Door / Front Left	Paint / Scratch / Line
20	Shield / Back	Paint / Scratch / Line
21	Fender / Front Left	Paint / Poor Previous Repair
22	Door / Back Left	Paint / Scratch / Line
23	Door / Front Left	Bodywork / Dent / Deformation
24	Shield / Front	Bodywork / Assembly



1. Seat Cushion / Back Right
Interior / Dirty -



2. Shield / Front
Paint / Scratch / Line -



3. Shield / Front
Paint / Scratch / Line -



4. Front Light / Front Right
Glass Break -



5. Shield / Back
Paint / Scratch / Line -



6. Rim
Out of Bodywork / Scratch -



7. Rim Brake pads
Out of Bodywork / Scratch -




8. Fender / Front Right
Bodywork / Dent / Deformation -



9. Fender / Back Right
Bodywork / Dent / Deformation -



10. Shield / Front
Bodywork / Dent / Deformation -




11. Rim
Out of Bodywork / Scratch -




12. Door / Front Right
Bodywork / Dent / Deformation -




13. Rocker Panel / Center Right
Bodywork / Dent / Deformation -



14. Door / Front Left
Bodywork / Dent / Deformation -



15. Mirror / Front Right
Paint / Scratch / Line -



16. Door / Front Right
Bodywork / Dent / Deformation -



17. Door / Back Left
Bodywork / Dent / Deformation -



18. Fender / Back Left
Bodywork / Dent / Deformation -



19. Door / Front Left
Paint / Scratch / Line -



20. Shield / Back
Paint / Scratch / Line -



21. Fender / Front Left
Paint / Poor Previous Repair -



22. Door / Back Left
Paint / Scratch / Line -



23. Door / Front Left
Bodywork / Dent / Deformation -



24. Shield / Front
Bodywork / Assembly -

Mechanical Condition

Tyres

Presence Anti-Theft Lock Nut 

 *No troubles detected, good condition or correct tests, according to vehicle age and mileage*

 *Damages or malfunction detected that requires repairs by the buyer*

 *Not applicable*

 *Not tested*

Disclaimer Section

The test drive is done on a flat surface and lasts about 2 minutes. The driven distance is a minimum of 300 meters, including a u-turn, an acceleration and a braking phase. The highest speed achieved during this test is 50km/h. The mechanical check is a visual and dynamic diagnosis without any disassembly. We cannot guarantee any mechanical wear part.