



status report

customer:	Bank 11, Neuss
contract number:	1329966230
reference:	

vehicle data			
Cupra Ateca Basis			
Vehicle identification number	VSSZZZ5F6R6522462	mileage read:	18908 km
∴			
First Registration / construction year:	20.06.2024 / 2023	Visit Date / place of birth:	27.08.2025 Heidenheim
Bodywork:	SUV	Re - import:	no
Body type:	hatchback	KBA no. :	7593//ATC
Fuel / emission class:	gasoline / € 6	transmission type:	automatic
Displacement / power:	1498 ccm / 110 kW (150 PS)	Engine:	front-wheel drive
paint:	"Magic" Schwarz	Number of previous owners:	Unbekannt
Doors / seats:	5 / 5	number keys:	2
Next HU / AU:	- / -	cushion type:	Leather / fabric
Service book available:	no	Interior Color:	black
smoking vehicle:	yes	Last service km / on the:	- / -
Vehicle roadworthy:	yes	Vehicle roadworthy:	no
Submitted vehicle documents:	For example, I (Fzg.Schein)	state outside:	4 - moderate
visit condition:	-	condition inside:	4 - moderate
state general:	4 - moderate		

Accessories (presented to the visiting time)			
GPS sat nav disk:	Fzg.Schlüssel:	Service book provided / maintained:	Last service at / on:
Hard Disk Drive	2	no / -	- / -
☒ AHK key	☒ AHK removable	☒ AHK fixed	☒ AHK swivel
☒ Fernbed . entertainment	☒ Fernbed . Auxiliary heating	☒ headphone	☒ LED headlights
☒ Load compartment cover	☒ navigation system	☒ Persenning	☒ partition net
☒ Wind Deflector	☒ Xenon headlights		

☒ **available** ☒ **not available**

Hüsges GmbH
Gießerallee 23
47877 Willich
Tel.: 02154 / 9534 0
E-Mail: gutachten@huesges-group.eu

The status report was created impartially and to the best of my knowledge. The images listed in the status report are part of the vehicle description regarding the equipment and the vehicle condition.



Hüsges Gruppe®
Die Gutachter



mounted tires		
Tyre / wheel type:	summer tires	polished aluminum
1st axis - Left / states .	Bridgestone	235/40/R19/96Y 0 mm
1st axis - right / states .	Bridgestone	235/40/R19/96Y 0 mm
2nd axis - Left / states .	Bridgestone	235/40/R19/96Y 4 mm
2nd axis - right / states .	Bridgestone	235/40/R19/96Y 4 mm
traffic Safety:	not roadworthy	
spare wheel:	-	
state spare wheel:	-	

standard equipment	
• 3rd brake light • Airbag on the passenger side can be switched off • Ambient lighting LED • Drive type front-wheel drive • Exterior mirrors electr. adjustable, heated and foldable with lowering mirror and welcome light • Board computer • Roof rails black • Double tone horn • Electronics. Differentialsperre (XDS) • Fahrassistenz-System Berganfahr-Assistent • Driver assistance system drowsiness detection • Driver assistance system Environment monitoring system (front assist) with city emergency braking function • Full Link (MirrorLink, Apple CarPlay and Android Auto) • Luggage compartment cover / roller blind • Glove compartment with LED lighting • Rear spoiler body color (roof spoiler) • 5-door body • Driver side knee airbag • Head airbag system • Lumbar support, front right seat, adjustable • LM rims • Front center console with center armrest, cup holder, storage box and rear air vents • Motor 1.5 Ltr. - 110 kW 16V TSI ACT • Emergency call system • Electric parking brake • Wheel arch covers painted front and rear	• Storage pocket on the front seat backrests • Airbag driver / passenger side • Traction control (ASR) • Audio navigation system with color touchscreen <i>Radioempfang digital (DAB+), Sprachsteuerungs-System, USB-Schnittstelle vorn (2-fach, Typ C), Mobile Online Dienste Cupra Connect</i> • Integrated Bluetooth interface with hands-free system <i>Bluetooth Audio-Streaming</i> • Glasses compartment • Double tailpipe exhaust system, left / right • Door sill trims (aluminum) at the front, illuminated • Electron. Stability Check (ESC) • Driver assistance system Driving profile selection (CUPRA Drive Profile) • Driver assistance system Park assist with parking assistance front and rear including reversing camera • Electric windows front + rear with comfort switch • LED footwell lighting • 7-speed transmission - DSG dual clutch transmission • LED rear lights with dynamic flashing light • Isofix mounts for child seat on the back seat • Climatronic 2-zone air conditioning • Digital instrument cluster (virtual cockpit) • Lumbar support, front left seat, adjustable • Light and vision package <i>Lichtassistent (Coming Home, Leaving Home), Licht- und Regensensor, Innenspiegel mit Abblendautomatik</i>

- Tire control display
- Low in emissions according to the Euro 6d emissions standard
- Kessy locking / starting system
- Side airbag
- Electro-mechanical power steering
- Height adjustable front right seat
- Sun visor on the left with mirror (illuminated)
- Sports bucket seats at the front with integrated headrests
- Socket (12V connection) at the front
- Front bumper Cupra design
- USB charging ports (2-way, type C) for 2nd row of seats
- Immobilizer (electronic)
- Central locking with remote control

- Rear center armrest
- Facelift
- LED fog lights with cornering light
- Otto Particulate Filter (OPF)
- Aluminum-foot Design
- Wheelbase 2681 mm
- Split / foldable rear seat back (1 / 3-2 / 3)
- Full LED headlights
Leuchtweitenregelung automatisch
- Lettering on the tailgate (CUPRA)
- Rear side windows and rear window darkened
- Height-adjustable front left seat
- Seat cover / seat center upholstery in microfiber
- Sun visor on the right with mirror (illuminated)
- Start / stop system
- Rear bumper Cupra design with diffuser
- Daytime running lights LED
- Lashing eyes for the trunk / load compartment
- Thermal insulation glazing

special Features

- Trailer coupling (ball head with electrical release, swiveling)
- Business Package Cupra Plus
Fahrassistenz-Paket, Fahrassistenz-Paket: Stau- und Notfallassistent, Fahrassistenz-Paket: Travel Assist, Fahrassistenz-System: Fernlichtassistent, Fahrassistenz-System: Verkehrszeichenerkennung, Fahrassistenz-System: Pre-Crash-System, Fahrassistenz-System: Autom. Distanzregelung (ACC / PCC) mit vorausschauender Geschw.-Regelung, Fahrassistenz-System: Automatische Distanzregelung (ACC), Fahrassistenz-System: Totwinkel-Assistent mit Auspark-Assistent, Spurwechselassistent und Ausstiegswarnung, Fahrassistenz-System: Spurhalteassistent, Frontscheibe heizbar, Gepäckraum-Abtrennung (Netz), Rücksitzlehnen umklappbar mit Fernentriegelung im Kofferraum, Heckklappe/-Deckel elektr. betätigt (öffnen + schliessen, sensorgesteuert), Steckdose (12V-Anschluß) im Koffer-/Laderaum, Steckdose 230V im Gepäckraum, Lenkrad (CUPRA, Leder) mit Multifunktion und Schaltfunktion
- Anti-theft alarm system with interior monitoring and towing protection
- Camera system environment view (top view, 360°)
- Spare wheel as an emergency wheel

- Audio system BeatsAudio sound system
- Headliner black
- Induction charging cradle for smartphone
- Metallic paint
- Electric sliding/tilting roof (glass)
- Winter package
Sitzheizung vorn

- Stowage/storage compartment under the front seats

We remind you that the data provided were taken from the DAT database. No liability can be assumed for the completeness and correctness.

General examination

Subfloor Inspection:	not possible A visit to the underside of your vehicle could not be performed. Hoist or lifting means not available .
Mileage plausible:	not testable not testable
reference:	
Note Road Safe:	Vordere Bereifung beschädigt.

Farbabweichung Plastikteile

Accident injury assessment

Rep. Predamages / -height gross:	no detectable As part of a paint film thickness measuring the body outer skin no previous damage could be detected .
Layers of paint thickness measurement:	Within the tolerances At the vehicle , a resist layer thickness measurement was carried out on the body outer skin. The measured values ??were within the tolerances of original finishes . Evidence that points to a repaired accident damage or repainting carried out , were identified.
Existing collision damage:	found At the unrepaired vehicle accident damage were observed on visual examination on the body skin .
reference:	Fahrzeug mit bestehenden Unfallschaden, zur Schadensermittlung wurden keine Demontagearbeiten durchgeführt, verborgen gebliebene Schäden können nicht ausgeschlossen werden. Unfallschaden Kosten wurden überschlägig Kalkuliert, Kostenerweiterung möglich.

Overview conducted technology audit					
Alternator / Generator:		examined limited	Battery / accumulator:		examined limited
oil loss:		examined limited			
air conditioning:		examined limited	lighting system:		examined limited
coupling:		unavailable	exhaust System:		examined limited
engine running:		examined limited	shock absorber:		not possible
transmission:		examined limited			

Performed testing technology	
Alternator / Generator:	The function of the alternator (generator) was tested using the charging indicator light in the instrument cluster .
Battery / accumulator:	The battery (accumulator) could be considered limited during the visit .
oil loss:	The vehicle could be checked only limited to oil leaks .
air conditioning:	The air conditioning system could be tested only restricted during the visit .
lighting system:	The Lichtenlange could be considered limited to the tour date .
coupling:	The vehicle has no clutch , as it is a Autmatikgetriebe or the like.
exhaust System:	The exhaust system has been tested only restricted during the visit .
engine running:	Checking the engine running was limited. Here no audible or visual abnormalities were noted .
shock absorber:	The shock absorber could not be checked during the inspection .
transmission:	The transmission could be examined in the context of limited test drive / pull test .
reference:	*Alters-, Transport- und Laufleistungsbedingte Gebrauchsspuren vorhanden. Kosten- und Schadenserweiterung möglich.

damage



	component	Damage	Rep kind
1.	Rim front - right	Damaged	Replace
2.	tire front - right	Damaged	Replace
3.		Damaged	Replace
4.		Damaged	Replace
5.	Front bumper	Accident damage	Replace
6.	Zierleiste Tür Hinten - Rechts	Scratch(es)	Paint
7.		Scratch(es)	Paint
8.	Rim front - left	Damaged	Replace
9.	tire front - left	Damaged	Replace
10.		Dirty	
11.	Front fender - right	Damaged	Refurbish and paint
12.	proof of maintenance	Missing	Replace
13.	maintenance	Due	Replace
14.	spoiler	Accident damage	Replace

The expert points out that the vehicle in addition to age to the damage listed in the report and may have a high mileage -related wear , as in normal use are inevitable (small bumps , dents , scratches) and thus is not entitled to change or reduction .

There shall be no liability for any defect and / or remained hidden damage in terms of electronics and mechanics accepted ,\r\nand for fraudulent misrepresentation and concealed defects .

photographic record



front Left



front Right




rear Left



rear Right



inside




inside



trunk



instrument cluster



mileage



filler cap



rims



rims




rims



rims



engine compartment



service book



Others



Navigation system



1. Rim front - right



1. Rim front - right



2. tire front - right



2. tire front - right



2. tire front - right



3.



4.



4.



4.



5. Front bumper



5. Front bumper




5. Front bumper



5. Front bumper



5. Front bumper



5. Front bumper



5. Front bumper



6. Zierleiste Tür Hinten - Rechts



6. Zierleiste Tür Hinten - Rechts



7.



7.



8. Rim front - left



8. Rim front - left



9. tire front - left



10.



10.



10.



10.



10.



11. Front fender - right



11. Front fender - right