



SEAT Ateca

Ateca 2.0 TDI 4Drive DSG

VIN NO VSSZZZ5FZJ6543426
Registration Number FZJ6543426



MOT Date	Number of Owners	Number of Keys	Odometer Reading
2027-03-01	3	2	93125 km
Last Service	Last Service Mileage	First Registration Date	Country First Registered
-	-	2018-05-07	Germany

Inspection Report Summary

Customer	BCA Online	Report Number	P20251009101130
Inspection Date / Place	2025-10-09 / SULOJA Brackel	Cosmetic Grade	3

Vehicle Summary

Vehicle Condition	Runner	VAT Type	Margin
Fuel Type	Diesel	Road Worthy	Yes
Colour	White	Engine Size (cc)	1968
Engine Size	2.0	No of Doors	5
Body Type	SUV	Drive Train	All-Wheel-Drive permanent
Seat Colour		No of Seats	5
Seat Covering Name		Seat Covering	Cloth/Synthetic Leather
Charging Cables		NEDC CO2 Rating (q/km)	135
Gearbox Type	Automatic		

Vehicle History & Documents

Service Book Available	-	Next Service Mileage	km
Previous Usage		Imported	No
Manufacturer Warrenty			







Equipment

Tinted Glass	USB Socket	Airbag Status	Ambientlighting
Anti-lock braking	Auxiliary Socket	Cruise control	Digital Radio
Front parking sensors	Heated wing mirrors	Remote central locking	Roof rails
Stability control	CD - multichanger	Electrictailgate	Leather steering wheel
Radio	Tow ball	360°camera	Alloys wheels
AndroidAuto	AppleCarPlay	Bluetooth telephone interface	Diesel particulate filter
Enhanced speaker system	Heated windscreen	Remote adjusting wing mirrors	Reversing Camera
Satellite navigation	Sunroof	Electrically folding wing mirrors	Keyless Entry
LED Headlamps	Rear parking sensors		

Equipment Details


Tow Ball Type	Pivoted	Air Conditioning	Dual Zone Climate Control
Alloy Wheel Size	18	Enhanced Speaker System	Seat Sound
Seat Heating	Front		

Wheels & Tyres


Right Front Tyre Depth	4	Left Front Tyre Depth	4
Right Rear Tyre Depth	3	Left Rear Tyre Depth	3

Cosmetic Damage

4 Schäden



0 Schäden




Component		Damage	Comments
1	Side Panel / Back Left	Paint / Poor Previous Repair	
2	Door / Back Right	Paint / Scratch / Scuff	
3	Hood	Bodywork / Dent / Dent	
4	Door / Front Left	Paint / Scratch / Scuff	



1. Side Panel / Back Left
Paint / Poor Previous Repair -



2. Door / Back Right
Paint / Scratch / Scuff -



3. Hood
Bodywork / Dent / Dent -



4. Door / Front Left
Paint / Scratch / Scuff -

Mechanical Condition

Control Lights

ABS Warning Light	✓	ESP Fault/Traction Control Malfunction Light	✓
Diesel Particulate Filter Light	✓	Airbag Warning Light	✓
Oil Pressure Warning Light	✓	Brake Warning Light	✓
Power Steering Warning Light	✓	Alternator / Battery	✓
No Dashboard Lights	✓	Display Defect	✓
Tire Pressure Monitoring System	✓		

Engine

Engine Status / EML	✓	Engine Leak Visible	✓
Engine Starts	✓		

Gearbox

Gear Box	✓
----------	---

Levels

Brakes Fluid	✓	Coolant Fluid	✓
--------------	---	---------------	---

Equipments Test

Main & Spare Keys Functioning	✓	Electric Windows	✓
Navigation System	✓	Audio Equipment	✓
Parking Sensors / Cameras Functioning	✓	AC / Heating System	✓

Test Drive Inspection

Steering Wheel			
Steering Noise / Anomaly		✓	
Engine			
Engine Noise	✓	The Gears Scratch / Skip / Abnormal Operation	✓
Fume Quantity	✓	Power Loss	✓
Brake			
Brake System Anomaly		✓	
General			
Test Driven Status		✓	
✓ <i>No troubles detected, good condition or correct tests, according to vehicle age and mileage</i>			
! <i>Damages or malfunction detected that requires repairs by the buyer</i>			
NA <i>Not applicable</i>			
= <i>Not tested</i>			

Disclaimer

Please also note the "UserGuide condition report", which shows the scope of the vehicle description.

[User Guide](#)