



status report

customer: BCA Autoauktionen GmbH
contract number:
reference:

vehicle data

Seat Leon ST Cupra 300 4Drive

Vehicle identification number	VSSZZZ5FZJR006379	mileage read:	79333 km
First Registration / construction year:	01.08.2017 / 17	Visit Date / place of birth:	04.09.2025 Wolnzach
Bodywork:	cars	Re - import:	no
Body type:	hatchback	KBA no. :	7593//AMY
Fuel / emission class:	gasoline / € 6	transmission type:	automatic
Displacement / power:	1984 ccm / 221 kW (300 PS)	Engine:	four-wheel
paint:	"Mystery" Blau	Number of previous owners:	4
Doors / seats:	5 / 5	number keys:	2
Next HU / AU:	06.2026 / 06.2026	cushion type:	Leather / Alcantara
Service book available:	digital	Interior Color:	black
smoking vehicle:	no	Last service km / on the:	- / -
Vehicle roadworthy:	yes	Vehicle roadworthy:	yes
Submitted vehicle	-	state outside:	2 - Good
documents:		condition inside:	2 - Good
visit condition:	-		
state general:	2 - Good		

Accessories (presented to the visiting time)

GPS sat nav disk:	Fzg.Schlüssel:	Service book provided / maintained:	Last service at / on:
CD / DVD	2	digital / -	- / -

☒ AHK key	☒ AHK removable	☒ AHK fixed	☒ AHK swivel
☒ Fernbed . entertainment	☒ Fernbed . Auxiliary heating	☒ headphone	☒ LED headlights
☒ Load compartment cover	☒ navigation system	☒ Persenning	☒ partition net
☒ Wind Deflector	☒ Xenon headlights		

☒ available ☒ not available

Hüsges GmbH
Gießerallee 23
47877 Willich
Tel.: 02154 / 9534 0
E-Mail: gutachten@huesges-group.eu

The status report was created impartially and to the best of my knowledge. The images listed in the status report are part of the vehicle description regarding the equipment and the vehicle condition.



Hüsges Gruppe®
Die Gutachter



mounted tires		
Tyre / wheel type:	Winter tires	aluminum
1st axis - Left / states .	Yokohama	225/35/R19/88W 8 mm
1st axis - right / states .	Yokohama	225/35/R19/88W 8 mm
2nd axis - Left / states .	Yokohama	225/35/R19/88W 8 mm
2nd axis - right / states .	Yokohama	225/35/R19/88W 8 mm
traffic Safety:	roadworthy	
spare wheel:	-	
state spare wheel:	-	

standard equipment	
• 3rd brake light • Storage pocket on front seat backrests • Airbag driver / passenger side • Anti-Blockier-System (ABS) • Drive all-wheel drive • Outside mirror black • board computer • Headliner black • Elektron. Differentialsperre (EDS) • Electron. Stability control (ESC) • Driving Assistance System Driving profile selection (SEAT Drive Profile) • Power windows Rear • Luggage compartment cover / roller blind • Transmission 6-speed dual-clutch gearbox DSG • rear spoiler • Isofix seats for child seat • Climatronic air conditioning 2-zone • Trunk light • Rear headrests (3- fold) • Variable load floor and removable • Lumbar support front right seat , adjustable • Light and sight package <i>Lichtassistent (Coming Home, Leaving Home), Licht- und Regensensor, Innenspiegel mit Abblendautomatik</i> • model refinement • Park brake electric • Rear seat backrest split / folding (1 / 3-2 / 3) • Low emissions Euro 6 emissions standard • Headlight LED <i>Heckleuchten LED</i>	• Storage package <i>Mittelkonsole vorn mit Mittelarmlehne, Becherhalter, Ablagebox und Luftausströmer hinten, Stau-/Ablagefach unter Sitz vorn links</i> • Airbag front passenger side can be switched off • Ambient lighting LED • Drive slip control (ASR) • Outside mirror electr. adjustable, heatable and foldable, both <i>Außenspiegel elektr. anklappbar, Außenspiegel mit Spiegelabsenkung, rechts, Außenspiegel elektr. verstell- und heizbar, beide</i> • Outside temperature display • brake Assist • Dynamic-Package <i>Fahrassistenz-System: Adaptive Fahrwerksregelung (DCC), Progressivlenkung</i> • Electron. Stability Program (ESP) • Driving Assistance System Hill Start Assist • • Electric windows front • Speed control system (cruise control) • Glove compartment illuminated • Interior light package LED • Body 5-door • Knee airbag driver side • Head airbag system • Adjustable front head restraints • Lumbar support front left seat , adjustable • Steering wheel with shift paddles / buttons • Rear center armrest

• Darkened rear side windows and rear windscreen • Seat front right height adjustable • Seat cover / upholstery leather / Alcantara • Sun visor right with mirror (illuminated) • Start / Stop system • Socket (12V) port forward • Immobilizer (electronic) • Central locking with remote control	• • Tire monitoring display • Rear seat backs folded down with remote unlocking the trunk • Shift / selector lever handle leather • side airbags • Front left seat height adjustment • Seat cover / leather upholstery • Sun visor left with mirror (illuminated) • Sport chassis FR / Cupra • Socket (12V connection) in the luggage compartment • LED daytime running lights • Wärmeschutzverglasung
--	---

special Features	
• Audio Navigation System Plus <i>Sprachsteuerungs-System, Bluetooth Audio-Streaming, USB-Anschluss, Lenkrad mit Multifunktion</i> • Park distance control front and rear, optically • Luggage compartment partition (net) • Leather package including sports seats <i>Sitzheizung vorn</i> • Digital radio reception (DAB) • Sound system SEAT <i>10 Lautsprecher</i>	• <i>Bremsanlage: Brembo, Hochleistungs-Bremssättel (Bremssättel Rot), LM-Felgen</i> • Fahrassistenz-Paket 4 <i>Fahrassistenz-System: Fernlichtassistent, Fahrassistenz-System: Verkehrszeichenerkennung, Fahrassistenz-System: Automatische Distanzregelung (ACC), Fahrassistenz-System: Stauassistent (Traffic Jam Assist), Fahrassistenz-System: Spurhalteassistent, Frontkamera</i> • Induction charging tray for smartphone (connectivity box) • Metallic paint • • Startanlage Keyless Access

We remind you that the data provided were taken from the DAT database. No liability can be assumed for the completeness and correctness.

General examination	
Subfloor Inspection:	not possible A visit to the underside of your vehicle could not be performed. Hoist or lifting means not available .
Mileage plausible:	yes yes

reference:

Note Road Safe:

Farbabweichung Plastikteile

Accident injury assessment

Rep. Predamages / -height gross: **no detectable**

As part of a paint film thickness measuring the body outer skin no previous damage could be detected .

Layers of paint thickness measurement:

Within the tolerances

At the vehicle , a resist layer thickness measurement was carried out on the body outer skin. The measured values ??were within the tolerances of original finishes . Evidence that points to a repaired accident damage or repainting carried out , were identified.

Existing collision damage:

Not established

On the vehicle body shell were on visual examination found no existing accident damages (other than the usual signs of use) .

reference:

Overview conducted technology audit			
Alternator / Generator:	✓ in order	Battery / accumulator:	✓ in order
oil loss:	✓ in order		
air conditioning:	✓ in order	lighting system:	✓ in order
coupling:	✗ unavailable	exhaust System:	✗ not checked
engine running:	✓ in order	shock absorber:	✓ in order
transmission:	✓ examined limited		

Performed testing technology	
Alternator / Generator:	The function of the alternator (generator) was tested using the charging indicator light in the instrument cluster .
Battery / accumulator:	The battery (accumulator) was examined during the inspection .
oil loss:	The vehicle was inspected during the visit to an oil leak .
air conditioning:	A function of the air conditioning was found to visiting time .
lighting system:	The lighting system was to tour date in order.
coupling:	The vehicle has no clutch , as it is a Autmatikgetriebe or the like.
exhaust System:	The exhaust system was not tested during the visit .
engine running:	A field test of the engine was performed.
shock absorber:	The shock absorbers were tested at the tour without any findings.
transmission:	The transmission could be examined in the context of limited test drive / pull test .
reference:	*

damage



component	Damage	Rep kind
1. Motorhaube	Chipping from stones	Smart repair
2. Dachholm links	Delle	Gentle refurbishing
3. side skirt - left	Rust	Refurbish and paint
4. Felge hinten links	Scratch(es)	Paint
5. Dach	Chipping from stones	Smart repair
6.		

The expert points out that the vehicle in addition to age to the damage listed in the report and may have a high mileage -related wear , as in normal use are inevitable (small bumps , dents , scratches) and thus is not entitled to change or reduction .

There shall be no liability for any defect and / or remained hidden damage in terms of electronics and mechanics accepted ,\r\nand for fraudulent misrepresentation and concealed defects .

photographic record



front Left



front Right



rear Left



rear Right



inside



trunk



instrument cluster



mileage



filler cap



rims



rims



rims



rims



engine compartment



service book



Others



Navigation system



Navigation system



1. Motorhaube



1. Motorhaube



1. Motorhaube



2. Dachholm links




2. Dachholm links



2. Dachholm links



3. side skirt - left



3. side skirt - left



3. side skirt - left



3. side skirt - left



4. Felge hinten links



4. Felge hinten links




4. Felge hinten links



5. Dach



5. Dach



5. Dach