



status report

customer:	Bank 11, Neuss
contract number:	1151705030
reference:	

vehicle data			
Seat Leon FR			
Vehicle identification number	VSSZZZ5FZLR082176	mileage read:	42101 km
..			
First Registration / construction year:	17.08.2020 / 2019	Visit Date / place of birth:	19.09.2025 Riedstadt-Goddelau
Bodywork:	cars	Re - import:	no
Body type:	hatchback	KBA no. :	7593//AOK
Fuel / emission class:	gasoline / € 6	transmission type:	automatic
Displacement / power:	1498 ccm / 110 kW (150 PS)	Engine:	front-wheel drive
paint:	"Magnetic Tech"	Number of previous owners:	Unbekannt
Doors / seats:	5 / 5	number keys:	2
Next HU / AU:	- / -	cushion type:	Leather / fabric
Service book available:	no	Interior Color:	black
smoking vehicle:	no	Last service km / on the:	- / -
Vehicle roadworthy:	yes	Vehicle roadworthy:	yes
Submitted vehicle	-	state outside:	3 - Average
documents:			
visit condition:	-	condition inside:	3 - Average
state general:	3 - Average		

Accessories (presented to the visiting time)			
GPS sat nav disk:	Fzg.Schlüssel:	Service book provided / maintained:	Last service at / on:
SD Card	2	no / -	- / -
☒ AHK key	☒ AHK removable	☒ AHK fixed	☒ AHK swivel
☒ Fernbed . entertainment	☒ Fernbed . Auxiliary heating	☒ headphone	☒ LED headlights
☒ Load compartment cover	☒ navigation system	☒ Persenning	☒ partition net
☒ Wind Deflector	☒ Xenon headlights		

☒ **available**

☒ **not available**

The status report was created impartially and to the best of my knowledge. The images listed in the status report are part of the vehicle description regarding the equipment and the vehicle condition.



Hüsges Gruppe®
Die Gutachter



mounted tires		
Tyre / wheel type:	Winter tires	aluminum
1st axis - Left / states .	Continental	225/40/R18/92V 2 mm
1st axis - right / states .	Continental	225/40/R18/92V 2 mm
2nd axis - Left / states .	Continental	225/40/R18/92V 4 mm
2nd axis - right / states .	Continental	225/40/R18/92V 4 mm
traffic Safety:	roadworthy	
spare wheel:	Notrad	
state spare wheel:	Vollwertig	

Unmounted tires		
Tyre / wheel type:	summer tires	without rim
1st axis - Left / states .	Bridgestone	225/40/R18/92Y 4 mm
1st axis - right / states .	Bridgestone	225/40/R18/92Y 4 mm
2nd axis - Left / states .	Bridgestone	225/40/R18/92Y 4 mm
2nd axis - right / states .	Bridgestone	225/40/R18/92Y 4 mm
traffic Safety:	roadworthy	

standard equipment	
• Storage pocket on front seat backrests • Airbag driver / passenger side • Drive slip control (ASR) • Power side mirrors . anklappbar <i>Außenspiegel elektr. verstellbar (mit Memory)</i> • Side mirrors with mirror lowering , right • Outside temperature display • board computer • Elektron. Differentialsperre (EDS) • Electron. Stability control (ESC) • Driving Assistance System Hill Start Assist and electron. differential lock • • Electric windows front • Transmission 7 - speed dual - clutch gearbox DSG • LED taillights • Interior light package LED • Body 5-door • Knee airbag driver side • Rear headrests (3- fold) • Lumbar support front left seat , adjustable • Steering wheel (sports / leather) • Center console with center armrest , cup holders , storage box and rear air vents	• Airbag front passenger side can be switched off • Anti-Blockier-System (ABS) • • Outside mirror electr. adjustable, heatable and foldable, both • Exterior mirrors and exterior door handles in body color • Indicator LED integrated in the exterior mirror • brake Assist • Electron. Stability Program (ESP) • Driving Assistance System Hill Start Assist • Driving Assistance System Driving profile selection (SEAT Drive Profile) • Power windows Rear • Speed control system (cruise control) • Glove compartment illuminated • Interior chrome accents • Isofix seats for child seat • Climatronic air conditioning 2-zone • Head airbag system • Adjustable front head restraints • Lumbar support front right seat , adjustable • LM rims • model refinement

• Motor 1,5 Ltr. - 110 kW 16V TRANS ACT • Otto Particle Filter (OPF) • Tire monitoring display • Low emissions according to Euro 6d TEMP emission standard • SEAT Media System Plus <i>8 Lautsprecher, Sprachsteuerungs-System, iPod-Anschluss, Lenkrad mit Multifunktion</i> • Darkened rear side windows and rear windscreen • Front left seat height adjustment • Sun visor left with mirror (illuminated) • Sport chassis FR / Cupra • Start / Stop system • Socket (12V) port forward • daytime running lights • Wärmeschutzverglasung	• Fog lights integrated with cornering light • Park brake electric • Rear seat backrest split / folding (1 / 3-2 / 3) • Shift / selector lever handle leather • side airbags • Power steering electronically controlled (Servotronic) • Seat front right height adjustable • Sun visor right with mirror (illuminated) • Front sports seats • / Storage tray under the front seats <i>Stau-/Ablagefach unter Sitz vorn links</i> • Bumper painted • Immobilizer (electronic) • Central locking with remote control
--	--

special Features	
• Audio - navigation system with touchscreen color display <i>8 Lautsprecher, USB-Anschluss, iPod-Anschluss</i> • painted mirrors • Metallic paint • LED headlights <i>Heckleuchten LED, Kennzeichenbeleuchtung LED</i>	• Audio system BeatsAudio sound system <i>10 Lautsprecher</i> • Park distance control front and rear, optically • Spare wheel as an emergency wheel • Winter package <i>Scheinwerfer-Reinigungsanlage (SRA), Scheibenwaschdüsen heizbar, Sitzheizung vorn</i>

We remind you that the data provided were taken from the DAT database. No liability can be assumed for the completeness and correctness.

General examination	
Subfloor Inspection:	not possible A visit to the underside of your vehicle could not be performed. Hoist or lifting means not available .
Mileage plausible:	not testable not testable Wartungsnachweise fehlen
reference:	
Note Road Safe:	

Rep. Predamages / -height gross:	no detectable As part of a paint film thickness measuring the body outer skin no previous damage could be detected .
Layers of paint thickness measurement:	Within the tolerances At the vehicle , a resist layer thickness measurement was carried out on the body outer skin. The measured values ??were within the tolerances of original finishes . Evidence that points to a repaired accident damage or repainting carried out , were identified.
Existing collision damage:	Not established On the vehicle body shell were on visual examination found no existing accident damages (other than the usual signs of use) .
reference:	

Overview conducted technology audit					
Alternator / Generator:			examined limited	Battery / accumulator:	
			in order		
oil loss:			examined limited		
air conditioning:			examined limited	lighting system:	
			examined limited		
coupling:			unavailable	exhaust System:	
			examined limited		
engine running:			Out of order	shock absorber:	
			examined limited		
transmission:			examined limited		

Performed testing technology	
Alternator / Generator:	The function of the alternator (generator) was tested using the charging indicator light in the instrument cluster .
Battery / accumulator:	The battery (accumulator) was examined during the inspection .
oil loss:	The vehicle could be checked only limited to oil leaks .
air conditioning:	The air conditioning system could be tested only restricted during the visit .
lighting system:	The Lichtenlange could be considered limited to the tour date .
coupling:	The vehicle has no clutch , as it is a Autmatikgetriebe or the like.
exhaust System:	The exhaust system has been tested only restricted during the visit .
engine running:	A field test of the engine had to acoustic or visual defects for visiting time . **Engine warning light.
shock absorber:	The shock absorber could be tested only restricted during the visit .
transmission:	The transmission could be examined in the context of limited test drive / pull test .
reference:	*Fahrzeug hat Alter und Laufleistungs bedingte Gebrauchsspuren innen und außen. Fahrzeug mit bestehendem Hagelschaden, zur Schadensermittlung wurden keine Demontagearbeiten durchgeführt, verborgen gebliebene Schäden können nicht ausgeschlossen werden. Hagelschaden Kosten wurden überschlägig Kalkuliert, Kostenerweiterung möglich.

damage



component	Damage	Rep kind
1. Motorkontrollleuchte	Error message	Carry out a fault diagnosis
2. Reifendruckkontrollleuchte	Error message	Carry out a fault diagnosis
3. instrument cluster	Wear and tear	acceptable
4. proof of maintenance	Missing	Replace
5. Beide Reifen Vorne	Worn	Replace
6. Front bumper	Damaged	Refurbish and paint
7. hood	Damaged	Refurbish and paint
8. Roof frame - left	Damaged	Refurbish and paint
9. Dach 58x 10-20mm	Hail damage	Gentle refurbishing
10. Sidewall - Rear - Left		Smart repair
11. Rear bumper	Damaged	Refurbish and paint
12. Heckklappe 7x 10-20mm	Hail damage	Gentle refurbishing
13. tailgate trim	Damaged	Smart repair
14. headlining	Damaged	Smart repair
15. Sidewall - Rear - right	Delle	Smart repair
16. Türeinstieg Hinten - Rechts	Scratch(es)	Paint
17. Cargo cover	Missing	Replace
18. maintenance	Due	Replace

The expert points out that the vehicle in addition to age to the damage listed in the report and may have a high mileage -related wear , as in normal use are inevitable (small bumps , dents , scratches) and thus is not entitled to change or reduction .

There shall be no liability for any defect and / or remained hidden damage in terms of electronics and mechanics accepted ,\r\nand for fraudulent misrepresentation and concealed defects .

photographic record



front Left



front Right



rear Left



rear Right



inside



inside



trunk



instrument cluster



mileage



filler cap



rims



rims




rims




rims



engine compartment



service book



1. Motorkontrollleuchte



2. Reifendruckkontrollleuchte



3. instrument cluster



5. Beide Reifen Vorne



5. Beide Reifen Vorne



6. Front bumper



6. Front bumper



6. Front bumper



7. hood



7. hood




8. Roof frame - left




8. Roof frame - left



8. Roof frame - left




9. Dach 58x 10-20mm



9. Dach 58x 10-20mm




9. Dach 58x 10-20mm



9. Dach 58x 10-20mm



10. Sidewall - Rear - Left



11. Rear bumper



11. Rear bumper



12. Heckklappe 7x 10-20mm



12. Heckklappe 7x 10-20mm



12. Heckklappe 7x 10-20mm



13. tailgate trim




14. headlining



15. Sidewall - Rear - right



16. Türeinstieg Hinten - Rechts



18. maintenance