

SEAT Arosa Arosa 1.0 VIN NO VSSZZZ6HZ3R005657

Registration Number HZ3R005657



MOT Date

Number of Owners

P2

Odometer Reading

☆-

23: 1

85148 km

Last Service

Last Service Mileage

First Registration Date

Country First Registered

2003-04-24

Number of Keys

=-

Inspection Report Summary

Customer	BCA Online	Report Number	P20250922141047
Inspection Date / Place	2025-09-22 / Dello Lübeck	Cosmetic Grade	3

Vehicle Summary

Vehicle Condition	Runner	VAT Type	Margin
Fuel Type	Petrol	Road Worthy	Yes
Colour	Red	Engine Size (cc)	999
Engine Size	1.0	No of Doors	3
Body Type	Sedan	Drive Train	Front
Seat Colour		No of Seats	4
Seat Covering Name	Schwarz	Seat Covering	Cloth
Charging Cables		WLTP CO2 Emissions	
Gearbox Type	Manual		

Vehicle History & Documents

Service Book Available	Missing	Next Service Mileage	km
Previous Usage		Imported	No
Manufacturer Warrenty			





































Equipment

Airbag Status	Split folding rear seats	Remote central locking	Radio
Equipment Details			
Air Conditioning		No	
Wheels & Tyres			
Left Rear Tyre Depth	6	Right Rear Tyre Depth	6
Left Front Tyre Depth	5	Right Front Tyre Depth	5

Cosmetic Damage



	Component	Damage	Comments
1	Tailgate	Paint / Poor Previous Repair	
2	Fender / Front Right	Paint / Poor Previous Repair	
3	Fender / Front Left	Bodywork / Dent / Deformation	
4	Door / Front Left	Bodywork / Dent / Deformation	
5	Fender / Back Left	Bodywork / Dent / Deformation	
6	Roof	Bodywork / Dent / Deformation	
7	Fender / Back Right	Bodywork / Dent / Deformation	
8	Door / Front Right	Bodywork / Dent / Deformation	
9	Fender / Front Left	Paint / Corrosion	
10	Windshield / Front	Paint / Chipping	
11	Door / Front Left	Paint / Chipping	
12	Bumper / Back	Paint / Scratch / Scuff	


13	Bumper / Back	Paint / Scratch / Scuff
14	Fender / Back Right	Paint / Scratch / Scuff
15	Headrest / Back Left	Interior / Missing
16	Headrest / Back Right	Interior / Missing
17	Tailgate	Paint / Chipping



Hamb RALL B


1. Tailgate Paint / Poor Previous Repair -

2. Fender / Front Right Paint / Poor Previous Repair -




3. Fender / Front Left Bodywork / Dent / Deformation -

4. Door / Front Left Bodywork / Dent / Deformation -




5. Fender / Back Left Bodywork / Dent / Deformation -

6. Roof Bodywork / Dent / Deformation -



7. Fender / Back Right Bodywork / Dent / Deformation -

8. Door / Front Right Bodywork / Dent / Deformation -




9. Fender / Front Left Paint / Corrosion -

10. Windshield / Front Paint / Chipping -



11. Door / Front Left Paint / Chipping -

12. Bumper / Back Paint / Scratch / Scuff -




13. Bumper / Back Paint / Scratch / Scuff -

14. Fender / Back Right Paint / Scratch / Scuff -



15. Headrest / Back Left Interior / Missing -

16. Headrest / Back Right Interior / Missing -



17. Tailgate Paint / Chipping -

Mechanical Condition

Control Lights		
Display Defect	Ø	Service Light
Airbag Warning Light	Ø	Oil Pressure Warning Light
Brake Warning Light	Ø	Alternator / Battery
No Dashboard Lights	Ø	
Equipments Test		
Central Locking	•	Main & Spare Keys Functioning
Electric Windows		Audio Equipment
Other Equipments		
Engine		
Engine Status / EML		Engine Leak Visible
Engine Starts	•	
Levels		
Brakes Fluid	Ø	Coolant Fluid

Test Drive Inspection

description.

Steering Wheel Steering | Noise / Anomaly **Engine** The Gears Scratch / Skip / **Engine Noise Abnormal Operation Fume Quantity Power Loss** Clutch **Clutch Functioning Brake Brake System Anomaly** General **Test Driven Status** No troubles detected, good condition or correct tests, according to vehicle age and mileage Damages or malfunction detected that requires repairs by the buyer NA Not applicable ■ Not tested Disclaimer Please also note the "UserGuide condition report", which shows the scope of the vehicle

User Guide