

Vehicle details

VIN	VSSZZZKJ2 MR168164	Brand	SEAT	Maintenance date	-
Licence Plate	E874CY	Model	IBIZA 1.0 59kw Reference 59KW	Maintenance mileage	-
Registration date	23/11/2021	Year	1000	Exterior Color	Red Solid
Odometer	42 823 km	Engine size	999	interior Color	Black
Fuel	Petrol	Body Type	Saloon / Hatchback	Next technical inspection	01/11/2026
Seats	-	Transmission	Manual	CO2	-
Doors	5	Gears	-		

Inspection Details

Inspection date	03/03/2025	Inspection loc.	Hödlmayr Logistics GmbH
-----------------	------------	-----------------	-------------------------



Generic equipment

Manual air-conditioning	✓
Cruise control	✓
Rain and light sensor	✓

Removable element

--	--


Technical Document

User manual	✓
Log books	✓
Spare key	✓
Remote key	✓

Tyres

Winter kit

Firestone 185/65/15 S Winter 6.4 mm



Firestone 185/65/15 S Winter 6.5 mm



Goodyear 185/65/15 S Winter 6.4 mm

Goodyear 185/65/15 S Winter 6.5 mm

Exterior

1



Part	Windscreen
Position	-
Damages	Stone impact
Severity	-
Repair mode	For info

2



Part	Bonnet
Position	-
Damages	Hail damaged
Severity	-
Repair mode	Repair

3



Part	Bumper
Position	Front
Damages	Scratched
Severity	-
Repair mode	Repair

4



Part	Bumper grille
Position	Front right
Damages	Scratched
Severity	-
Repair mode	Replace

5

Part	Door
Position	Front left
Damages	Dent & Chips
Severity	-
Repair mode	Repair

6

Part	Door
Position	Back left
Damages	Scratched
Severity	-
Repair mode	For info

7

Part	Roof post A/B/C
Position	Left
Damages	Hail damaged
Severity	-
Repair mode	Repair

10

Part	Tailgate / Boot door
Position	-
Damages	Hail damaged
Severity	-
Repair mode	Repair

11


Part	Bumper
Position	Back
Damages	Scratched
Severity	-
Repair mode	Repair

12

Part	Roof
Position	-
Damages	Hail damaged
Severity	-
Repair mode	Repair

Interior damage


8



Part	Carpet
Position	-
Damages	Burnt
Severity	Diameter (mm) > 5
Repair mode	Replace

● ● ●

9



Part	Interior cleaning
Position	-
Damages	Not carried out
Severity	-
Repair mode	Lumpsum

● ●

Others

13



Part	Paint preparation
Position	-
Damages	-
Severity	-
Repair mode	Paintworks

14



Part	Paint preparation
Position	-
Damages	-
Severity	-
Repair mode	Plastic paint