



## status report

<b>customer:</b>	<b>Opel Grosskunden/FSL/Free2Move</b>
<b>contract number:</b>	
<b>reference:</b>	

vehicle data			
<b>Opel Movano C Kasten HKa L3H2 3,5t Edition</b>			
Vehicle identification number	<b>VXEYCBPFC12V96105</b>	mileage read:	<b>43782 km</b>
..:			
First Registration / construction year:	<b>24.02.2023 / 2022</b>	Visit Date / place of birth:	<b>26.08.2025 Dorfmark</b>
Bodywork:	<b>pickup</b>	Re - import:	<b>no</b>
Body type:	<b>van</b>	KBA no. :	<b>3003//BAM</b>
Fuel / emission class:	<b>diesel / € 6</b>	transmission type:	<b>6 speed manual transmission</b>
Displacement / power:	<b>2179 ccm / 103 kW (140 PS)</b>	Engine:	<b>front-wheel drive</b>
paint:	<b>white</b>	Number of previous owners:	<b>1</b>
Doors / seats:	<b>2 / 3</b>	number keys:	<b>2</b>
Next HU / AU:	<b>- / -</b>	cushion type:	<b>substance</b>
Service book available:	<b>yes</b>	Interior Color:	<b>black</b>
smoking vehicle:	<b>no</b>	Last service km / on the:	<b>- / -</b>
Vehicle roadworthy:	<b>yes</b>	Vehicle roadworthy:	<b>yes</b>
Submitted vehicle documents:	<b>For example, I ( Fzg.Schein )</b>	state outside:	<b>2 - Good</b>
visit condition:	<b>-</b>	condition inside:	<b>2 - Good</b>
state general:	<b>2 - Good</b>		

Accessories (presented to the visiting time )			
<b>GPS sat nav disk:</b>	<b>Fzg.Schlüssel:</b>	<b>Service book provided / maintained:</b>	<b>Last service at / on:</b>
-	2	yes / -	- / -
<input checked="" type="checkbox"/> AHK key	<input checked="" type="checkbox"/> AHK removable	<input checked="" type="checkbox"/> AHK fixed	<input checked="" type="checkbox"/> AHK swivel
<input checked="" type="checkbox"/> Fernbed . entertainment	<input checked="" type="checkbox"/> Fernbed . Auxiliary heating	<input checked="" type="checkbox"/> headphone	<input checked="" type="checkbox"/> LED headlights
<input checked="" type="checkbox"/> Load compartment cover	<input checked="" type="checkbox"/> navigation system	<input checked="" type="checkbox"/> Persenning	<input checked="" type="checkbox"/> partition net
<input checked="" type="checkbox"/> Wind Deflector	<input checked="" type="checkbox"/> Xenon headlights		



**available**



**not available**

The status report was created impartially and to the best of my knowledge. The images listed in the status report are part of the vehicle description regarding the equipment and the vehicle condition.



Hüsges Gruppe®  
**Die Gutachter**



mounted tires		
Tyre / wheel type:	<b>All season tires</b>	<b>steel</b>
1st axis - Left / states .	<b>Anderer</b>	<b>215/70/15/109/107- 5 mm</b>
1st axis - right / states .	<b>Anderer</b>	<b>215/70/15/109/107- 5 mm</b>
2nd axis - Left / states .	<b>Anderer</b>	<b>215/70/15/109/107- 5 mm</b>
2nd axis - right / states .	<b>Anderer</b>	<b>215/70/15/109/107- 5 mm</b>
traffic Safety:	<b>roadworthy</b>	
spare wheel:	-	
state spare wheel:	-	

standard equipment	
<ul style="list-style-type: none"> <li>• Airbag driver</li> <li>• Drive Front Wheel Drive</li> <li>• Document holder (smartphone / tablet)</li> <li>• Driving assistance system Hill Start Assist</li> <li>• Transmission 6-speed</li> <li>• Karosserievariante vehicle length L3</li> <li>• air conditioning</li> <li>• Steering column (steering wheel ) adjustable</li> <li>• Parkpilotsystem</li> <li>• Low in emissions according to the Euro 6d emissions standard</li> </ul>	<ul style="list-style-type: none"> <li>• Anti- lock braking system ( ABS)</li> <li>• Audio system multimedia (DAB+ / USB / MP3) <i>Radiofernbedienung am Lenkrad, Touchscreen-Farbdisplay</i></li> <li>• Electron. Stability Program (ESP )</li> <li>• Generator 180 A</li> <li>• Body / Structure box high room</li> <li>• Karosserievariante high roof ( H2 )</li> <li>• L3H2, 3,5 t</li> <li>• Engine 2.2 Ltr. - 103 kW CDTI</li> <li>• Wheelbase 4035mm</li> <li>• USB port</li> </ul>

special Features	
<ul style="list-style-type: none"> <li>• DAB tuner (digital radio reception) <i>Antenne (Dreifunktionsantenne) in Außenspiegel integriert</i></li> <li>• Rear wing doors with glazing ( opening angle 180 degrees)</li> </ul>	<ul style="list-style-type: none"> <li>• Vehicle keys (2) both foldable</li> <li>• Load compartment bulkhead with window</li> </ul>











We remind you that the data provided were taken from the DAT database.\n\nNo liability can be assumed for the completeness and correctness.

General examination	
<b>Subfloor Inspection:</b>	<b>Conducted limited</b> To investigate the vehicle (ä . Lift o . ) Were not lifting means even a ramp or pit available. For this reason, a visit to the vehicle's underside was limited.
<b>Mileage plausible:</b>	<b>yes</b> yes
<b>reference:</b>	

**Note Road Safe:**

**Accident injury assessment**

<b>Rep. Predamages / -height gross:</b>	<b>no detectable</b> As part of a paint film thickness measuring the body outer skin no previous damage could be detected .
<b>Layers of paint thickness measurement:</b>	<b>Within the tolerances</b> At the vehicle , a resist layer thickness measurement was carried out on the body outer skin. The measured values ??were within the tolerances of original finishes . Evidence that points to a repaired accident damage or repainting carried out , were identified.
<b>Existing collision damage:</b>	<b>Not established</b> On the vehicle body shell were on visual examination found no existing accident damages (other than the usual signs of use) .
<b>reference:</b>	

Overview conducted technology audit					
<b>Alternator / Generator:</b>			examined limited	<b>Battery / accumulator:</b>	
			examined limited		
<b>oil loss:</b>			examined limited		
<b>air conditioning:</b>			examined limited	<b>lighting system:</b>	
			examined limited		
<b>coupling:</b>			examined limited	<b>exhaust System:</b>	
			examined limited		
<b>engine running:</b>			in order	<b>shock absorber:</b>	
			examined limited		
<b>transmission:</b>			examined limited		

Performed testing technology	
<b>Alternator / Generator:</b>	The function of the alternator (generator) was tested using the charging indicator light in the instrument cluster .
<b>Battery / accumulator:</b>	The battery (accumulator) could be considered limited during the visit .
<b>oil loss:</b>	The vehicle could be checked only limited to oil leaks .
<b>air conditioning:</b>	The air conditioning system could be tested only restricted during the visit .
<b>lighting system:</b>	The Lichtanlage could be considered limited to the tour date .
<b>coupling:</b>	The clutch could be tested only limited within the test drive / pull test .
<b>exhaust System:</b>	The exhaust system has been tested only restricted during the visit .
<b>engine running:</b>	A field test of the engine was performed.
<b>shock absorber:</b>	The shock absorber could be tested only restricted during the visit .
<b>transmission:</b>	The transmission could be examined in the context of limited test drive / pull test .
<b>reference:</b>	*Nutzfahrzeug typische Gebrauchsspuren und Beschädigungen.

damage



	<b>component</b>	<b>Damage</b>	<b>Rep kind</b>
1.	maintenance	Missing	Replace
2.	exterior body	Wear and tear	acceptable
3.	Verkleidung Tür Hinten Links	Damaged	Replace
4.		Wear and tear	acceptable
5.	Sidewall - Rear - right	Deformed (slightly)	Refurbish and paint

The expert points out that the vehicle in addition to the age- damage listed in the report and may have a high mileage -related wear , as in normal use are inevitable ( small bumps , dents , scratches) .

There shall be no liability for any defect and / or remained hidden damage in terms of electronics and mechanics accepted ,\r\nand for fraudulent misrepresentation and concealed defects .



photographic record



front Left



front Right



rear Left



rear Right



inside



trunk





instrument cluster



mileage



filler cap



rims



rims



rims






rims



engine compartment



service book



Others



3. Verkleidung Tür Hinten Links

**Damaged**



3. Verkleidung Tür Hinten Links

**Damaged**



4. **Wear and tear**



4. **Wear and tear**



4. **Wear and tear**



4. **Wear and tear**



4. **Wear and tear**



4. **Wear and tear**





4. **Wear and tear**



5. Sidewall - Rear - right **Deformed (slightly)**



5. Sidewall - Rear - right **Deformed (slightly)**



5. Sidewall - Rear - right **Deformed (slightly)**