



status report

customer: Opel Grosskunden/FSL/Free2Move
contract number:
reference:

vehicle data

Opel Movano C Kasten GKa L4H3 3,5t Edition

Vehicle identification number	VXEYDCPFCNG008841	mileage read:	87587 km
First Registration / construction year:	26.09.2022 / 2022	Visit Date / place of birth:	21.08.2025 Knautnaundorf
Bodywork:	transporter	Re - import:	no
Body type:	van	KBA no. :	3003//BAN
Fuel / emission class:	diesel / € 6	transmission type:	manual transmission
Displacement / power:	2179 ccm / 121 kW (165 PS)	Engine:	front-wheel drive
paint:	Casabl/Arctic/EisWeiss/Kaolin	Number of previous owners:	1
Doors / seats:	2 / 3	number keys:	2
Next HU / AU:	08.2026 / 08.2026	cushion type:	substance
Service book available:	yes	Interior Color:	black
smoking vehicle:	yes	Last service km / on the:	62700 / 13.02.2024
Vehicle roadworthy:	yes	Vehicle roadworthy:	yes
Submitted vehicle documents:	-	state outside:	3 - Average
visit condition:	-	condition inside:	3 - Average
state general:	3 - Average		

Accessories (presented to the visiting time)

GPS sat nav disk:	Fzg.Schlüssel:	Service book provided / maintained:	Last service at / on:
-	2	yes / -	62700 / 13.02.2024
☒ AHK key	☒ AHK removable	☒ AHK fixed	☒ AHK swivel
☒ Fernbed . entertainment	☒ Fernbed . Auxiliary heating	☒ headphone	☒ LED headlights
☒ Load compartment cover	☒ navigation system	☒ Persenning	☒ partition net
☒ Wind Deflector	☒ Xenon headlights		

☒ **available**

☒ **not available**

Hüsges GmbH
Gießerallee 23
47877 Willich
Tel.: 02154 / 9534 0
E-Mail: gutachten@huesges-group.eu

The status report was created impartially and to the best of my knowledge. The images listed in the status report are part of the vehicle description regarding the equipment and the vehicle condition.



Hüsges Gruppe®
Die Gutachter



mounted tires		
Tyre / wheel type:	Winter tires	Steel with wheel cover
1st axis - Left / states .	Anderer	215/75/16/116/114R 4 mm
1st axis - right / states .	Anderer	215/75/16/116/114R 4 mm
2nd axis - Left / states .	Anderer	215/75/16/116/114R 4 mm
2nd axis - right / states .	Anderer	215/75/16/116/114R 4 mm
traffic Safety:	roadworthy	
spare wheel:	vorhanden	
state spare wheel:	-	

standard equipment	
• Airbag driver • Drive Front Wheel Drive • Document holder (smartphone / tablet) • Driving assistance system Hill Start Assist • Transmission 6-speed • Karosserievariante vehicle length L4 • L4H3, 3.5 t, reinforced • Steering column (steering wheel) adjustable • Parkpilotsystem • Low in emissions according to the Euro 6d emissions standard • USB port	• Anti- lock braking system (ABS) • Audio system multimedia (DAB+ / USB / MP3) <i>Radiofernbedienung am Lenkrad, Touchscreen-Farbdisplay</i> • Electron. Stability Program (ESP) • Generator 180 A • Body / Structure box Grossraum • air conditioning • Cargo space partition cpl. • Engine 2.2 Ltr. - 121 kW CDTI • Wheelbase 4035mm • Steel rims 6x16 • Disclosure in barn-/FG-room halfway

special Features	
• DAB tuner (digital radio reception) <i>Antenne (Dreifunktionsantenne) in Außenspiegel integriert</i> • Design-Package 2 <i>Nebelscheinwerfer, Tagfahrlicht LED, Seitenmarkierungsleuchten, Radvollabdeckungen</i> • Vehicle keys (2) both foldable • Rear View Camera	• Roof storage / storage gallery roof in front • Driving assistance system Autonomous emergency braking assistant • Rear wing doors without glazing (opening angle 250 degrees) • Seats in the cab driver's seat , suspension seat

We remind you that the data provided were taken from the DAT database. No liability can be assumed for the completeness and correctness.

General examination	
Subfloor Inspection:	not possible A visit to the underside of your vehicle could not be performed. Hoist or lifting means not available .

Mileage plausible: **not testable**
 not testable

reference:

Note Road Safe:

Accident injury assessment

Rep. Predamages / -height gross: **Expertly repaired**

On a vehicle coating thickness measurement on the body outer skin were noted repaired previous damage in the frames that were repaired and apparently without disassembly of components without residual traces accident . If there is an impairment of the observed accident before it was taken into account in if conducted vehicle valuation.

Layers of paint thickness measurement:

Out of tolerance

At the vehicle , a resist layer thickness measurement was carried out on the body outer skin. The measured values ??were outside the tolerances of original finishes .

Existing collision damage:

found

At the unrepaired vehicle accident damage were observed on visual examination on the body skin .

reference:

Fahrzeug mit bestehenden Unfallschaden, zur Schadensermittlung wurden keine Demontearbeiten durchgeführt, verborgen gebliebene Schäden können nicht ausgeschlossen werden. Unfallschaden Kosten wurden überschlägig Kalkuliert, Kostenerweiterung möglich.

Overview conducted technology audit					
Alternator / Generator:			examined limited	Battery / accumulator:	
			examined limited		
oil loss:			examined limited	examined limited	
air conditioning:			examined limited	lighting system:	
			examined limited		
coupling:			examined limited	Out of order	
engine running:			examined limited	exhaust System:	
			examined limited		
transmission:			examined limited	examined limited	
			examined limited	shock absorber:	
			examined limited		
			examined limited	not possible	

Performed testing technology	
Alternator / Generator:	The function of the alternator (generator) was tested using the charging indicator light in the instrument cluster .
Battery / accumulator:	The battery (accumulator) could be considered limited during the visit .
oil loss:	The vehicle could be checked only limited to oil leaks .
air conditioning:	The air conditioning system could be tested only restricted during the visit .
lighting system:	For sightseeing timing defects in the lighting system were noted . *Fehlermeldung
coupling:	The clutch could be tested only limited within the test drive / pull test .
exhaust System:	The exhaust system has been tested only restricted during the visit .
engine running:	Checking the engine running was limited. Here no audible or visual abnormalities were noted .
shock absorber:	The shock absorber could not be checked during the inspection .
transmission:	The transmission could be examined in the context of limited test drive / pull test .
reference:	*Nutzfahrzeug typische Gebrauchsspuren und Beschädigungen.

damage



	component	Damage	Rep kind
1.	Beleuchtung	Error message	Carry out a fault diagnosis
2.	Wartung (nicht durch Wartungsnachweis belegt)	Missing	Replace
3.	Türeinstieg Vorne - Links	Scrape	Paint
4.		Material wear	Replace
5.	Laderaum und Innenraum	Wear and tear	acceptable
6.	Hecktürverkleidung rechts	Damaged	Replace
7.	Seitenwandverkleidungen links	Damaged	Replace
8.	Seitenwandverkleidungen rechts	Damaged	Replace
9.	Laderaumboden Abschlussleiste	Increase in play	Uninstall/install
10.	Scharniere Hecktüren	Abnormal noises	Carry out a fault diagnosis
11.	Outside mirror - left	Scrape	Replace
12.	Fahrzeug links	Accident damage	Refurbish and paint
13.	Verkleidung Trennwand	Damaged	Replace
14.	Tür Vorne - Links - Innen	Scratch(es)	Smart repair
15.	Sidewall - Rear - right	Damaged	Refurbish and paint
16.	Radlaufleiste hinten Seitenwandverkleidung links außen	Scrape	Replace
17.	Tailgate left	Subsequently painted	acceptable
18.	Fahrzeug (Kratzer, Harz-/Säureeinwirkung, Flugrost, Verschmutzungen)	Scratch(es)	
19.	Hecktür Rechts	Damaged	Smart repair
20.	Radzierblende hinten rechts	Damaged	Replace

The expert points out that the vehicle in addition to the age- damage listed in the report and may have a high mileage -related wear , as in normal use are inevitable (small bumps , dents , scratches) .

There shall be no liability for any defect and / or remained hidden damage in terms of electronics and mechanics accepted ,\r\nand for fraudulent misrepresentation and concealed defects .

photographic record



front Left



front Right




rear Left



rear Right



inside



trunk



instrument cluster



mileage



filler cap



rims



rims




rims



rims



engine compartment



service book



Others



Navigation system



1. Beleuchtung

Error message



3. Türeinstieg Vorne - Links

Scrape



3. Türeinstieg Vorne - Links

Scrape



3. Türeinstieg Vorne - Links

Scrape



3. Türeinstieg Vorne - Links

Scrape



4.

Material wear



4.

Material wear



4. **Material wear**



5. Laderaum und Innenraum **Wear and tear**



5. Laderaum und Innenraum **Wear and tear**



5. Laderaum und Innenraum **Wear and tear**



6. Hecktürverkleidung rechts **Damaged**



6. Hecktürverkleidung rechts **Damaged**



6. Hecktürverkleidung rechts

Damaged



7. Seitenwandverkleidungen links

Damaged




7. Seitenwandverkleidungen links

Damaged




7. Seitenwandverkleidungen links

Damaged



7. Seitenwandverkleidungen links

Damaged



8. Seitenwandverkleidungen rechts

Damaged



8. Seitenwandverkleidungen rechts

Damaged



8. Seitenwandverkleidungen rechts

Damaged



9. Laderaumboden Abschlussleiste

Increase in play



9. Laderaumboden Abschlussleiste

Increase in play



9. Laderaumboden Abschlussleiste

Increase in play



9. Laderaumboden Abschlussleiste

Increase in play



11. Outside mirror - left

Scrape



11. Outside mirror - left

Scrape



12. Fahrzeug links

Accident damage



12. Fahrzeug links

Accident damage



12. Fahrzeug links

Accident damage



12. Fahrzeug links

Accident damage




12. Fahrzeug links

Accident damage



12. Fahrzeug links

Accident damage



12. Fahrzeug links

Accident damage



12. Fahrzeug links

Accident damage



12. Fahrzeug links

Accident damage



13. Verkleidung Trennwand

Damaged



13. Verkleidung Trennwand

Damaged



14. Tür Vorne - Links - Innen

Scratch(es)



14. Tür Vorne - Links - Innen

Scratch(es)



14. Tür Vorne - Links - Innen

Scratch(es)



14. Tür Vorne - Links - Innen

Scratch(es)



15. Sidewall - Rear - right

Damaged



15. Sidewall - Rear - right

Damaged




15. Sidewall - Rear - right

Damaged




15. Sidewall - Rear - right

Damaged




15. Sidewall - Rear - right

Damaged



15. Sidewall - Rear - right

Damaged



15. Sidewall - Rear - right

Damaged



16. Radlaufleiste hinten Seitenwandverkleidung links außen

Scrape



16. Radlaufleiste hinten Seitenwandverkleidung links außen

Scrape



16. Radlaufleiste hinten Seitenwandverkleidung links außen

Scrape



16. Radlaufleiste hinten Seitenwandverkleidung links außen

Scrape



17. Tailgate left

Subsequently painted



18. Fahrzeug (Kratzer, Harz-/Säureeinwirkung, Flugrost, Verschmutzungen)



18. Fahrzeug (Kratzer, Harz-/Säureeinwirkung, Flugrost, Verschmutzungen)
Scratch(es)



19. Hecktür Rechts
Damaged



19. Hecktür Rechts
Damaged



19. Hecktür Rechts
Damaged



20. Radzierblende hinten rechts
Damaged



20. Radzierblende hinten rechts
Damaged



20. Radzierblende hinten rechts

Damaged



20. Radzierblende hinten rechts

Damaged