

status report

customer: Opel Grosskunden/FSL/Free2Move
contract number:
reference:

vehicle data

Opel Astra L Sports Tourer Business Elegance

Vehicle identification number	VXKFCYHZLP1047106	mileage read:	53095 km
∴			
First Registration / construction year:	12.07.2023 / 2023	Visit Date / place of birth:	14.05.2025 Mücke-Atzenhain
Bodywork:	cars	Re - import:	no
Body type:	station wagon	KBA no. :	1889//AEY
Fuel / emission class:	diesel / € 6	transmission type:	manual transmission
Displacement / power:	1499 ccm / 96 kW (131 PS)	Engine:	front-wheel drive
paint:	black	Number of previous owners:	1
Doors / seats:	5 / 5	number keys:	2
Next HU / AU:	- / -	cushion type:	Leather / fabric
Service book available:	yes	Interior Color:	Multicolor
smoking vehicle:	no	Last service km / on the:	- / 19.01.2024
Vehicle roadworthy:	yes	Vehicle roadworthy:	yes
Submitted vehicle documents:	For example, I (Fzg.Schein)	state outside:	3 - Average
visit condition:	-	condition inside:	3 - Average
state general:	3 - Average		

Accessories (presented to the visiting time)

GPS sat nav disk:	Fzg.Schlüssel:	Service book provided / maintained:	Last service at / on:
Hard Disk Drive	2	yes / -	- / 19.01.2024

☒ AHK key	☒ AHK removable	☒ AHK fixed	☒ AHK swivel
☒ Fernbed . entertainment	☒ Fernbed . Auxiliary heating	☒ headphone	☒ LED headlights
☒ Load compartment cover	☒ navigation system	☒ Persenning	☒ partition net
☒ Wind Deflector	☒ Xenon headlights		

☒ **available**

☒ **not available**

Hüsges GmbH
Gießerallee 23
47877 Willich
Tel.: 02154 / 9534 0
E-Mail: gutachten@huesges-group.eu

The status report was created impartially and to the best of my knowledge. The images listed in the status report are part of the vehicle description regarding the equipment and the vehicle condition.



Hüsges Gruppe®
Die Gutachter



mounted tires		
Tyre / wheel type:	Winter tires	aluminum
1st axis - Left / states .	Goodyear	205/55/R16/94V 5.5 mm
1st axis - right / states .	Goodyear	205/55/R16/94V 5.5 mm
2nd axis - Left / states .	Goodyear	205/55/R16/94V 5 mm
2nd axis - right / states .	Goodyear	205/55/R16/94V 5 mm
traffic Safety:	roadworthy	
spare wheel:	Tirefit	
state spare wheel:	-	

standard equipment	
• Airbag driver / passenger side • Ambient lighting door trim • Audio-Navigationssystem Multimedia Navi Pro (10" Display) <i>Freisprecheinrichtung (Bluetooth) mit Sprachsteuerung, Opel Connect</i> • Power side mirrors . adjustable and heated , electric. anklappbar • DAB tuner (digital radio reception) • Roof rails (silver) • Elektron . Stability Program (ESP) • <i>Fahrassistenz-System: Verkehrszeichenerkennung, Fahrassistenz-System: aktiver Spurhalteassistent (Lenkunterstützung)</i> • Driving assistance system front collision warning • Window regulator front electr. with pinch protection • Luggage compartment partition (net) • LED Taillights • Rearview mirror with auto dip • Body 5-door • Head airbag system • Steering wheel (leather) • LM rims • Center armrest forward with storage compartment • Fog lights LED • Tire Pressure Monitoring System • Rear view camera with 180 ° view of the surroundings <i>Parkpilotsystem vorn und hinten</i> • Low pollutant according to the Euro 6d emissions	• Acoustic pedestrian protection (exterior sound) • Anti -lock braking system (ABS) <i>Bremsassistent</i> • Automatic recirculation control • Mirrors painted black • Roof car color • Electr . Brakeforce Distribution (EBD) • Ergonomic driver seat (extended scope) <i>Frontscheibe heizbar (ThermaTec), Sitzheizung vorn, Ergonomiesitz vorn links, Sitzverstellung vorn rechts (6-fach), Sitzverstellung vorn links (8-fach), Sitz vorn links mit ausziehbarer Oberschenkelauflage, Lendenwirbelstütze Sitz vorn links, elektr. verstellbar, Lenkrad heizbar</i> • Driving Assistance System Hill Start Assist (HSA , Hill Start Assist) • Driver assistance system Lane Keeping Assist • Parking brake electrically • Transmission 6-speed • • Isofix admissions for child seat in back seat • 2-zone automatic climate control • Rear headrests (3- fold) • Headlamp leveling automatically • Rear center armrest • Engine 1,5 Ltr. - 96 kW CDTI DPF • Tire repair kit • RuÄÿpartikelfilter • Split rear seat back (402040) • Headlight LED with cornering light <i>Einschaltautomatik für Fahrlicht, Fahrassistenz-System: Fernlichtassistent, Scheibenwischer mit Regensensor</i>

standard • Locking / starting system Keyless Open <i>Keyless Start</i> • Smartphone interface (Apple CarPlay & Android Auto) • Start / Stop system • LED daytime running lights • Central locking with remote control	• Side airbags • Sun visors with mirrors (illuminated) • Socket (12V) port in center console • Sun protection glazing behind darkened (Solar -Protect)
---	---

special Features	
• Metallic-/Mineraleffekt-Lackierung	

We remind you that the data provided were taken from the DAT database. No liability can be assumed for the completeness and correctness.

General examination	
Subfloor Inspection:	not possible A visit to the underside of your vehicle could not be performed. Hoist or lifting means not available .
Mileage plausible:	not testable not testable
reference:	
Note Road Safe:	

Farbabweichung Plastikteile

Accident injury assessment	
Rep. Predamages / -height gross:	Expertly repaired On a vehicle coating thickness measurement on the body outer skin were noted repaired previous damage in the frames that were repaired and apparently without disassembly of components without residual traces accident . If there is an impairment of the observed accident before it was taken into account in if conducted vehicle valuation.
Layers of paint thickness measurement:	Within the tolerances At the vehicle , a resist layer thickness measurement was carried out on the body outer skin. The measured values ??were within the tolerances of original finishes . Evidence that points to a repaired accident damage or repainting carried out , were identified.
Existing collision damage:	Not established



On the vehicle body shell were on visual examination found no existing accident damages (other than the usual signs of use) .

reference:

Overview conducted technology audit

Alternator / Generator:	✓ in order	Battery / accumulator:	✓ in order
oil loss:	✓ in order		
air conditioning:	✓ in order	lighting system:	✓ in order
coupling:	✓ in order	exhaust System:	✓ examined limited
engine running:	✓ in order	shock absorber:	✓ examined limited
transmission:	✓ in order		

Performed testing technology

Alternator / Generator:	The function of the alternator (generator) was tested using the charging indicator light in the instrument cluster .
Battery / accumulator:	The battery (accumulator) was examined during the inspection .
oil loss:	The vehicle was inspected during the visit to an oil leak .
air conditioning:	A function of the air conditioning was found to visiting time .
lighting system:	The lighting system was to tour date in order.
coupling:	The coupling was examined during the test drive / pull test .
exhaust System:	The exhaust system has been tested only restricted during the visit .
engine running:	A field test of the engine was performed.
shock absorber:	The shock absorber could be tested only restricted during the visit .
transmission:	The transmission was examined during the test drive / pull test .
reference:	*Fahrzeug mit Gebrauchsspuren

damage



	component	Damage	Rep kind
1.	Rear door - left	Subsequently painted	acceptable
2.	Sidewall - Rear - Left	Subsequently painted	acceptable
3.	Innenraum	Dirty (slightly)	
4.	Kofferraumbodenbelag	Dirty	
5.	Heckdeckelverkleidung	Damaged	Replace
6.	Karosserie Außen	Surface scratch(es)	
7.	Sidewall - Rear - right	Damaged	Refurbish and paint
8.	Door Rear - right	Damaged	Refurbish and paint
9.	Front door - right	Damaged	Refurbish and paint
10.	Outside mirror - right	Damaged	Replace
11.	Wartung	Due	Replace

The expert points out that the vehicle in addition to age to the damage listed in the report and may have a high mileage -related wear , as in normal use are inevitable (small bumps , dents , scratches) and thus is not entitled to change or reduction .

There shall be no liability for any defect and / or remained hidden damage in terms of electronics and mechanics accepted ,r\nand for fraudulent misrepresentation and concealed defects .

photographic record



front Left



front Right



rear Left



rear Right




inside



trunk



instrument cluster



mileage



filler cap



rims



rims




rims



rims



engine compartment



service book



Others



Navigation system



1. Rear door - left



1. Rear door - left



2. Sidewall - Rear - Left



2. Sidewall - Rear - Left




3. Innenraum




3. Innenraum



3. Innenraum



3. Innenraum



3. Innenraum



3. Innenraum



3. Innenraum




4. Kofferraumbodenbelag



4. Kofferraumbodenbelag




4. Kofferraumbodenbelag



4. Kofferraumbodenbelag



5. Heckdeckelverkleidung




5. Heckdeckelverkleidung



5. Heckdeckelverkleidung



5. Heckdeckelverkleidung



5. Heckdeckelverkleidung



5. Heckdeckelverkleidung



5. Heckdeckelverkleidung



5. Heckdeckelverkleidung



5. Heckdeckelverkleidung



7. Sidewall - Rear - right



7. Sidewall - Rear - right



7. Sidewall - Rear - right



7. Sidewall - Rear - right




8. Door Rear - right



8. Door Rear - right



8. Door Rear - right



8. Door Rear - right



8. Door Rear - right




8. Door Rear - right




9. Front door - right



9. Front door - right



9. Front door - right



9. Front door - right



9. Front door - right



9. Front door - right



9. Front door - right



9. Front door - right




9. Front door - right



10. Outside mirror - right



10. Outside mirror - right



10. Outside mirror - right



10. Outside mirror - right