



Hüsges Gruppe®
Die Gutachter

status report

customer: Bank 11, Neuss
contract number: 867016131
reference:

vehicle data

Opel Astra L Lim. 5-trg. GS Line

Vehicle identification number	VXKFPHNSLN1024942	mileage read:	15515 km
First Registration / construction year:	12.08.2022 / 2022	Visit Date / place of birth:	14.05.2025 Heidenheim
Bodywork:	cars	Re - import:	no
Body type:	hatchback	KBA no. :	1889//AET
Fuel / emission class:	gasoline / € 6	transmission type:	6 speed manual transmission
Displacement / power:	1199 ccm / 96 kW (131 PS)	Engine:	front-wheel drive
paint:	Chili Rot/Kardio Rot	Number of previous owners:	Unbekannt
Doors / seats:	5 / 5	number keys:	2
Next HU / AU:	- / -	cushion type:	Leather / fabric
Service book available:	yes	Interior Color:	black
smoking vehicle:	no	Last service km / on the:	- / -
Vehicle roadworthy:	no	Vehicle roadworthy:	no
Submitted vehicle documents:	-	state outside:	3 - Average
visit condition:	in the parking garage	condition inside:	3 - Average
state general:	3 - Average		

Accessories (presented to the visiting time)

GPS sat nav disk:	Fzg.Schlüssel:	Service book provided /	Last service at / on:
Hard Disk Drive	2	maintained:	- / -
		yes / -	
☒ AHK key	☒ AHK removable	☒ AHK fixed	☒ AHK swivel
☒ Fernbed . entertainment	☒ Fernbed . Auxiliary heating	☒ headphone	☒ LED headlights
☒ Load compartment cover	☒ navigation system	☒ Persenning	☒ partition net
☒ Wind Deflector	☒ Xenon headlights		

☒ **available**

☒ **not available**

Hüsges GmbH
Ein Unternehmen der Hüsges Gruppe
Bankverbindung
Sparkasse Krefeld
Kto.-Nr. 1048206 · BLZ 320 500 00

Gießerallee 23
47877 Willich
Tel.: 02154 / 9534 0
Fax: 02154 / 9534 1025
Email:
info@huesges-gruppe.de



Rechtsform: Gesellschaft
mit beschränkter Haftung
Sitz: Willich
Registergericht: Krefeld HRB
Steuer-Nr.: 102/5821/0943

Geschäftsführung:
Arndt Hüsges
Dipl.- Ing. (FH) Bernd Hüsges

Hüsges GmbH
Gießerallee 23
47877 Willich
Tel.: 02154 / 9534 0
E-Mail: gutachten@huesges-group.eu

The status report was created impartially and to the best of my knowledge. The images listed in the status report are part of the vehicle description regarding the equipment and the vehicle condition.



Hüsges Gruppe®
Die Gutachter



mounted tires		
Tyre / wheel type:	summer tires	polished aluminum
1st axis - Left / states .	Michelin	225/40/R18/92Y 6 mm
1st axis - right / states .	Michelin	225/40/R18/92Y 6 mm
2nd axis - Left / states .	Michelin	225/40/R18/92Y 6.5 mm
2nd axis - right / states .	Michelin	225/40/R18/92Y 6.5 mm
traffic Safety:	roadworthy	
spare wheel:	nicht vorhanden	
state spare wheel:	Siehe Gutachten	

standard equipment	
• Airbag Fahrer-/Beifahrerseite (26803) Akustischer Fußgängerschutz (Außensound) (38937) Ambiente-Beleuchtung Türverkleidung (37605) Anti-Blockier-System (ABS) (40000) Bremsassistent Außenspiegel elektr. verstell- und heizbar, elektr. anklappbar (15302) Außenspiegel schwarz lackiert (15813) DAB-Tuner (Radioempfang digital) (24050) Dach Diamant-Schwarz (11413) Design-Paket high gloss Exterieur (1124) Dach, Design-Ausführung (schwarz), Kühlergrill, Opel Vizor, Rahmen in Hochglanz-Schwarz, Schriftzug Heckklappe Schwarz, Hochglanz Elektr. Bremskraftverteilung (EBD) (40307) Elektron. Stabilitäts-Programm (ESP) (70308) Fahrassistentz-System Berganfahr-Assistent (HSA, Hill Start Assist) (70603) Fahrassistentz-System Frontkollisionswarnung (40963) Fahrassistentz-System Spurhalteassistent (42907) Fensterheber vorn elektr. mit Einklemmschutz (35004) Feststellbremse elektrisch (40803) Getriebe 6-Gang (75205) Heckleuchten LED (18802) Innenspiegel mit Abblendautomatik (37901) Isofix-Aufnahmen für Kindersitz an Rücksitz (39308) Kamerasystem 360° (39816) Parkpilotsystem vorn und hinten Karosserie 5-türig (10005) Klimaautomatik 2-Zonen (29003) Kopf-Airbag-System (26901) Kopfstützen hinten (3-fach) (34807) Lenkrad (Leder) (69009) Leuchtweitenregelung automatisch (18208) Mittelarmlehne hinten (27300) Mittelarmlehne vorn mit Ablagefach (27204) Motor 1,2 Ltr. - 96 kW (96600) Nebelscheinwerfer LED (18313) Otto-	

Partikelfilter (OPF) (77640) Reifen-Reparaturkit
 (68802) Reifendruck-Kontrollsystem (25903)
 Schadstoffarm nach Abgasnorm Euro 6d (77274)
 Scheinwerfer LED Eco (18032) Einschaltautomatik
 für Fahrlicht, Fahrassistenz-System
 Fernlichtassistent, Scheibenwischer mit
 Regensensor Schließ-/Startsystem Keyless Open
 (35507) Keyless Start Seitenairbag vorn (26903)
 Sonnenblenden mit Spiegel (beleuchtet) (37905)
 Start/Stop-Anlage (77601) Steckdose (12V-
 Anschluß) in Mittelkonsole (39010) Tagfahrlicht
 LED (18913) Wärmeschutzverglasung hinten
 abgedunkelt (Solar-Protect) (22203)
 Zentralverriegelung mit Fernbedienung (35301)

special Features

- | | |
|--|--|
| <ul style="list-style-type: none"> • Anhängerkupplung (Kugelkopf abnehmbar) ohne Werkzeug • Fahrassistenz-Paket IntelliDrive • LM-Felgen 7,5x18 (5-Speichen, Tricolor, schwarz) | <ul style="list-style-type: none"> • Ergonomiesitz vorn links/rechts • Head-up-Display • Metallic-/Mineraleffekt-Lackierung |
|--|--|

We remind you that the data provided were taken from the DAT database. No liability can be assumed for the completeness and correctness.

General examination

Subfloor Inspection:	Conducted limited To investigate the vehicle (ä . Lift o .) Were not lifting means even a ramp or pit available. For this reason, a visit to the vehicle's underside was limited.
Mileage plausible:	not testable not testable
reference:	
Note Road Safe:	Frontschaden

Farbabweichung Plastikteile

Accident injury assessment

Rep. Predamages / -height gross:	If not properly repaired The vehicle repaired previous damage have been observed on the body outer skin that are exposed and apparently with no disassembly of components with residual traces
---	--

**Layers of paint thickness
measurement:**

accident . If there is an impairment of the observed accident before it was taken into account in if conducted vehicle valuation.

Out of tolerance

At the vehicle , a resist layer thickness measurement was carried out on the body outer skin. The measured values ??were outside the tolerances of original finishes .

Existing collision damage:

found

At the unrepared vehicle accident damage were observed on visual examination on the body skin .

reference:

Fahrzeug mit bestehenden Unfallschaden, zur Schadensermittlung wurden keine Demontearbeiten durchgeführt, verborgen gebliebene Schäden können nicht ausgeschlossen werden. Unfallschaden Kosten wurden überschlägig Kalkuliert, Kostenerweiterung möglich.

Overview conducted technology audit					
Alternator / Generator:			examined limited	Battery / accumulator:	
			Out of order		
oil loss:			examined limited		
air conditioning:			examined limited	lighting system:	
			examined limited		
coupling:			examined limited	exhaust System:	
			examined limited		
engine running:			examined limited	shock absorber:	
			examined limited		
transmission:			examined limited		

Performed testing technology	
Alternator / Generator:	The function of the alternator (generator) was tested using the charging indicator light in the instrument cluster .
Battery / accumulator:	The battery (accumulator) was discharged for visiting time . **Battery deep discharge. Vehicle was bridged with a jumper.
oil loss:	The vehicle could be checked only limited to oil leaks .
air conditioning:	The air conditioning system could be tested only restricted during the visit .
lighting system:	The Lichtenlange could be considered limited to the tour date .
coupling:	The clutch could be tested only limited within the test drive / pull test .
exhaust System:	The exhaust system has been tested only restricted during the visit .
engine running:	Checking the engine running was limited. Here no audible or visual abnormalities were noted .
shock absorber:	The shock absorber could be tested only restricted during the visit .
transmission:	The transmission could be examined in the context of limited test drive / pull test .
reference:	*Fahrzeug war zum Zeitpunkt der Begutachtung Verschmutzt/Nass/Vereist/Zugeparkt oder wurde bei unzureichender bzw schlechter Beleuchtung besichtigt.Manche Bereiche waren unter Umständen verdeckt oder zugesagt.Unter Umständen waren nicht alle Fahrzeugsysteme und Ausstattung prüfbar.Versteckte Schäden oder Schadensenerweiterung möglich.

damage



component	Damage	Rep kind
1. Sidewall - Rear - right	Subsequently painted	acceptable
2. Door Rear - right	Subsequently painted	acceptable
3. Front door - right	Subsequently painted	acceptable
4. Front fender - right	Subsequently painted	acceptable
5. Motorkontrolle	Error message	Carry out a fault diagnosis
6. Batterie	Empty battery	Replace
7. Wartung	Due	Replace
8. Reifendichtmittel inkl Kompressor	Missing	Replace
9. Felge vorn links	Scratch(es)	Replace
10. Front fender - left	Accident damage	Replace
11. Front door - left	Scratch(es)	Paint
12. Sidewall - Rear - Left	Deformed	Refurbish and paint
13. Felge Hinten links	Scratch(es)	Replace
14. Rear bumper	Scratch(es)	Paint
15. Front fender - right	Accident damage	Refurbish and paint
16. Felge vorn rechts	Scratch(es)	Replace
17. Türverkleidung Hinten rechts	Scratch(es)	Smart repair
18. Hupe	Not okay	Carry out a fault diagnosis
19. Front bumper	Accident damage	Replace
20. Halogen headlights - left	Accident damage	Replace
21. hood	Accident damage	Replace

The expert points out that the vehicle in addition to age to the damage listed in the report and may have a high mileage -related wear , as in normal use are inevitable (small bumps , dents , scratches) and thus is not entitled to change or reduction .

There shall be no liability for any defect and / or remained hidden damage in terms of electronics and mechanics accepted ,r\nand for fraudulent misrepresentation and concealed defects .

photographic record



front Left



front Right



rear Left



rear Right



inside



inside



trunk



instrument cluster



mileage



filler cap



rims



rims




rims



rims




engine compartment



service book



Others



Navigation system



1. Sidewall - Rear - right



2. Door Rear - right




3. Front door - right




4. Front fender - right



5. Motorkontrolle



5. Motorkontrolle



7. Wartung



9. Felge vorn links



9. Felge vorn links




10. Front fender - left



10. Front fender - left



11. Front door - left



11. Front door - left



11. Front door - left



12. Sidewall - Rear - Left



12. Sidewall - Rear - Left



13. Felge Hinten links



13. Felge Hinten links



14. Rear bumper



14. Rear bumper



14. Rear bumper



14. Rear bumper



14. Rear bumper



15. Front fender - right



15. Front fender - right



16. Felge vorn rechts



16. Felge vorn rechts



17. Türverkleidung Hinten rechts



17. Türverkleidung Hinten rechts



19. Front bumper



19. Front bumper



20. Halogen headlights - left



20. Halogen headlights - left



21. hood



21. hood



21. hood