



status report

customer: Opel Grosskunden/FSL/Free2Move
contract number:
reference:

vehicle data

Opel Astra L Lim. 5-trg. Elegance

Vehicle identification number	VXKFPHNSTN1022513	mileage read:	32952 km
First Registration / construction year:	18.07.2022 / 2022	Visit Date / place of birth:	11.04.2025 Dahlwitz-Hoppegarten
Bodywork:	cars	Re - import:	no
Body type:	hatchback	KBA no. :	1889//AET
Fuel / emission class:	gasoline / € 6	transmission type:	automatic
Displacement / power:	1199 ccm / 96 kW (131 PS)	Engine:	front-wheel drive
paint:	Jade Weiss/Arktis Weiss	Number of previous owners:	2
Doors / seats:	5 / 5	number keys:	2
Next HU / AU:	- / -	cushion type:	Imitation leather / fabric
Service book available:	yes	Interior Color:	gray
smoking vehicle:	yes	Last service km / on the:	16799 / 02.11.2023
Vehicle roadworthy:	yes	Vehicle roadworthy:	no
Submitted vehicle documents:	Eg II (veh - letter)	state outside:	4 - moderate
visit condition:	-	condition inside:	4 - moderate
state general:	4 - moderate		

Accessories (presented to the visiting time)

GPS sat nav disk:	Fzg.Schlüssel:	Service book provided / maintained:	Last service at / on:
-	2	yes / -	16799 / 02.11.2023
☒ Fernbed . Auxiliary heating	☒ partition net	☒ Wind Deflector	☒ AHK fixed
☒ AHK removable	☒ AHK swivel	☒ AHK key	☒ Fernbed . entertainment
☒ headphone	☒ Load compartment cover	☒ LED headlights	☒ navigation system
☒ Persenning	☒ Xenon headlights		

☒ available ☒ not available

Hüsges GmbH
Gießerallee 23
47877 Willich
Tel.: 02154 / 9534 0
E-Mail: gutachten@huesges-group.eu

The status report was created impartially and to the best of my knowledge. The images listed in the status report are part of the vehicle description regarding the equipment and the vehicle condition.



Hüsges Gruppe®
Die Gutachter



mounted tires		
Tyre / wheel type:	All season tires	aluminum
1st axis - Left / states .	Goodyear	205/55/R16/94V 4 mm
1st axis - right / states .	Goodyear	205/55/R16/94V 4 mm
2nd axis - Left / states .	Goodyear	205/55/R16/94V 6 mm
2nd axis - right / states .	Goodyear	205/55/R16/94V 6 mm
traffic Safety:	not roadworthy	
spare wheel:	-	
state spare wheel:	-	

standard equipment	
• Airbag driver / passenger side • Ambient lighting door trim • Multimedia audio system <i>Freisprecheinrichtung Bluetooth, Opel Connect, Smartphone Schnittstelle (Apple CarPlay & Android Auto)</i> • Mirrors painted black • Roof car color • Elektron . Stability Program (ESP) • Driving Assistance System Hill Start Assist (HSA , Hill Start Assist) • Driver assistance system Lane Keeping Assist • Parking brake electrically • LED Taillights • Isofix admissions for child seat in back seat • 2-zone automatic climate control • Rear headrests (3- fold) • Headlamp leveling automatically • Rear center armrest • • Otto Particle Filter (OPF) • Tire Pressure Monitoring System • Low pollutant according to the Euro 6d emissions standard • Locking / starting system Keyless Open <i>Keyless Start</i> • Sun visors with mirrors (illuminated) • Socket (12V) port in center console • Sun protection glazing behind darkened (Solar -Protect)	• Acoustic pedestrian protection (exterior sound) • Anti -lock braking system (ABS) <i>Bremsassistent</i> • Power side mirrors . adjustable and heated , electric. anklappbar • DAB tuner (digital radio reception) • Electr . Brakeforce Distribution (EBD) • <i>Fahrassistenz-System: Verkehrszeichenerkennung, Fahrassistenz-System: Müdigkeitserkennungs-Sensor, Fahrassistenz-System: aktiver Spurhalteassistent (Lenkunterstützung)</i> • Driving assistance system front collision warning • Window regulator front electr. with pinch protection • Transmission automatic - with start / stop (8-speed) • Rearview mirror with auto dip • Body 5-door • Head airbag system • Steering wheel (leather) • LM rims • Center armrest forward with storage compartment • Fog lights LED • Tire repair kit • Rear view camera with 180 ° view of the surroundings <i>Parkpilotsystem vorn und hinten</i> • Headlight LED with cornering light <i>Einschaltautomatik für Fahrlicht, Fahrassistenz-System: Fernlichtassistent, Scheibenwischer mit Regensensor</i> • Side airbags • Start / Stop system

- LED daytime running lights
- Central locking with remote control

special Features

- Ergonomic seats driver and passenger seat (extended scope)
Frontscheibe heizbar (ThermaTec), Sitzheizung vorn, Ergonomiesitz vorn links/rechts, Lenkrad heizbar
- Special varnishing snow-white

We remind you that the data provided were taken from the DAT database. No liability can be assumed for the completeness and correctness.

General examination

Subfloor Inspection:	Conducted limited To investigate the vehicle (ä . Lift o .) Were not lifting means even a ramp or pit available. For this reason, a visit to the vehicle's underside was limited.
Mileage plausible:	no no
reference:	
Note Road Safe:	Unfallschaden

Farbabweichung Plastikteile

Accident injury assessment

Rep. Predamages / -height gross:	no detectable As part of a paint film thickness measuring the body outer skin no previous damage could be detected .
Layers of paint thickness measurement:	Within the tolerances At the vehicle , a resist layer thickness measurement was carried out on the body outer skin. The measured values ??were within the tolerances of original finishes . Evidence that points to a repaired accident damage or repainting carried out , were identified.
Existing collision damage:	found At the unrepaired vehicle accident damage were observed on visual examination on the body skin .
reference:	Fahrzeug mit bestehenden Unfallschaden, zur Schadensermittlung wurden keine Demontagearbeiten durchgeführt, verborgen gebliebene Schäden können nicht ausgeschlossen werden. Unfallschaden Kosten wurden überschlägig Kalkuliert, Kostenerweiterung möglich.

Overview conducted technology audit					
Alternator / Generator:			examined limited	Battery / accumulator:	
			in order		
oil loss:			examined limited		
air conditioning:			not possible	lighting system:	
			unavailable		
engine running:			examined limited		
transmission:			examined limited		
					

Performed testing technology	
Alternator / Generator:	The function of the alternator (generator) was tested using the charging indicator light in the instrument cluster .
Battery / accumulator:	The battery (accumulator) was examined during the inspection .
oil loss:	The vehicle could be checked only limited to oil leaks .
air conditioning:	The air conditioning could not be checked during the inspection . **Due to weather conditions not possible examination.
lighting system:	The Lichtanlage could be considered limited to the tour date .
coupling:	The vehicle has no clutch , as it is a Automatikgetriebe or the like.
exhaust System:	The exhaust system has been tested only restricted during the visit .
engine running:	Checking the engine running was limited. Here no audible or visual abnormalities were noted .
shock absorber:	The shock absorber could be tested only restricted during the visit .
transmission:	The transmission could be examined in the context of limited test drive / pull test .
reference:	*Fahrzeug hat Alter und Laufleistungs bedingte Gebrauchsspuren innen und außen.

damage



component	Damage	Rep kind
1. maintenance	Due	Replace
2. Reifenrep.Satz	Missing	Replace
3. Cargo cover	Missing	Replace
4. Rear bumper	Damaged	Replace
5. tailgate trim	Damaged	Replace
6.	Damaged	Replace
7. tailgate	Wear and tear	acceptable
8. roof	Deformed (slightly)	Smart repair
9. Sidewall - Rear - right	Scratch(es)	Paint
10.	Scratch(es)	Smart repair
11. side skirt - right	Deformed (slightly)	Refurbish and paint
12. Türeinstieg Hinten - Rechts	Scratch(es)	Paint
13.	Dirty (strong)	
14. Door Rear - right	Damaged	Smart repair
15. Front door - right	Deformed (slightly)	Smart repair
16. exterior body	Accident damage	Replace
17. Sidewall - Rear - Left	Wear and tear	acceptable
18. Rear door - left	Deformed (slightly)	Smart repair
19. Türeinstieg Hinten - Links	Scratch(es)	Paint
20. Front door - left	Wear and tear	acceptable
21.	Scratch(es)	Paint
22.	Damaged	Replace

The expert points out that the vehicle in addition to age to the damage listed in the report and may have a high mileage -related wear , as in normal use are inevitable (small bumps , dents , scratches) and thus is not entitled to change or reduction .

There shall be no liability for any defect and / or remained hidden damage in terms of electronics and mechanics accepted ,\r\nand for fraudulent misrepresentation and concealed defects .

photographic record



front Left



front Right



rear Left



rear Right



inside



trunk



instrument cluster



mileage



filler cap



rims



rims




rims



rim



engine compartment



service book



Others



1. maintenance



3. Cargo cover



4. Rear bumper



4. Rear bumper



4. Rear bumper



4. Rear bumper




4. Rear bumper



5. tailgate trim




6.



7. tailgate



8. roof



8. roof



9. Sidewall - Rear - right



9. Sidewall - Rear - right



10.



11. side skirt - right



11. side skirt - right



12. Türeinstieg Hinten - Rechts



13.




13.



13.



14. Door Rear - right



14. Door Rear - right



15. Front door - right



15. Front door - right



16. exterior body



16. exterior body



16. exterior body



16. exterior body



16. exterior body



16. exterior body




17. Sidewall - Rear - Left



17. Sidewall - Rear - Left



18. Rear door - left



18. Rear door - left



19. Türeinstieg Hinten - Links



20. Front door - left



20. Front door - left



21.



21.



22.