



status report

customer:	Opel Grosskunden/FSL/Free2Move
contract number:	
reference:	

vehicle data			
Opel Astra L Sports Tourer Business Elegance			
Vehicle identification number	VXKFRHNSTP1042460	mileage read:	37755 km
..:			
First Registration / construction year:	05.07.2023 / 2023	Visit Date / place of birth:	01.09.2025 Heidenheim
Bodywork:	cars	Re - import:	no
Body type:	station wagon	KBA no. :	1889//AFA
Fuel / emission class:	gasoline / € 6	transmission type:	automatic
Displacement / power:	1199 ccm / 96 kW (131 PS)	Engine:	front-wheel drive
paint:	black	Number of previous owners:	1
Doors / seats:	5 / 5	number keys:	2
Next HU / AU:	07.2026 / 07.2026	cushion type:	substance
Service book available:	yes	Interior Color:	gray
smoking vehicle:	no	Last service km / on the:	37744 / 21.07.2025
Vehicle roadworthy:	yes	Vehicle roadworthy:	yes
Submitted vehicle	-	state outside:	3 - Average
documents:			
visit condition:	-	condition inside:	3 - Average
state general:	3 - Average		

Accessories (presented to the visiting time)			
GPS sat nav disk:	Fzg.Schlüssel:	Service book provided /	Last service at / on:
Hard Disk Drive	2	maintained:	37744 / 21.07.2025
		yes / -	
☒ AHK key	☒ AHK removable	☒ AHK fixed	☒ AHK swivel
☒ Fernbed . entertainment	☒ Fernbed . Auxiliary heating	☒ headphone	☒ LED headlights
☒ Load compartment cover	☒ navigation system	☒ Persenning	☒ partition net
☒ Wind Deflector	☒ Xenon headlights		

☒ **available** ☒ **not available**

The status report was created impartially and to the best of my knowledge. The images listed in the status report are part of the vehicle description regarding the equipment and the vehicle condition.



Hüsges Gruppe®
Die Gutachter



mounted tires		
Tyre / wheel type:	summer tires	original aluminum
1st axis - Left / states .	Michelin	225/45/R17/94V 5.2 mm
1st axis - right / states .	Michelin	225/45/R17/94V 5.2 mm
2nd axis - Left / states .	Michelin	225/45/R17/94V 5.6 mm
2nd axis - right / states .	Michelin	225/45/R17/94V 5.6 mm
traffic Safety:	roadworthy	
spare wheel:	-	
state spare wheel:	-	

Unmounted tires		
Tyre / wheel type:	Winter tires	Steel with wheel cover
1st axis - Left / states .	Fulda	205/55/R16/91H 6.1 mm
1st axis - right / states .	Fulda	205/55/R16/91H 7.1 mm
2nd axis - Left / states .	Fulda	205/55/R16/91H 7.1 mm
2nd axis - right / states .	Fulda	205/55/R16/91H 6.1 mm
traffic Safety:	roadworthy	

standard equipment	
• Airbag driver / passenger side • Ambient lighting door trim • Audio-Navigationssystem Multimedia Navi Pro (10" Display) <i>Freisprecheinrichtung (Bluetooth) mit Sprachsteuerung, Opel Connect</i> • Power side mirrors . adjustable and heated , electric. anklappbar • DAB tuner (digital radio reception) • Roof rails (silver) • Elektron . Stability Program (ESP) • <i>Fahrassistenz-System: Verkehrszeichenerkennung, Fahrassistenz-System: aktiver Spurhalteassistent (Lenkunterstützung)</i> • Driving assistance system front collision warning • Window regulator front electr. with pinch protection • Luggage compartment partition (net) • LED Taillights • Rearview mirror with auto dip • Body 5-door • Head airbag system • Steering wheel (leather) • LM rims	• Acoustic pedestrian protection (exterior sound) • Anti -lock braking system (ABS) <i>Bremsassistent</i> • Automatic recirculation control • Mirrors painted black • Roof car color • Electr . Brakeforce Distribution (EBD) • Ergonomic driver seat (extended scope) <i>Frontscheibe heizbar (ThermaTec), Sitzheizung vorn, Ergonomiesitz vorn links, Sitzverstellung vorn rechts (6-fach), Sitzverstellung vorn links (8-fach), Sitz vorn links mit ausziehbarer Oberschenkelauflage, Lendenwirbelstütze Sitz vorn links, elektr. verstellbar, Lenkrad heizbar</i> • Driving Assistance System Hill Start Assist (HSA , Hill Start Assist) • Driver assistance system Lane Keeping Assist • Parking brake electrically • Transmission automatic - with start / stop (8-speed) • • Isofix admissions for child seat in back seat • 2-zone automatic climate control • Rear headrests (3- fold) • Headlamp leveling automatically • Rear center armrest

• Center armrest forward with storage compartment • Fog lights LED • Tire repair kit • Rear view camera with 180 ° view of the surroundings <i>Parkpilotsystem vorn und hinten</i> • Low in emissions according to the Euro 6e emissions standard • Locking / starting system Keyless Open <i>Keyless Start</i> • Smartphone interface (Apple CarPlay & Android Auto) • Start / Stop system • LED daytime running lights • Central locking with remote control	• • Otto Particle Filter (OPF) • Tire Pressure Monitoring System • Split rear seat back (402040) • Headlight LED with cornering light <i>Einschaltautomatik für Fahrlicht, Fahrassistenz-System: Fernlichtassistent, Scheibenwischer mit Regensensor</i> • Side airbags • Sun visors with mirrors (illuminated) • Socket (12V) port in center console • Sun protection glazing behind darkened (Solar -Protect)
---	---

special Features	
• IntelliDrive driving assistance package <i>Adaptive Geschwindigkeits-Regelanlage (Tempomat), Autonomer Notbrems-Assistent und Frontkamera, Frontkamera inkl. Adaptive Geschwindigkeitsregelanlage, Fahrassistenz-System: Autonomer Notbrems-Assistent mit Frontkollisionswarnung und Fußgängererkennung, Fahrassistenz-System: Verkehrszeichenerkennung, Fahrassistenz-System: aktiver Spurhalteassistent (Lenkunterstützung), Fahrassistenz-System: Querverkehrs- Assistent Heck (Rückfahr-Assistent), Fahrassistenz-System: Müdigkeitserkennungs-Sensor</i> • Metallic / mineral effect spraying	•

We remind you that the data provided were taken from the DAT database. No liability can be assumed for the completeness and correctness.

General examination	
Subfloor Inspection:	not possible A visit to the underside of your vehicle could not be performed. Hoist or lifting means not available .
Mileage plausible:	yes yes
reference:	
Note Road Safe:	

Accident injury assessment

Rep. Predamages / -height gross:	no detectable As part of a paint film thickness measuring the body outer skin no previous damage could be detected .
Layers of paint thickness measurement:	Within the tolerances At the vehicle , a resist layer thickness measurement was carried out on the body outer skin. The measured values ??were within the tolerances of original finishes . Evidence that points to a repaired accident damage or repainting carried out , were identified.
Existing collision damage:	Not established On the vehicle body shell were on visual examination found no existing accident damages (other than the usual signs of use) .
reference:	

Overview conducted technology audit					
Alternator / Generator:			examined limited	Battery / accumulator:	
			in order		
oil loss:			in order		
air conditioning:			in order	lighting system:	
			in order		
coupling:			unavailable	exhaust System:	
			examined limited		
engine running:			in order	shock absorber:	
			not checked		
transmission:			examined limited		

Performed testing technology	
Alternator / Generator:	The function of the alternator (generator) was tested using the charging indicator light in the instrument cluster .
Battery / accumulator:	The battery (accumulator) was examined during the inspection .
oil loss:	The vehicle was inspected during the visit to an oil leak .
air conditioning:	A function of the air conditioning was found to visiting time .
lighting system:	The lighting system was to tour date in order.
coupling:	The vehicle has no clutch , as it is a Autmatikgetriebe or the like.
exhaust System:	The exhaust system has been tested only restricted during the visit .
engine running:	A field test of the engine was performed.
shock absorber:	The shocks were not examined during the inspection .
transmission:	The transmission could be examined in the context of limited test drive / pull test .
reference:	*Fahrzeug hat Alter und Laufleistungs bedingte Gebrauchsspuren innen und außen.

damage

The expert points out that the vehicle in addition to the age- damage listed in the report and may have a high mileage -related wear , as in normal use are inevitable (small bumps , dents , scratches) .

There shall be no liability for any defect and / or remained hidden damage in terms of electronics and mechanics accepted ,r\nand for fraudulent misrepresentation and concealed defects .

photographic record



front Left



front Right



rear Left



rear Right




inside



trunk



instrument cluster



mileage



filler cap



rims



rims




rims



rims




engine compartment



service book



Others



Navigation system



tires



tires



tires



tires