



## status report

|                         |                                       |
|-------------------------|---------------------------------------|
| <b>customer:</b>        | <b>Opel Grosskunden/FSL/Free2Move</b> |
| <b>contract number:</b> |                                       |
| <b>reference:</b>       |                                       |

| vehicle data                            |                                  |                              |                              |
|-----------------------------------------|----------------------------------|------------------------------|------------------------------|
| <b>Opel Astra L Sports Tourer Basis</b> |                                  |                              |                              |
| Vehicle identification number           | <b>VXKFRHNSTP1042461</b>         | mileage read:                | <b>45452 km</b>              |
| ..                                      |                                  |                              |                              |
| First Registration / construction year: | <b>05.07.2023 / 2023</b>         | Visit Date / place of birth: | <b>01.09.2025 Heidenheim</b> |
| Bodywork:                               | <b>cars</b>                      | Re - import:                 | <b>no</b>                    |
| Body type:                              | <b>station wagon</b>             | KBA no. :                    | <b>1889//AFA</b>             |
| Fuel / emission class:                  | <b>gasoline / € 6</b>            | transmission type:           | <b>automatic</b>             |
| Displacement / power:                   | <b>1199 ccm / 81 kW (110 PS)</b> | Engine:                      | <b>front-wheel drive</b>     |
| paint:                                  | <b>black</b>                     | Number of previous owners:   | <b>1</b>                     |
| Doors / seats:                          | <b>5 / 5</b>                     | number keys:                 | <b>2</b>                     |
| Next HU / AU:                           | <b>07.2026 / 07.2026</b>         | cushion type:                | <b>substance</b>             |
| Service book available:                 | <b>yes</b>                       | Interior Color:              | <b>gray</b>                  |
| smoking vehicle:                        | <b>no</b>                        | Last service km / on the:    | <b>41138 / 06.05.2025</b>    |
| Vehicle roadworthy:                     | <b>yes</b>                       | Vehicle roadworthy:          | <b>yes</b>                   |
| Submitted vehicle                       | <b>-</b>                         | state outside:               | <b>3 - Average</b>           |
| documents:                              |                                  |                              |                              |
| visit condition:                        | <b>-</b>                         | condition inside:            | <b>3 - Average</b>           |
| state general:                          | <b>3 - Average</b>               |                              |                              |

| Accessories (presented to the visiting time )               |                                                                 |                                                |                                                    |
|-------------------------------------------------------------|-----------------------------------------------------------------|------------------------------------------------|----------------------------------------------------|
| <b>GPS sat nav disk:</b>                                    | <b>Fzg.Schlüssel:</b>                                           | <b>Service book provided / maintained:</b>     | <b>Last service at / on:</b>                       |
| Hard Disk Drive                                             | 2                                                               | yes / -                                        | 41138 / 06.05.2025                                 |
| <input checked="" type="checkbox"/> AHK key                 | <input checked="" type="checkbox"/> AHK removable               | <input checked="" type="checkbox"/> AHK fixed  | <input checked="" type="checkbox"/> AHK swivel     |
| <input checked="" type="checkbox"/> Fernbed . entertainment | <input checked="" type="checkbox"/> Fernbed . Auxiliary heating | <input checked="" type="checkbox"/> headphone  | <input checked="" type="checkbox"/> LED headlights |
| <input checked="" type="checkbox"/> Load compartment cover  | <input checked="" type="checkbox"/> navigation system           | <input checked="" type="checkbox"/> Persenning | <input checked="" type="checkbox"/> partition net  |
| <input checked="" type="checkbox"/> Wind Deflector          | <input checked="" type="checkbox"/> Xenon headlights            |                                                |                                                    |



**available**



**not available**

Hüsges GmbH  
Gießerallee 23  
47877 Willich  
Tel.: 02154 / 9534 0  
E-Mail: gutachten@huesges-group.eu

The status report was created impartially and to the best of my knowledge. The images listed in the status report are part of the vehicle description regarding the equipment and the vehicle condition.



Hüsges Gruppe®  
**Die Gutachter**



| mounted tires               |                     |                              |
|-----------------------------|---------------------|------------------------------|
| Tyre / wheel type:          | <b>summer tires</b> | <b>original aluminum</b>     |
| 1st axis - Left / states .  | <b>Michelin</b>     | <b>225/40/R18/92Y 6.6 mm</b> |
| 1st axis - right / states . | <b>Michelin</b>     | <b>225/40/R18/92Y 6.6 mm</b> |
| 2nd axis - Left / states .  | <b>Michelin</b>     | <b>225/40/R18/92Y 5.7 mm</b> |
| 2nd axis - right / states . | <b>Michelin</b>     | <b>225/40/R18/92Y 5.7 mm</b> |
| traffic Safety:             | <b>roadworthy</b>   |                              |
| spare wheel:                | -                   |                              |
| state spare wheel:          | -                   |                              |

| Unmounted tires             |                     |                               |
|-----------------------------|---------------------|-------------------------------|
| Tyre / wheel type:          | <b>Winter tires</b> | <b>Steel with wheel cover</b> |
| 1st axis - Left / states .  | <b>Bridgestone</b>  | <b>205/55/R16/91H 4.5 mm</b>  |
| 1st axis - right / states . | <b>Bridgestone</b>  | <b>205/55/R16/91H 4.0 mm</b>  |
| 2nd axis - Left / states .  | <b>Bridgestone</b>  | <b>205/55/R16/91H 4.8 mm</b>  |
| 2nd axis - right / states . | <b>Bridgestone</b>  | <b>205/55/R16/91H 5.3 mm</b>  |
| traffic Safety:             | <b>roadworthy</b>   |                               |

| standard equipment                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                       |                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                           |
|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| <ul style="list-style-type: none"> <li>• Airbag driver / passenger side</li> <li>• Multimedia audio system<br/><i>Freisprecheinrichtung Bluetooth, Opel Connect, Smartphone Schnittstelle (Apple CarPlay &amp; Android Auto)</i></li> <li>• DAB tuner (digital radio reception)</li> <li>• Elektron . Stability Program ( ESP )</li> <li>• Driving assistance system front collision warning</li> <li>• Parking brake electrically</li> <li>• LED Taillights</li> <li>• Body 5-door</li> <li>• Head airbag system</li> <li>• Headlamp leveling automatically</li> <li>• Fog lights LED</li> <li>• Tire repair kit</li> <li>• Split rear seat back ( 402040 )</li> <li>• Headlight LED with cornering light<br/><i>Einschaltautomatik für Fahrlicht, Fahrassistenten-System: Fernlichtassistent, Scheibenwischer mit Regensensor</i></li> <li>• Steel rims 7x16</li> <li>• Socket (12V ) port in center console</li> <li>• Central locking with remote control</li> </ul> | <ul style="list-style-type: none"> <li>• Anti -lock braking system ( ABS )<br/><i>Bremsassistent</i></li> <li>• Mirrors painted black</li> <li>• Electr . Brakeforce Distribution ( EBD)</li> <li>• Driving Assistance System Hill Start Assist ( HSA , Hill Start Assist )</li> <li>• Driver assistance system Lane Keeping Assist</li> <li>• Transmission 6-speed</li> <li>• Isofix admissions for child seat in back seat</li> <li>• Keyless Start</li> <li>• Rear headrests (3- fold)</li> <li>• 1.2 Ltr motor. - 81 kW</li> <li>• Otto Particle Filter (OPF)</li> <li>• Tire Pressure Monitoring System</li> <li>• Low pollutant according to the Euro 6d emissions standard</li> <li>• Side airbags</li> <li>• Start / Stop system</li> <li>• LED daytime running lights</li> </ul> |

| special Features                                                                       |                                                                                   |
|----------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------|
| <ul style="list-style-type: none"> <li>• Fahrassistenten-Paket IntelliDrive</li> </ul> | <ul style="list-style-type: none"> <li>• Heckklappenöffnung elektrisch</li> </ul> |

- Metallic-/Mineraleffekt-Lackierung

We remind you that the data provided were taken from the DAT database. No liability can be assumed for the completeness and correctness.

#### General examination

|                             |                                                                                                                                   |
|-----------------------------|-----------------------------------------------------------------------------------------------------------------------------------|
| <b>Subfloor Inspection:</b> | <b>not possible</b><br>A visit to the underside of your vehicle could not be performed.<br>Hoist or lifting means not available . |
| <b>Mileage plausible:</b>   | <b>yes</b><br>yes                                                                                                                 |
| <b>reference:</b>           |                                                                                                                                   |
| <b>Note Road Safe:</b>      |                                                                                                                                   |

#### Accident injury assessment

|                                               |                                                                                                                                                                                                                                                                                                       |
|-----------------------------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| <b>Rep. Predamages / -height gross:</b>       | <b>no detectable</b><br>As part of a paint film thickness measuring the body outer skin no previous damage could be detected .                                                                                                                                                                        |
| <b>Layers of paint thickness measurement:</b> | <b>Within the tolerances</b><br>At the vehicle , a resist layer thickness measurement was carried out on the body outer skin. The measured values ??were within the tolerances of original finishes . Evidence that points to a repaired accident damage or repainting carried out , were identified. |
| <b>Existing collision damage:</b>             | <b>Not established</b><br>On the vehicle body shell were on visual examination found no existing accident damages (other than the usual signs of use) .                                                                                                                                               |
| <b>reference:</b>                             |                                                                                                                                                                                                                                                                                                       |

| Overview conducted technology audit |  |                                                                                     |                  |                               |  |
|-------------------------------------|--|-------------------------------------------------------------------------------------|------------------|-------------------------------|--|
| <b>Alternator / Generator:</b>      |  |    | examined limited | <b>Battery / accumulator:</b> |  |
|                                     |  |  | in order         |                               |  |
| <b>oil loss:</b>                    |  |    | in order         |                               |  |
| <b>air conditioning:</b>            |  |    | in order         | <b>lighting system:</b>       |  |
|                                     |  |  | in order         |                               |  |
| <b>coupling:</b>                    |  |    | unavailable      | <b>exhaust System:</b>        |  |
|                                     |  |  | examined limited |                               |  |
| <b>engine running:</b>              |  |    | in order         | <b>shock absorber:</b>        |  |
|                                     |  |  | not checked      |                               |  |
| <b>transmission:</b>                |  |    | examined limited |                               |  |

| Performed testing technology   |                                                                                                                      |
|--------------------------------|----------------------------------------------------------------------------------------------------------------------|
| <b>Alternator / Generator:</b> | The function of the alternator (generator) was tested using the charging indicator light in the instrument cluster . |
| <b>Battery / accumulator:</b>  | The battery (accumulator) was examined during the inspection .                                                       |
| <b>oil loss:</b>               | The vehicle was inspected during the visit to an oil leak .                                                          |
| <b>air conditioning:</b>       | A function of the air conditioning was found to visiting time .                                                      |
| <b>lighting system:</b>        | The lighting system was to tour date in order.                                                                       |
| <b>coupling:</b>               | The vehicle has no clutch , as it is a Autmatikgetriebe or the like.                                                 |
| <b>exhaust System:</b>         | The exhaust system has been tested only restricted during the visit .                                                |
| <b>engine running:</b>         | A field test of the engine was performed.                                                                            |
| <b>shock absorber:</b>         | The shocks were not examined during the inspection .                                                                 |
| <b>transmission:</b>           | The transmission could be examined in the context of limited test drive / pull test .                                |
| <b>reference:</b>              | *Fahrzeug hat Alter und Laufleistungs bedingte Gebrauchsspuren innen und außen.                                      |

damage



|    | component         | Damage               | Rep kind |
|----|-------------------|----------------------|----------|
| 1. | hood              | Chipping from stones | Paint    |
| 2. | Rim front - right | Damaged              | Replace  |
| 3. | Rim front - left  | Damaged              | Replace  |

The expert points out that the vehicle in addition to the age- damage listed in the report and may have a high mileage -related wear , as in normal use are inevitable ( small bumps , dents , scratches) .

There shall be no liability for any defect and / or remained hidden damage in terms of electronics and mechanics accepted ,r\nand for fraudulent misrepresentation and concealed defects .

photographic record



front Left




front Right



rear Left



rear Right



inside



trunk



instrument cluster



mileage



filler cap



rims



rims




rims



rims




engine compartment



service book



Others



Navigation system



tires



tires



tires



tires



tires



1. hood

Chipping from stones



1. hood

Chipping from stones



1. hood

**Chipping from stones**



2. Rim front - right

**Damaged**



2. Rim front - right

**Damaged**



3. Rim front - left

**Damaged**



3. Rim front - left

**Damaged**