



## status report

**customer:** Bank 11, Neuss  
**contract number:** 1169258830  
**reference:**

### vehicle data

#### Opel Corsa F Elegance

|                                         |                                        |                              |                              |
|-----------------------------------------|----------------------------------------|------------------------------|------------------------------|
| Vehicle identification number           | <b>VXKUPHNKKL4023805</b>               | mileage read:                | <b>122641 km</b>             |
| First Registration / construction year: | <b>28.11.2019 / 2019</b>               | Visit Date / place of birth: | <b>02.09.2025 Heidenheim</b> |
| Bodywork:                               | <b>cars</b>                            | Re - import:                 | <b>no</b>                    |
| Body type:                              | <b>limousine</b>                       | KBA no. :                    | <b>1889//ABU</b>             |
| Fuel / emission class:                  | <b>gasoline / € 6</b>                  | transmission type:           | <b>manual transmission</b>   |
| Displacement / power:                   | <b>1199 ccm / 74 kW (101 PS)</b>       | Engine:                      | <b>front-wheel drive</b>     |
| paint:                                  | <b>SchneeWeiss/SummitWhite /Arctic</b> | Number of previous owners:   | <b>Unbekannt</b>             |
| Doors / seats:                          | <b>5 / 5</b>                           | number keys:                 | <b>1</b>                     |
| Next HU / AU:                           | <b>01.2026 / 01.2026</b>               | cushion type:                | <b>substance</b>             |
| Service book available:                 | <b>yes</b>                             | Interior Color:              | <b>black</b>                 |
| smoking vehicle:                        | <b>yes</b>                             | Last service km / on the:    | <b>100706 / 07.07.2023</b>   |
| Vehicle roadworthy:                     | <b>no</b>                              | Vehicle roadworthy:          | <b>no</b>                    |
| Submitted vehicle documents:            | <b>-</b>                               | state outside:               | <b>3 - Average</b>           |
| visit condition:                        | <b>-</b>                               | condition inside:            | <b>3 - Average</b>           |
| state general:                          | <b>3 - Average</b>                     |                              |                              |

### Accessories (presented to the visiting time )

|                                                             |                                                                 |                                                |                                                    |
|-------------------------------------------------------------|-----------------------------------------------------------------|------------------------------------------------|----------------------------------------------------|
| <b>GPS sat nav disk:</b>                                    | <b>Fzg.Schlüssel:</b>                                           | <b>Service book provided / maintained:</b>     | <b>Last service at / on:</b>                       |
| -                                                           | 1                                                               | yes / -                                        | 100706 / 07.07.2023                                |
| <input checked="" type="checkbox"/> AHK key                 | <input checked="" type="checkbox"/> AHK removable               | <input checked="" type="checkbox"/> AHK fixed  | <input checked="" type="checkbox"/> AHK swivel     |
| <input checked="" type="checkbox"/> Fernbed . entertainment | <input checked="" type="checkbox"/> Fernbed . Auxiliary heating | <input checked="" type="checkbox"/> headphone  | <input checked="" type="checkbox"/> LED headlights |
| <input checked="" type="checkbox"/> Load compartment cover  | <input checked="" type="checkbox"/> navigation system           | <input checked="" type="checkbox"/> Persenning | <input checked="" type="checkbox"/> partition net  |
| <input checked="" type="checkbox"/> Wind Deflector          | <input checked="" type="checkbox"/> Xenon headlights            |                                                |                                                    |

☒ **available**

☒ **not available**

Hüsges GmbH  
Gießerallee 23  
47877 Willich  
Tel.: 02154 / 9534 0  
E-Mail: gutachten@huesges-group.eu

The status report was created impartially and to the best of my knowledge. The images listed in the status report are part of the vehicle description regarding the equipment and the vehicle condition.



Hüsges Gruppe®  
**Die Gutachter**



#### mounted tires

|                             |                         |                            |
|-----------------------------|-------------------------|----------------------------|
| Tyre / wheel type:          | <b>All season tires</b> | <b>original aluminum</b>   |
| 1st axis - Left / states .  | <b>Barum</b>            | <b>195/55/R16/87H 4 mm</b> |
| 1st axis - right / states . | <b>Barum</b>            | <b>195/55/R16/87H 4 mm</b> |
| 2nd axis - Left / states .  | <b>Barum</b>            | <b>195/55/R16/87H 4 mm</b> |
| 2nd axis - right / states . | <b>Barum</b>            | <b>195/55/R16/87H 4 mm</b> |
| traffic Safety:             | <b>not roadworthy</b>   |                            |
| spare wheel:                | <b>RunFlatTire</b>      |                            |
| state spare wheel:          | <b>Gebraucht</b>        |                            |

#### standard equipment

- |                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                          |                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                              |
|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| <ul style="list-style-type: none"> <li>• 6 speakers</li> <li>• Anti -lock braking system ( ABS )</li> <li>• B-pillars black high gloss (outside)</li> <li>• Brake Assist ( HBA)</li> <li>• Driving Assistance System Hill Start Assist ( HSA , Hill Start Assist )</li> <li>• Driver assistance system Lane Keeping Assist</li> <li>• Color display (7 inches)</li> <li>• Window regulator front electr. with pinch protection</li> <li>• Speed control system (tempomat) including speed limiter system<br/><i>Geschwindigkeits-Regelanlage (Tempomat)</i></li> <li>• rear window wiper</li> <li>• Isofix seats for child seat on front passenger seat</li> <li>• Body 5-door</li> <li>• Head airbag system</li> <li>• Steering column ( steering wheel ) adjustable</li> <li>•</li> <li>• 1.2 Ltr motor. - 74 kW</li> <li>• Rear fog light</li> <li>• Tire repair kit</li> <li>• Low pollutant according to the Euro 6d emissions standard</li> <li>• Side airbags</li> <li>• Seat cover / upholstery fabric / leather replica</li> <li>• Bumper body color</li> <li>• Chrome interior door handles</li> <li>• Warning system for seat belt , driver's side</li> </ul> | <ul style="list-style-type: none"> <li>• Airbag driver / passenger side</li> <li>• Multimedia audio system<br/><i>DAB-Tuner (Radioempfang digital)</i></li> <li>• board computer</li> <li>• Elektron . Stability Program Plus ( ESP )</li> <li>• Driver assistance system Fatigue detection sensor</li> <li>• Driver assistance system Traffic sign recognition</li> <li>• Electric windows front + rear</li> <li>• Luggage compartment lighting (LED)</li> <li>• Transmission 6-speed</li> <li>• Interior trim strips silver / black (gray)</li> <li>• Isofix admissions for child seat in back seat</li> <li>• air conditioner</li> <li>• Steering wheel (sport / leather - 3-spoke, flattened below) with multifunction</li> <li>• Front reading lights ( 2 )</li> <li>• Center armrest forward with storage compartment</li> <li>• Fog lights LED</li> <li>• Otto Particle Filter (OPF)</li> <li>• Rear seat divided/foldable (6040)</li> <li>•</li> <li>• <i>Leuchtweitenregelung, Blinkleuchten LED in Außenspiegel integriert, Fahrassistenz-System: Fernlichtassistent, Tagfahrlicht LED</i></li> <li>• Visibility Package<br/><i>Einschaltautomatik für Fahrlicht, Scheibenwischer mit Regensensor, Innenspiegel mit Abblendautomatik</i></li> <li>• Start / Stop system</li> <li>• Exterior body color door handles</li> <li>• Warning system for safety , passenger side</li> <li>• Warning system for rear seat belts</li> </ul> |
|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|

| special Features                                                                                                         |                                                                                                                                                                        |
|--------------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| <ul style="list-style-type: none"> <li>• Parking Assist System, rear</li> <li>• Special varnishing snow-white</li> </ul> | <ul style="list-style-type: none"> <li>• Heated front seats<br/><i>Lenkrad heizbar</i></li> <li>• Sun protection glazing behind darkened ( Solar -Protect )</li> </ul> |

We remind you that the data provided were taken from the DAT database. No liability can be assumed for the completeness and correctness.

| General examination         |                                                                                                                                   |
|-----------------------------|-----------------------------------------------------------------------------------------------------------------------------------|
| <b>Subfloor Inspection:</b> | <b>not possible</b><br>A visit to the underside of your vehicle could not be performed.<br>Hoist or lifting means not available . |
| <b>Mileage plausible:</b>   | <b>not testable</b><br>not testable                                                                                               |
| <b>reference:</b>           |                                                                                                                                   |
| <b>Note Road Safe:</b>      | unfallschaden                                                                                                                     |

#### Farbabweichung Plastikteile

| Accident injury assessment                    |                                                                                                                                                                                                                                                                                                       |
|-----------------------------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| <b>Rep. Predamages / -height gross:</b>       | <b>no detectable</b><br>As part of a paint film thickness measuring the body outer skin no previous damage could be detected .                                                                                                                                                                        |
| <b>Layers of paint thickness measurement:</b> | <b>Within the tolerances</b><br>At the vehicle , a resist layer thickness measurement was carried out on the body outer skin. The measured values ??were within the tolerances of original finishes . Evidence that points to a repaired accident damage or repainting carried out , were identified. |
| <b>Existing collision damage:</b>             | <b>found</b><br>At the unrepaired vehicle accident damage were observed on visual examination on the body skin .                                                                                                                                                                                      |
| <b>reference:</b>                             | Fahrzeug mit bestehenden Unfallschaden, zur Schadensermittlung wurden keine Demontearbeiten durchgeführt, verborgen gebliebene Schäden können nicht ausgeschlossen werden. Unfallschaden Kosten wurden überschlägig Kalkuliert, Kostenerweiterung möglich.                                            |

| Overview conducted technology audit |  |                                                                                     |                  |                               |  |
|-------------------------------------|--|-------------------------------------------------------------------------------------|------------------|-------------------------------|--|
| <b>Alternator / Generator:</b>      |  |    | not checked      | <b>Battery / accumulator:</b> |  |
|                                     |  |  | Out of order     |                               |  |
| <b>oil loss:</b>                    |  |    | Out of order     |                               |  |
| <b>air conditioning:</b>            |  |    | not checked      | <b>lighting system:</b>       |  |
|                                     |  |  | not checked      |                               |  |
| <b>coupling:</b>                    |  |    | examined limited | <b>exhaust System:</b>        |  |
|                                     |  |  | examined limited |                               |  |
| <b>engine running:</b>              |  |    | Out of order     | <b>shock absorber:</b>        |  |
|                                     |  |  | not checked      |                               |  |
| <b>transmission:</b>                |  |    | examined limited |                               |  |

| Performed testing technology   |                                                                                                                           |
|--------------------------------|---------------------------------------------------------------------------------------------------------------------------|
| <b>Alternator / Generator:</b> | The function of the alternator (generator) was not tested.<br>*Riemen ist abgesprungen                                    |
| <b>Battery / accumulator:</b>  | The battery (accumulator) was discharged for visiting time .<br>**Battery deep discharge.                                 |
| <b>oil loss:</b>               | The vehicle was inspected during the visit to an oil leak .<br>*Antriebsriemen für Lichtmaschine abgesprungen<br>**motor. |
| <b>air conditioning:</b>       | The air conditioning was not tested during the visit .                                                                    |
| <b>lighting system:</b>        | The lighting system has not been tested visiting time .                                                                   |
| <b>coupling:</b>               | The clutch could be tested only limited within the test drive / pull test .                                               |
| <b>exhaust System:</b>         | The exhaust system has been tested only restricted during the visit .                                                     |
| <b>engine running:</b>         | A field test of the engine had to acoustic or visual defects for visiting time .<br>**Engine warning light.               |
| <b>shock absorber:</b>         | The shocks were not examined during the inspection .                                                                      |
| <b>transmission:</b>           | The transmission could be examined in the context of limited test drive / pull test .<br>*Im Stand schaltbar              |
| <b>reference:</b>              | *Fahrzeug hat Alter und Laufleistungs bedingte Gebrauchsspuren innen und außen.                                           |

damage



|    | <b>component</b>           | <b>Damage</b> | <b>Rep kind</b>             |
|----|----------------------------|---------------|-----------------------------|
| 1. | Rear bumper                | Breakage      | Replace                     |
| 2. | Cargo cover                | Missing       | Replace                     |
| 3. | Luftführung                | Breakage      | Replace                     |
| 4. | Rillenriemen Lichtmaschine | Not okay      | Carry out a fault diagnosis |
| 5. | tire front - right         | Damaged       | Replace                     |
| 6. | key                        | Missing       | Replace                     |
| 7. | maintenance                | Due           | Replace                     |
| 8. | battery                    | Empty battery | Replace                     |

The expert points out that the vehicle in addition to age to the damage listed in the report and may have a high mileage -related wear , as in normal use are inevitable ( small bumps , dents , scratches) and thus is not entitled to change or reduction .

There shall be no liability for any defect and / or remained hidden damage in terms of electronics and mechanics accepted ,r\nand for fraudulent misrepresentation and concealed defects .



photographic record



front Left



front Right



rear Left



rear Right



inside



inside






trunk



instrument cluster



mileage



filler cap



rims



rims





rims



rims



engine compartment



service book



Others



Navigation system





1. Rear bumper



1. Rear bumper



1. Rear bumper



2. Cargo cover



2. Cargo cover



3. Luftführung





3. Luftführung



3. Luftführung



4. Rillenriemen Lichtmaschine



4. Rillenriemen Lichtmaschine



4. Rillenriemen Lichtmaschine



4. Rillenriemen Lichtmaschine





5. tire front - right



5. tire front - right