


Vehicle details

VIN	VXKUPHNKK L4270497	Brand	OPEL	Maintenance date	-
Licence Plate	J5-35-NF	Model	CORSA 1.2 TURBO ELEGANCE 74KW ACTI ELEGANCE APL 5d	Maintenance mileage	-
Registration date	14/09/2020	Year	2020	Exterior Color	Red Metallic
Odometer	66 736 km	Engine size	1199	interior Color	Black
Fuel	Petrol	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Manual	CO2	-
Doors	5	Gears	6		

Inspection Details

Inspection date	16/09/2025	Inspection loc.	Ayvens Veghel
-----------------	------------	-----------------	---------------



Generic equipment

Manual air-conditioning	✓
Cruise control	✓
GPS system	✓
Alloy wheel rims	✓
Metallic paint	✓
Central locking	✓
Electric windows	✓
Mixed upholstery	✓
Park Distance Control	✓
Audio System	✓
Led lighting	✓

Removable element

Spare wheel (wheel & tyre)	✓
Rear parcel shelf	✓


Technical Document

User manual	✓
Warranty booklet	✓
Key	✓
Remote key	✓
Sat Nav CD ROM Software	✓

Tyres

Continental 195/55/16 Summer 4.5 mm		Continental 195/55/16 Summer 4.5 mm	
Continental 195/55/16 Summer 5.5 mm		Continental 195/55/16 Summer 4.0 mm	

Exterior

2		Part Position Damages Severity Repair mode	Wing Back left Scratched Length (cm) > 10 Repair	3		Part Position Damages Severity Repair mode	Wing Back right Dent & Chips Diameter (mm) > 20 Repair
4		Part Position Damages Severity Repair mode	Door Back right Scratched Length (cm) > 10 Repair	5		Part Position Damages Severity Repair mode	Alloy wheel 16" Front right Scratched - Lumpsum repair
6		Part Position Damages Severity Repair mode	Wing Front right Dent & Chips Diameter (mm) > 20 Repair	7		Part Position Damages Severity Repair mode	Bumper Front right Scratched Length (cm) > 10 Repair
9		Part Position Damages Severity Repair mode	Door Front right Dent & Chips Diameter (mm) > 20 Repair	10		Part Position Damages Severity Repair mode	Roof - Chemical deposit - Lumpsum repair

Interior damage

1		Part Position Damages Severity Repair mode	Interior cleaning Front left Stained/dirty - Cleaning
---	---	--	---

Others



8



●

●

●

●

●

Part	Damage appraisal
Position	Front
Damages	Stone impact
Severity	-
Repair mode	For info