


Vehicle details

VIN	VXKUPHNKK L4406324	Brand	OPEL	Maintenance date	01/01/1900
Licence Plate	J7-31-XR	Model	CORSA 1.2 TURBO ELEGANCE 74KW ACTI ELEGANCE APL 5d	Maintenance mileage	-
Registration date	05/11/2020	Year	2020	Exterior Color	Grey Metallic
Odometer	43 123 km	Engine size	1199	interior Color	Grey
Fuel	Petrol	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Manual	CO2	-
Doors	5	Gears	6		

Inspection Details

Inspection date	12/11/2025	Inspection loc.	Dekra Ayvens
-----------------	------------	-----------------	--------------



Generic equipment

Manual air-conditioning	✓
Cruise control	✓
Alloy wheel rims	✓
Metallic paint	✓
Central locking	✓
Electric windows	✓
Mixed upholstery	✓
Park Distance Control	✓
Audio System	✓
Led lighting	✓


Removable element

Spare wheel (wheel & tyre)	✓
Rear parcel shelf	✓

Technical Document

User manual	✓
Warranty booklet	✓
Spare key	✓
Key	✓

Tyres



Exterior

1		<table border="1"> <tr><td>Part</td><td>Wing</td></tr> <tr><td>Position</td><td>Front right</td></tr> <tr><td>Damages</td><td>Dented</td></tr> <tr><td>Severity</td><td>Diameter (mm) > 20</td></tr> <tr><td>Repair mode</td><td>Smart Repair</td></tr> </table>	Part	Wing	Position	Front right	Damages	Dented	Severity	Diameter (mm) > 20	Repair mode	Smart Repair	2		<table border="1"> <tr><td>Part</td><td>Bonnet</td></tr> <tr><td>Position</td><td>-</td></tr> <tr><td>Damages</td><td>Scratched</td></tr> <tr><td>Severity</td><td>Length (cm) > 10</td></tr> <tr><td>Repair mode</td><td>Repair</td></tr> </table>	Part	Bonnet	Position	-	Damages	Scratched	Severity	Length (cm) > 10	Repair mode	Repair
Part	Wing																								
Position	Front right																								
Damages	Dented																								
Severity	Diameter (mm) > 20																								
Repair mode	Smart Repair																								
Part	Bonnet																								
Position	-																								
Damages	Scratched																								
Severity	Length (cm) > 10																								
Repair mode	Repair																								
3		<table border="1"> <tr><td>Part</td><td>Door</td></tr> <tr><td>Position</td><td>Back right</td></tr> <tr><td>Damages</td><td>Scratched</td></tr> <tr><td>Severity</td><td>Length (cm) > 10</td></tr> <tr><td>Repair mode</td><td>Repair</td></tr> </table>	Part	Door	Position	Back right	Damages	Scratched	Severity	Length (cm) > 10	Repair mode	Repair	4		<table border="1"> <tr><td>Part</td><td>Door</td></tr> <tr><td>Position</td><td>Back left</td></tr> <tr><td>Damages</td><td>Dent & Chips</td></tr> <tr><td>Severity</td><td>Diameter (mm) > 20</td></tr> <tr><td>Repair mode</td><td>Repair</td></tr> </table>	Part	Door	Position	Back left	Damages	Dent & Chips	Severity	Diameter (mm) > 20	Repair mode	Repair
Part	Door																								
Position	Back right																								
Damages	Scratched																								
Severity	Length (cm) > 10																								
Repair mode	Repair																								
Part	Door																								
Position	Back left																								
Damages	Dent & Chips																								
Severity	Diameter (mm) > 20																								
Repair mode	Repair																								
5		<table border="1"> <tr><td>Part</td><td>Bumper</td></tr> <tr><td>Position</td><td>Back</td></tr> <tr><td>Damages</td><td>Broken</td></tr> <tr><td>Severity</td><td>-</td></tr> <tr><td>Repair mode</td><td>Replace</td></tr> </table>	Part	Bumper	Position	Back	Damages	Broken	Severity	-	Repair mode	Replace	6		<table border="1"> <tr><td>Part</td><td>Wing</td></tr> <tr><td>Position</td><td>Back right</td></tr> <tr><td>Damages</td><td>Scratched</td></tr> <tr><td>Severity</td><td>Length (cm) > 10</td></tr> <tr><td>Repair mode</td><td>Repair</td></tr> </table>	Part	Wing	Position	Back right	Damages	Scratched	Severity	Length (cm) > 10	Repair mode	Repair
Part	Bumper																								
Position	Back																								
Damages	Broken																								
Severity	-																								
Repair mode	Replace																								
Part	Wing																								
Position	Back right																								
Damages	Scratched																								
Severity	Length (cm) > 10																								
Repair mode	Repair																								

Comments

Opslagpark : Dekra Ayvens