

OPEL Astra Astra 1.7 CDTI Caravan DPF



VIN NO W0L0AHL3592054104 Registration Number 3592054104

MOT Date

Number of Owners

P2

Odometer Reading

₩-

2

223980 km

Last Service

Last Service Mileage

First Registration Date

Country First Registered

2017-06-10

119202

2009-01-14

Number of Keys

=-

Inspection Report Summary

Customer	BCA Online	Report Number	P20250922104042
Inspection Date / Place	2025-09-22 / Dello Lübeck	Cosmetic Grade	4

Vehicle Summary

Vehicle Condition	Runner	VAT Type	Margin
Fuel Type	Diesel	Road Worthy	Yes
Colour	Silver	Engine Size (cc)	1686
Engine Size	1.7	No of Doors	5
Body Type	Stationwagon / Estate	Drive Train	Front
Seat Colour		No of Seats	5
Seat Covering Name	Schwarz, grau	Seat Covering	Cloth
Charging Cables		NEDC CO2 Rating (q/km)	149
Gearbox Type	Manual		

Vehicle History & Documents

Service Book Available	Present	Next Service Mileage	km
Previous Usage		Imported	No
Manufacturer Warrenty			









































Equipment


Trip Computer	Anti-lock braking	Cruise control	Front fog lamps
Remote adjusting wing mirrors	Roof rails	Split folding rear seats	Xenon headlamps
Leather steering wheel	Rain sensitive windscreen wipers	Airbag Status	Auxiliary Socket
Diesel particulate filter	Headlamp wash/wipe	Remote central locking	Satellite navigation
Stability control	CD Player	Radio	

Equipment Details


Wheels & Tyres

Left Rear Tyre Depth	6	Right Rear Tyre Depth	6
Left Front Tyre Depth	5	Right Front Tyre Depth	5

Cosmetic Damage



	Component	Damage	Comments
1	Seat / Front Left	Interior / Holed	
2	Hood	Bodywork / Dent / Deformation	
3	Mirror / Front Right	Paint / Scratch / Scuff	
4	Bumper / Front	Paint / Scratch / Scuff	
5	Bumper / Front	Missing Part	
6	Fender / Back Left	Bodywork / Dent / Deformation	
7	Bumper / Back	Paint / Scratch / Scuff	
8	Tailgate	Paint / Corrosion	
9	Bumper / Back	Paint / Scratch / Scuff	
10	Back Light / Right	Paint / Chemical Damage	



1. Seat / Front Left Interior / Holed -

2. Hood Bodywork / Dent / Deformation -



3. Mirror / Front Right Paint / Scratch / Scuff -

4. Bumper / Front Paint / Scratch / Scuff -



5. Bumper / Front Missing Part -

6. Fender / Back Left Bodywork / Dent / Deformation -



7. Bumper / Back Paint / Scratch / Scuff -

8. Tailgate Paint / Corrosion -



9. Bumper / Back Paint / Scratch / Scuff -

10. Back Light / Right Paint / Chemical Damage -

Mechanical Condition

Control Lights			
Display Defect	•	Service Light	
ABS Warning Light	⊘	ESP Fault/Traction Control Malfunction Light	•
Diesel Particulate Filter Light	•	Airbag Warning Light	•
Oil Pressure Warning Light	⊘	Brake Warning Light	Ø
Power Steering Warning Light	•	Alternator / Battery	⊘
No Dashboard Lights	•		
Equipments Test			
Central Locking	•	Main & Spare Keys Functioning	
Electric Windows	•	Navigation System	•
Audio Equipment	⊘	AC / Heating System	
Other Equipments	•		
Engine			
Engine Status / EML	•	Engine Leak Visible	•
Engine Starts	⊘		
Levels			
Brakes Fluid	•	Coolant Fluid	•

Test Drive Inspection

description.

Steering Wheel Steering | Noise / Anomaly **Engine** The Gears Scratch / Skip / **Engine Noise Abnormal Operation Fume Quantity Power Loss** Clutch **Clutch Functioning Brake Brake System Anomaly** General **Test Driven Status** No troubles detected, good condition or correct tests, according to vehicle age and mileage Damages or malfunction detected that requires repairs by the buyer NA Not applicable ■ Not tested Disclaimer Please also note the "UserGuide condition report", which shows the scope of the vehicle

User Guide