


Vehicle details

VIN	W0L0SDL68 D4020151	Brand	OPEL	Maintenance date	-
Licence Plate	KV-19-49	Model	Corsa 1.3 CDTi ecoFLEX	Maintenance mileage	-
Registration date	13/11/2012	Year	2012	Exterior Color	Grey Metallic
Odometer	115 357 km	Engine size	1248	interior Color	Grey
Fuel	Diesel	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Manual	CO2	-
Doors	5	Gears	5		

Inspection Details

Inspection date	23/05/2025	Inspection loc.	Dekra Ayvens
-----------------	------------	-----------------	--------------



Generic equipment

Manual air-conditioning	✓
GPS system	✓
Metallic paint	✓
Central locking	✓
Electric windows	✓
Mixed upholstery	✓
Audio System	✓

Removable element


Spare wheel (wheel & tyre)	✓
Rear parcel shelf	✓

Technical Document

Spare key	✗
User manual	✓
Warranty booklet	✓
Remote key	✓
Sat Nav CD ROM Software	✓

Tyres

Winter kit



Exterior

3



Door

PositionFront left

DamagesDented

SeverityDiameter (mm) > 20

Repair modeSmart Repair

5



Wing

PositionBack right

DamagesDented

SeverityDiameter (mm) > 20

Repair modeSmart Repair

7



Bumper

PositionFront

DamagesScratched

SeverityLength (cm) > 10

Repair modeRepair

9



Roof


Position-

DamagesChemical deposit

Severity-

Repair modeLumpsum repair

11



Exterior door mirror shell

PositionFront right

DamagesScratched

SeverityLength (cm) > 10

Repair modeRepair

13



Rear side window trim

PositionBack left

DamagesScratched

SeverityLength (cm) > 10

Repair modeRepair

4



Door

PositionBack left

DamagesScratched

SeverityLength (cm) > 10

Repair modeRepair

6



Door

PositionFront right

DamagesDented

SeverityDiameter (mm) > 20

Repair modeSmart Repair

8



Bonnet

Position-

DamagesChemical deposit

Severity-

Repair modeLumpsum repair

10



Door


PositionBack right

DamagesDent & Chips

SeverityDiameter (mm) > 20

Repair modeRepair

12



Exterior door handles

PositionFront right

DamagesScratched

SeverityLength (cm) > 10

Repair modeRepair

Interior damage

1



Part	Spare key
Position	-
Damages	Missing
Severity	-
Repair mode	Replace

2



Part	Fabric seat
Position	Front left
Damages	Stained/dirty
Severity	-
Repair mode	Cleaning