

OPEL Corsa Corsa 1.3 CDTI DPF ecoFLEX Start-Stop



VIN NO W0L0SDL68D4039889 Registration Number 68D4039889

MOT Date

Last Service

2024-11-22

₩-

Number of Owners

Last Service Mileage

2

183060

Number of Keys

₽ 2
First Registration Date

= 2012-11-14

Odometer Reading

188409 km

Country First Registered

Inspection Report Summary

Customer	BCA Online	Report Number	P20250919105938
Inspection Date / Place	2025-09-19 / ARS Altmann AG Riedstadt	Cosmetic Grade	4

Vehicle Summary

Vehicle Condition	Runner	VAT Type	Margin
Fuel Type	Diesel	,	
Fuel Type	Diesei	Road Worthy	Yes
Colour	Silver	Engine Size (cc)	1248
Engine Size	1.2	No of Doors	5
Body Type	Sedan	Drive Train	Front
Seat Colour		No of Seats	5
Seat Covering Name	Schwarz	Seat Covering	Cloth/Synthetic Leather
Charging Cables		NEDC CO2 Rating (q/km)	95
Gearbox Type	Manual		

Vehicle History & Documents

Service Book Available	Full Service History	Next Service Mileage	km
Previous Usage		Imported	No
Manufacturer Warrenty			






































Equipment

Right Rear Tyre Depth

Trip Computer	Alloys wheels	Auxiliary Socket	Diesel particulate filter
Remote adjusting wing mirrors	Stability control	Central locking	Radio
Airbag Status	Anti-lock braking	Cruise control	Front fog lamps
Remote central locking	CD Player	Leather steering wheel	
Equipment Details			
Equipment Details Air Conditioning	Yes	Alloy Wheel Size	15
	Yes	Alloy Wheel Size	15

Left Rear Tyre Depth

Cosmetic Damage



	Component	Damage	Comments
1	Hood	Bodywork / Dent / Dent	
2	Bumper / Front	Paint / Scratch / Scuff	
3	Seat / Front Left	Interior / Ripped	
4	Door / Back Left	Paint / Scratch / Scuff	
5	Side Panel / Back Left	Paint / Scratch / Scuff	
6	Bumper / Back	Paint / Scratch / Scuff	
7	Bumper / Back	Paint / Scratch / Scuff	
8	Luggage Space Cover / Back	Interior / Missing	
9	Door / Back Right	Paint / Scratch / Scuff	
10	Pillar / Back Right	Paint / Scratch / Scuff	
11	Door / Front Right	Bodywork / Dent / Deformation	
12	Fender / Front Right	Bodywork / Dent / Deformation	


To Mill / Front Might Out of Body Work / Octation	13	Rim / Front Right	Out of Bodywork /	/ Scratch
---	----	-------------------	-------------------	-----------

14 Windshield / Front Glass Break / Impact



1. Hood Bodywork / Dent / Dent -

2. Bumper / Front Paint / Scratch / Scuff -



3. Seat / Front Left Interior / Ripped -

4. Door / Back Left Paint / Scratch / Scuff -



5. Side Panel / Back Left Paint / Scratch / Scuff -

6. Bumper / Back Paint / Scratch / Scuff -



7. Bumper / Back Paint / Scratch / Scuff -

8. Luggage Space Cover / Back Interior / Missing -




9. Door / Back Right Paint / Scratch / Scuff -

10. Pillar / Back Right Paint / Scratch / Scuff -



11. Door / Front Right Bodywork / Dent / Deformation -

12. Fender / Front Right Bodywork / Dent / Deformation -



13. Rim / Front Right Out of Bodywork / Scratch -

14. Windshield / Front Glass Break / Impact -

Mechanical Condition

Control Lights			
Display Defect	⊘	Service Light	•
ABS Warning Light	•	ESP Fault/Traction Control Malfunction Light	•
Diesel Particulate Filter Light	•	Airbag Warning Light	•
Oil Pressure Warning Light	⊘	Brake Warning Light	•
Power Steering Warning Light	•	Alternator / Battery	•
No Dashboard Lights	•		
Equipments Test			
Central Locking	•	Main & Spare Keys Functioning	•
Electric Windows	•	Audio Equipment	•
AC / Heating System	⊘		
Engine			
Engine Status / EML	•	Engine Leak Visible	•
Engine Starts	⊘		
Gearbox			
Gear Box	•		
Levels			
Brakes Fluid	⊘	Coolant Fluid	•

Test Drive Inspection

description.

