



OPEL Astra

Astra 1.6 Caravan

VIN NO W0L0TGF3542221871
Registration Number 3542221871



MOT Date

2025-11-01

Last Service



Number of Owners

5

Last Service Mileage



Number of Keys

2

First Registration Date

2004-08-30

Odometer Reading

244490 km

Country First Registered

Germany

Inspection Report Summary


Customer	BCA Online	Report Number	P20250716122707
Inspection Date / Place	2025-07-16 / BCA Oberndorf	Cosmetic Grade	9

Vehicle Summary

Vehicle Condition	Runner	VAT Type	Margin
Fuel Type	Petrol	Road Worthy	No
Colour	Silver	Engine Size (cc)	1598
Engine Size	1.6	No of Doors	5
Body Type	Stationwagon / Estate	Drive Train	Front
Seat Colour		No of Seats	5
Seat Covering Name	Schwarz/muster	Seat Covering	Cloth
Charging Cables		NEDC CO2 Rating (q/km)	182
Gearbox Type	Automatic		

Vehicle History & Documents

Service Book Available	Present Unrecorded	Next Service Mileage	km
Previous Usage		Imported	No
Manufacturer Warrenty			







Equipment

Tow ball	Alloys wheels	Front fog lamps	Roof rails
CD Player	Radio	Airbag Status	Anti-lock braking
Remote central locking	Split folding rear seats	Central locking	


Equipment Details

Tow Ball Type	Detachable	Air Conditioning	Yes
Alloy Wheel Size	15	Seat Heating	No

Wheels & Tyres

Right Front Tyre Depth	5	Left Front Tyre Depth	5
Right Rear Tyre Depth	5	Left Rear Tyre Depth	5

Cosmetic Damage



Component		Damage	Comments
1	Bumper / Front	Paint / Scratch / Scuff	
2	Fender / Front Left	Paint / Corrosion	
3	Roof	Paint / Scratch / Scuff	
4	Side Panel / Back Left	Paint / Corrosion	
5	Seat / Front Left	Interior / Ripped	
6	Bumper / Back	Bodywork / Dent / Dent	
7	Tailgate	Paint / Corrosion	
8	Side Panel / Back Right	Paint / Corrosion	
9	Fender / Front Right	Paint / Scratch / Line	
10	Roof Upholstery	Interior / Loose	



1. Bumper / Front
Paint / Scratch / Scuff -




2. Fender / Front Left
Paint / Corrosion -



3. Roof
Paint / Scratch / Scuff -



4. Side Panel / Back Left
Paint / Corrosion -



5. Seat / Front Left
Interior / Ripped -




6. Bumper / Back
Bodywork / Dent / Dent -



7. Tailgate
Paint / Corrosion -



8. Side Panel / Back Right
Paint / Corrosion -



9. Fender / Front Right
Paint / Scratch / Line -



10. Roof Upholstery
Interior / Loose -

Mechanical Condition

Control Lights

Display Defect	✓	Service Light	✓
ABS Warning Light	✓	Airbag Warning Light	✓
Oil Pressure Warning Light	✓	Brake Warning Light	✓
Power Steering Warning Light	✓	Alternator / Battery	✓
No Dashboard Lights	✓		

Equipments Test

Central Locking	✓	Main & Spare Keys Functioning	✓
Electric Windows	✓	Audio Equipment	✓
AC / Heating System	✓	Other Equipments	✓

Engine

Engine Status / EML	✓	Engine Leak Visible	⚠
Engine Starts	✓		

Gearbox

Gear Box	✓
----------	---

Levels

Brakes Fluid	✓	Coolant Fluid	⚠
--------------	---	---------------	---

Test Drive Inspection

Steering Wheel			
Steering Noise / Anomaly		✓	
Engine			
Engine Noise	✓	The Gears Scratch / Skip / Abnormal Operation	✓
Fume Quantity	!	Power Loss	✓
Clutch			
Clutch Functioning		✓	
Brake			
Brake System Anomaly		✓	
General			
Test Driven Status		Not Performed	
✓ No troubles detected, good condition or correct tests, according to vehicle age and mileage			
! Damages or malfunction detected that requires repairs by the buyer			
NA Not applicable			
= Not tested			

Disclaimer

Please also note the "UserGuide condition report", which shows the scope of the vehicle description. [User Guide](#)