



OPEL CORSA

Corsa 1.4 90 ch Edition

VIN NO W0L0XEP68G4115474
Registration Number DZ832BG



MOT Date



Last Service



Number of Owners



Last Service Mileage



Number of Keys



First Registration Date



Odometer Reading



Country First Registered



Inspection Report Summary

| | | | |
|-------------------------|-------------------------|----------------|-----------------|
| Customer | BCAuto Encheres | Report Number | P20251013142604 |
| Inspection Date / Place | 2025-10-13 / BCA GARONS | Cosmetic Grade | 3 |

Vehicle Summary

| | | | |
|-------------------|---------------|------------------------|-------------|
| Vehicle Condition | Non-Runner | VAT Type | Exempt Rate |
| Fuel Type | Petrol | Gearbox Type | Manual |
| Colour | Light Grey | Engine Size (cc) | 1398 |
| Engine Size | 1.4 | No of Doors | 5 |
| Family | Passenger Car | Drive Train | Front |
| Seat Colour | | No of Seats | 5 |
| Charging Cables | | NEDC CO2 Rating (q/km) | 120 |
| Engine Rating CV | | Metalic Colour | Yes |
| Accident Damage | No | Euro Emission | |

Vehicle History & Documents

| | | | |
|------------------------|------------|----------------------|----|
| Service Book Available | Present | Next Service Mileage | km |
| Previous Usage | Normal Use | Imported | No |
| Manufacturer Warrenty | | | |





Equipment

Central locking

Stability control

Power assisted steering

Radio

Cruise control

Equipment Details

Seat Heating


No

Air Conditioning


Yes

Cosmetic Damage

11 Dommages



2 Dommages



| Component | | Damage | Comments |
|-----------|----------------------------|-------------------------------|----------|
| 1 | Shield / Front | Paint / Scratch / Line | |
| 2 | Shield / Back | Bodywork / Dent / Deformation | |
| 3 | Tailgate | Bodywork / Dent / Deformation | |
| 4 | Shield / Back | Bodywork / Dent / Deformation | |
| 5 | Luggage Space Cover / Back | Interior / Broken | |
| 6 | Back Light / Right | Glass Break | |
| 7 | Fender / Front Right | Bodywork / Dent / Deformation | |
| 8 | Fender / Back Left | Bodywork / Dent / Deformation | |
| 9 | Hubcap / Front Left | Out of Bodywork / Breakage | |
| 10 | Shield / Front | Bodywork / Assembly | |
| 11 | Door / Back Left | Paint / Scratch / Line | |
| 12 | Hubcap / Back Right | Out of Bodywork / Breakage | |

13 HandBrake Handle

Interior / Ripped



1. Shield / Front
Paint / Scratch / Line -




2. Shield / Back
Bodywork / Dent / Deformation -



3. Tailgate
Bodywork / Dent / Deformation -



4. Shield / Back
Bodywork / Dent / Deformation -



5. Luggage Space Cover / Back
Interior / Broken -



6. Back Light / Right
Glass Break -



7. Fender / Front Right
Bodywork / Dent / Deformation -



8. Fender / Back Left
Bodywork / Dent / Deformation -



9. Hubcap / Front Left
Out of Bodywork / Breakage -



10. Shield / Front
Bodywork / Assembly -



11. Door / Back Left
Paint / Scratch / Line -



12. Hubcap / Back Right
Out of Bodywork / Breakage -



13. HandBrake Handle
Interior / Ripped -

Mechanical Condition

Tyres

Presence Anti-Theft Lock Nut 

 *No troubles detected, good condition or correct tests, according to vehicle age and mileage*

 *Damages or malfunction detected that requires repairs by the buyer*

 *Not applicable*

 *Not tested*

Disclaimer Section

The test drive is done on a flat surface and lasts about 2 minutes. The driven distance is a minimum of 300 meters, including a u-turn, an acceleration and a braking phase. The highest speed achieved during this test is 50km/h. The mechanical check is a visual and dynamic diagnosis without any disassembly. We cannot guarantee any mechanical wear part.