



status report

customer: BCA Autoauktionen GmbH
contract number: 4002799981
reference:

vehicle data

Opel Insignia A Sports Tourer Innovation

Vehicle identification number	W0LGT8E10G1073166	mileage read:	156321 km
First Registration / construction year:	30.03.2016 / 2016	Visit Date / place of birth:	08.09.2025 Dahlwitz-Hoppegarten
Bodywork:	cars	Re - import:	unknown
Body type:	hatchback	KBA no. :	0035//BEL
Fuel / emission class:	diesel / € 6	transmission type:	automatic
Displacement / power:	1956 ccm / 125 kW (170 PS)	Engine:	front-wheel drive
paint:	Karbonschw GraphitSchw Midnigh	Number of previous owners:	4
Doors / seats:	5 / 5	number keys:	2
Next HU / AU:	- / -	cushion type:	substance
Service book available:	no	Interior Color:	black
smoking vehicle:	yes	Last service km / on the:	- / -
Vehicle roadworthy:	yes	Vehicle roadworthy:	yes
Submitted vehicle documents:	Eg II (veh - letter)	state outside:	3 - Average
visit condition:	-	condition inside:	3 - Average
state general:	3 - Average		

Accessories (presented to the visiting time)

GPS sat nav disk:	Fzg.Schlüssel:	Service book provided /	Last service at / on:
-	2	maintained:	- / -
		no / -	
☒ Fernbed . Auxiliary heating	☒ partition net	☒ Wind Deflector	☒ AHK fixed
☒ AHK removable	☒ AHK swivel	☒ AHK key	☒ Fernbed . entertainment
☒ headphone	☒ Load compartment cover	☒ LED headlights	☒ navigation system
☒ Persenning	☒ Xenon headlights		

☒ **available**

☒ **not available**

Hüsges GmbH
Gießerallee 23
47877 Willich
Tel.: 02154 / 9534 0
E-Mail: gutachten@huesges-group.eu

The status report was created impartially and to the best of my knowledge. The images listed in the status report are part of the vehicle description regarding the equipment and the vehicle condition.



Hüsges Gruppe®
Die Gutachter



mounted tires		
Tyre / wheel type:	All season tires	aluminum
1st axis - Left / states .	Anderer	245/45/R18/100W 5 mm
1st axis - right / states .	Anderer	245/45/R18/100W 5 mm
2nd axis - Left / states .	Anderer	245/45/R18/100W 6 mm
2nd axis - right / states .	Anderer	245/45/R18/100W 6 mm
traffic Safety:	roadworthy	
spare wheel:	-	
state spare wheel:	-	

standard equipment	
• Airbag switched off • Active front headrests • Drive Front Wheel Drive • Audio controls on steering wheel • Mirrors and electric folding . adjustable and heated • Bi -Xenon headlights with adaptive light distribution (AFL) <i>Leuchtweitenregelung automatisch, Fahrassistentz-System: Fernlichtassistent, Aktives Kurvenlicht (AFL), Scheinwerfer-Reinigungsanlage (SRA)</i> • Brake Assist (HBA) • Roof rails (silver) • Rev counter • Elektron . Stability Program (ESP) • Electric windows front + rear • Luggage cover / shade extendable • Automatic transmission - with Active Select (6 stages) • rear window wiper • Isofix admissions for child seat in back seat • 2-zone automatic climate control • Bumper protection (chrome / stainless steel) • Steering column (steering wheel) adjustable • Front reading lights (2) • Front center armrest • Engine 2.0 ltr. - 125 kW 16V CDTI • Smokers Package • RuÅpartikelfilter • Low emissions Euro 6 emission standards • Hydraulic power steering • Seat cover / upholstery fabric / leather replica	• Airbag driver / passenger side • Anti -lock braking system (ABS) • Audio navigation system Navi 900 Europa Touch <i>Feststellbremse elektrisch, Fahrassistentz-System: Berganfahr-Assistent (HSA, Hill Start Assist)</i> • exit lights • Body color door mirrors • board computer • Check Control System • double tone • Sill plates (aluminum) • Elektron . traction control • Window trim Stainless Steel / Chrome • Cruise control system (cruise control) • cup holders • Interior decor strips wood kibo • Body 5-door • Head airbag system • Steering wheel (leather) • Reading lights in the rear • Rear center armrest • model refinement • OnStar SOS Service • Tire Pressure Monitoring System • Rear seat split / folding • Side airbags • Visibility Package <i>Einschaltautomatik für Fahrlicht, Scheinwerfer-Reinigungsanlage (SRA), Scheibenwischer mit Regensensor, Innenspiegel mit Abblendautomatik</i> • Sun visors with mirrors (illuminated)

• Bumper body color • Chrome interior door handles • Wärmeschutzverglasung	• LED daytime running lights • immobilizer • Central locking with remote control
--	--

special Features	
• CD drive • Interior package <i>Mittelarmlehne hinten, Kopfstützen hinten (3-fach)</i> • heated steering wheel • Fog Lights • Premium seat front left <i>Sitz-Komfort-Paket 1, Sitz vorn links elektr. höhenverstellbar, Lendenwirbelstütze Sitz vorn links, elektr. verstellbar, Mittelarmlehne hinten</i> • Rear View Camera <i>Fahrassistenz-System: Querverkehrs-Assistent Heck (Rückfahr-Assistent), Fahrassistenz-System: Totwinkel-Assistent, Fahrassistenz-System: Spurhalteassistent</i> • Heated front seats • socket 230V • Sun protection glazing behind darkened (Solar -Protect)	• Tailgate with automatic opening and closing system • LM rims 8x18 (5 - twin-spoke , rotor design) • Metallic / mineral effect spraying • Parking Assist System • Spare wheel as Notrad • Seat Comfort Package 2 <i>Sitz-Komfort-Paket 1, Sitz vorn links elektr. höhenverstellbar, Lendenwirbelstütze Sitz vorn links, elektr. verstellbar, Sitz vorn rechts elektr. höhenverstellbar, Lendenwirbelstütze Sitz vorn rechts, elektr. verstellbar</i> • Socket (12V) port in the trunk / cargo area • Provision safety net behind front seats

We remind you that the data provided were taken from the DAT database. No liability can be assumed for the completeness and correctness.

General examination	
Subfloor Inspection:	Conducted limited To investigate the vehicle (ä . Lift o .) Were not lifting means even a ramp or pit available. For this reason, a visit to the vehicle's underside was limited.
Mileage plausible:	not testable not testable
reference:	
Note Road Safe:	

Farbabweichung Plastikteile

Accident injury assessment	
Rep. Predamages / -height gross:	no detectable As part of a paint film thickness measuring the body outer skin no previous damage

	could be detected .
Layers of paint thickness measurement:	Within the tolerances At the vehicle , a resist layer thickness measurement was carried out on the body outer skin. The measured values ??were within the tolerances of original finishes . Evidence that points to a repaired accident damage or repainting carried out , were identified.
Existing collision damage:	- -
reference:	

Overview conducted technology audit					
Alternator / Generator:		examined limited	Battery / accumulator:		examined limited
oil loss:		examined limited			
air conditioning:		Out of order	lighting system:		examined limited
coupling:		unavailable	exhaust System:		examined limited
engine running:		examined limited	shock absorber:		examined limited
transmission:		examined limited			

Performed testing technology	
Alternator / Generator:	The function of the alternator (generator) was tested using the charging indicator light in the instrument cluster .
Battery / accumulator:	The battery (accumulator) could be considered limited during the visit .
oil loss:	The vehicle could be checked only limited to oil leaks .
air conditioning:	The air conditioning was not okay for visiting time . **No cooling effect. Further diagnostic required.
lighting system:	The Lichtanlage could be considered limited to the tour date .
coupling:	The vehicle has no clutch , as it is a Autmatikgetriebe or the like.
exhaust System:	The exhaust system has been tested only restricted during the visit .
engine running:	Checking the engine running was limited. Here no audible or visual abnormalities were noted .
shock absorber:	The shock absorber could be tested only restricted during the visit .
transmission:	The transmission could be examined in the context of limited test drive / pull test .
reference:	*Marderspuren im Motorraum; Oberflächenkratzer/Kratzer rundum

damage



component	Damage	Rep kind
1.	Missing	Replace
2. maintenance	Missing	Replace
3. proof of maintenance	Missing	Replace
4. Schaltknauf	Damaged	Replace
5. Key with remote control	Wear and tear	acceptable
6. motor insulation	Damaged	Replace
7. Rear bumper	Wear and tear	acceptable
8. tailgate	Wear and tear	acceptable
9. Sidewall - Rear - right	Scratch(es)	Smart repair
10.	Wear and tear	acceptable
11. roof		Paint
12.	Scratch(es)	Paint
13.	Wear and tear	acceptable
14. Front bumper	Wear and tear	acceptable
15.	Wear and tear	acceptable
16. side skirt - left	Deformed	Refurbish and paint
17. Rear door - left	Damaged	Refurbish and paint
18.	Scratch(es)	Paint
19. headlining	Damaged	Smart repair
20. air conditioning	Not okay	Carry out a fault diagnosis

The expert points out that the vehicle in addition to age to the damage listed in the report and may have a high mileage -related wear , as in normal use are inevitable (small bumps , dents , scratches) and thus is not entitled to change or reduction .

There shall be no liability for any defect and / or remained hidden damage in terms of electronics and mechanics accepted , and for fraudulent misrepresentation and concealed defects .


photographic record




front Left



front Right



rear Left



rear Right



inside



inside



trunk



instrument cluster



mileage



filler cap



rims



rims




rims



rims



engine compartment




service book



Others




Navigation system



4. Schaltknäuf



5. Key with remote control



6. motor insulation



7. Rear bumper



7. Rear bumper



8. tailgate



9. Sidewall - Rear - right



10.



11. roof



12.



13.



14. Front bumper



15.



16. side skirt - left



17. Rear door - left



18.



19. headlining