

OPEL Astra Astra 1.3 CDTI DPF ecoFLEX Sports TourerStart/Stop



VIN NO W0LPD8EA5C8017786
Registration Number A5C8017786

MOT Date

★ 2024-12-01

Last Service

#-

Number of Owners

3

Last Service Mileage

2 -

Number of Keys

22

First Registration Date

2011-11-18

Odometer Reading

164554 km

Country First Registered

=-

Inspection Report Summary

Customer	BCA Online	Report Number	P20250903105854
Inspection Date / Place	2025-09-03 / Dello Bremen	Cosmetic Grade	5

Vehicle Summary

Vehicle Condition	Runner	VAT Type	Margin
Fuel Type	Diesel	Road Worthy	Yes
Colour	Silver	Engine Size (cc)	1248
Engine Size	1.2	No of Doors	5
Body Type	Stationwagon / Estate	Drive Train	Front
Seat Colour		No of Seats	5
Seat Covering Name	Schwarz	Seat Covering	Cloth
Charging Cables		NEDC CO2 Rating (q/km)	109
Gearbox Type	Manual		

Vehicle History & Documents

Service Book Available	Missing	Next Service Mileage	km
Previous Usage		Imported	No
Manufacturer Warrenty			



































Equipment

Trip Computer	Cruise control	Front fog lamps	Remote central locking
Stability control	Leather steering wheel	Anti-lock braking	Diesel particulate filter
Remote adjusting wing mirrors	Roof rails	CD Player	Radio


Equipment Details

Air Conditioning Yes	
----------------------	--

Wheels & Tyres

Right Front Tyre Depth	1	Left Front Tyre Depth	1
Right Rear Tyre Depth	2	Left Rear Tyre Depth	2

Cosmetic Damage



13	Door / Front Right	Paint / Poor Previous Repair
14	Fender / Front Right	Bodywork / Dent / Dent
15	Door / Back Left	Paint / Poor Previous Repair
16	Door / Front Left	Paint / Poor Previous Repair
17	Panel Filling / Front Left	Interior / Worn - out
18	Other	Bodywork / Dent / Dent



1. Roof Paint / Chipping -

2. Hood Paint / Scratch / Scuff -




3. Door / Front Left Bodywork / Dent / Dent -

4. Fender / Back Left Bodywork / Dent / Dent -



5. Bumper / Back Bodywork / Breakage -

6. Tailgate Bodywork / Dent / Dent -



7. Fender / Back Right Bodywork / Dent / Dent -

8. Door / Back Right Bodywork / Dent / Dent -



9. Rocker Panel / Center Right Bodywork / Dent / Dent -

10. Door / Front Right Bodywork / Dent / Dent -



11. Door / Front Right Bodywork / Dent / Dent -

12. Door / Back Right Paint / Poor Previous Repair -



13. Door / Front Right
Paint / Poor Previous Repair -

14. Fender / Front Right Bodywork / Dent / Dent -



15. Door / Back Left Paint / Poor Previous Repair -

16. Door / Front Left Paint / Poor Previous Repair -



17. Panel Filling / Front Left Interior / Worn - out -

Bodywork / Dent / Dent -

Mechanical Condition

Control Lights			
Control Lights			
Display Defect	•	Service Light	⊘
ABS Warning Light	•	ESP Fault/Traction Control Malfunction Light	•
Diesel Particulate Filter Light	•	Airbag Warning Light	⊘
Oil Pressure Warning Light	⊘	Brake Warning Light	②
Power Steering Warning Light	•	Alternator / Battery	•
No Dashboard Lights	•		
Equipments Test			
Central Locking	•	Main & Spare Keys Functioning	•
Electric Windows	⊘	Audio Equipment	⊘
AC / Heating System	⊘	Other Equipments	•
Engine			
Engine Status / EML	⊘	Engine Leak Visible	
Engine Starts	•		
Gearbox			
Gear Box	⊘		
Levels			
Brakes Fluid	•	Coolant Fluid	⊘

Test Drive Inspection

description.

Steering Wheel Steering | Noise / Anomaly **Engine** The Gears Scratch / Skip / **Engine Noise Abnormal Operation Fume Quantity Power Loss** Clutch **Clutch Functioning Brake Brake System Anomaly** General **Test Driven Status** NA No troubles detected, good condition or correct tests, according to vehicle age and mileage Damages or malfunction detected that requires repairs by the buyer NA Not applicable ■ Not tested Disclaimer Please also note the "UserGuide condition report", which shows the scope of the vehicle

User Guide