

OPEL Astra Astra 2.0 CDTI DPF Sports Tourer



VIN NO W0LPD8EN6D8020376 Registration Number N6D8020376

MOT Date

★ 2025-12-01

Last Service

Number of Owners

3

Last Service Mileage

? -

Number of Keys

22

First Registration Date

2012-11-27

Odometer Reading

210289 km

Country First Registered

Germany

Inspection Report Summary

| Customer | BCA Online | Report Number | P20250908120120 |
|-------------------------|--|----------------|-----------------|
| Inspection Date / Place | 2025-09-08 / SULOJA Mönchengladbach | Cosmetic Grade | 5 |

Vehicle Summary

| Vehicle Condition | Runner | VAT Type | Margin |
|--------------------|-----------------------|------------------------|--------|
| Fuel Type | Diesel | Road Worthy | Yes |
| Colour | Brown | Engine Size (cc) | 1956 |
| Engine Size | 2.0 | No of Doors | 5 |
| Body Type | Stationwagon / Estate | Drive Train | Front |
| Seat Colour | | No of Seats | 5 |
| Seat Covering Name | | Seat Covering | Cloth |
| Charging Cables | | NEDC CO2 Rating (q/km) | 129 |
| Gearbox Type | Manual | | |

Vehicle History & Documents

| Service Book Available - | Next Service Mileage | km |
|--------------------------|----------------------|----|
| Previous Usage | Imported | No |
| Manufacturer Warrenty | | |




































Equipment

| Tinted Glass | Airbag Status | Anti-lock braking | Bluetooth telephone interface |
|---------------------------|-------------------------------|------------------------|-------------------------------|
| Diesel particulate filter | Remote adjusting wing mirrors | Roof rails | Central locking |
| Radio | Tow ball | Alloys wheels | Auxiliary Socket |
| Cruise control | Front fog lamps | Remote central locking | Stability control |
| Leather steering wheel | Rear parking sensors | | |


Equipment Details

| Tow Ball Type | Detachable | Air Conditioning | Yes |
|------------------|------------|------------------|-----|
| Alloy Wheel Size | 17 | | |

Wheels & Tyres

| Right Front Tyre Depth | 5 | Left Front Tyre Depth | 5 |
|------------------------|---|-----------------------|---|
| Right Rear Tyre Depth | 5 | Left Rear Tyre Depth | 5 |

Cosmetic Damage



| | Component | Damage | Comments |
|----|-----------------------------|----------------------------|----------|
| 1 | Corner Bumper / Front Right | Bodywork / Breakage / Hole | |
| 2 | Hood | Bodywork / Dent / Dent | |
| 3 | Door / Back Left | Paint / Scratch / Scuff | |
| 4 | Side Panel / Back Left | Paint / Scratch / Scuff | |
| 5 | Tailgate | Bodywork / Dent / Dent | |
| 6 | Bumper / Back | Paint / Scratch / Scuff | |
| 7 | Roof | Bodywork / Dent / Dent | |
| 8 | Side Panel / Back Right | Bodywork / Breakage / Hole | |
| 9 | Door / Front Right | Paint / Scratch / Scuff | |
| 10 | Fender / Front Right | Bodywork / Dent / Dent | |
| 11 | Panel Filling / Front Left | Interior / Scratched | |



1. Corner Bumper / Front Right Bodywork / Breakage / Hole -

2. Hood Bodywork / Dent / Dent -



3. Door / Back Left Paint / Scratch / Scuff -

4. Side Panel / Back Left Paint / Scratch / Scuff -



5. Tailgate Bodywork / Dent / Dent -

6. Bumper / Back Paint / Scratch / Scuff -



7. Roof Bodywork / Dent / Dent -

8. Side Panel / Back Right Bodywork / Breakage / Hole -



9. Door / Front Right Paint / Scratch / Scuff -



11. Panel Filling / Front Left Interior / Scratched -

10. Fender / Front Right Bodywork / Dent / Dent -

Mechanical Condition

| Control Lights | | | |
|----------------------------------|------------|---|----------|
| ABS Warning Light | • | ESP Fault/Traction Control Malfunction Light | ⊘ |
| Diesel Particulate Filter Light | • | Airbag Warning Light | • |
| Oil Pressure Warning Light | ⊘ | Brake Warning Light | ⊘ |
| Power Steering Warning Light | • | Alternator / Battery | • |
| No Dashboard Lights | • | Display Defect | • |
| Service Light | (1) | | |
| Engine | | | |
| Engine Status / EML | • | Engine Leak Visible | • |
| Engine Starts | • | | |
| Gearbox | | | |
| Gear Box | • | | |
| Equipments Test | | | |
| AC / Heating System | • | Central Locking | • |
| Main & Spare Keys Functioning | • | Electric Windows | • |
| Audio Equipment | • | Parking Sensors / Cameras Functioning | • |
| Other Equipments | ⊘ | | |
| Levels | | | |
| Brakes Fluid | • | Coolant Fluid | ⊘ |

Test Drive Inspection

description.

Steering Wheel Steering | Noise / Anomaly **Engine** The Gears Scratch / Skip / **Engine Noise Abnormal Operation Fume Quantity Power Loss Brake Brake System Anomaly** Clutch **Clutch Functioning** General Not Performed **Test Driven Status** No troubles detected, good condition or correct tests, according to vehicle age and mileage Damages or malfunction detected that requires repairs by the buyer NA Not applicable ■ Not tested Disclaimer Please also note the "UserGuide condition report", which shows the scope of the vehicle

User Guide