



OPEL Zafira

Zafira Tourer 1.4 Turbo

VIN NO W0LPD9EC4G1117352
Registration Number C4G1117352



MOT Date	Number of Owners	Number of Keys	Odometer Reading
-	2	2	111337 km
Last Service	Last Service Mileage	First Registration Date	Country First Registered
2024-05-21	104202	2016-06-14	-

Inspection Report Summary


Customer	BCA Online	Report Number	P20250526103313
Inspection Date / Place	2025-05-26 / Dürkop Goslar	Cosmetic Grade	2

Vehicle Summary




Vehicle Condition	Runner	VAT Type	Margin
Fuel Type	Petrol	Road Worthy	Yes
Colour	Black	Engine Size (cc)	1364
Engine Size	1.4	No of Doors	5
Body Type	Stationwagon / Estate	Drive Train	Front
Seat Colour		No of Seats	5
Seat Covering Name	Schwarz	Seat Covering	Cloth
Charging Cables		NEDC CO2 Rating (q/km)	150
Gearbox Type	Manual		

Vehicle History & Documents

Service Book Available	Present	Next Service Mileage	km
Previous Usage		Imported	No
Manufacturer Warrenty			







Equipment

Trip Computer	Airbag Status	Anti-lock braking	Bluetooth telephone interface
Front fog lamps	Remote adjusting wing mirrors	Reversing Camera	Satellite navigation
CD Player	Radio	Rear parking sensors	USB Socket
Alloys wheels	Auxiliary Socket	Cruise control	Front parking sensors
Remote central locking	Roof rails	Stability control	Leather steering wheel
Rain sensitive windscreen wipers			

Equipment Details


Air Conditioning	Dual Zone Climate Control	Alloy Wheel Size	17
Seat Heating	Front		

Wheels & Tyres


Right Front Tyre Depth	6	Left Front Tyre Depth	6
Right Rear Tyre Depth	6	Left Rear Tyre Depth	6

Cosmetic Damage

3 Schäden




1 Schäden



Component	Damage	Comments
1 Roof	Bodywork / Dent / Dent	
2 Door / Front Right	Paint / Scratch / Scuff	
3 Luggage Space Cover / Back	Interior / Missing	
4 Rocker Panel / Center Left	Bodywork / Dent / Dent	



1. Roof
Bodywork / Dent / Dent -



2. Door / Front Right
Paint / Scratch / Scuff -



3. Luggage Space Cover / Back
Interior / Missing -



4. Rocker Panel / Center Left
Bodywork / Dent / Dent -

Mechanical Condition

Control Lights

Display Defect	✓	Service Light	!
ABS Warning Light	✓	ESP Fault/Traction Control Malfunction Light	✓
Airbag Warning Light	✓	Oil Pressure Warning Light	✓
Brake Warning Light	✓	Power Steering Warning Light	✓
Alternator / Battery	✓	No Dashboard Lights	✓
Tire Pressure Monitoring System	✓		

Equipments Test

Central Locking	✓	Main & Spare Keys Functioning	✓
Electric Windows	✓	Navigation System	✓
Audio Equipment	✓	Parking Sensors / Cameras Functioning	✓
AC / Heating System	✓	Other Equipments	✓

Engine

Engine Status / EML	✓	Engine Leak Visible	✓
Engine Starts	✓		

Gearbox

Gear Box	✓
----------	---

Levels

Brakes Fluid	✓	Coolant Fluid	✓
--------------	---	---------------	---

Test Drive Inspection

Steering Wheel			
Steering Noise / Anomaly		✓	
Engine			
Engine Noise	✓	The Gears Scratch / Skip / Abnormal Operation	✓
Fume Quantity	✓	Power Loss	✓
Clutch			
Clutch Functioning		✓	
Brake			
Brake System Anomaly		✓	
General			
Test Driven Status		NA	
✓ No troubles detected, good condition or correct tests, according to vehicle age and mileage			
! Damages or malfunction detected that requires repairs by the buyer			
NA Not applicable			
☐ Not tested			

Disclaimer

Please also note the "UserGuide condition report", which shows the scope of the vehicle description.

[User Guide](#)