



Expertise

Protocol number: 41861043
Order number / reference: 25287105
Inspection date: 2 Oct 2025

Manufacturer: Opel	Model: Astra 1.5 D Start/Stop Sports Tourer Edition
VIN: W0VBD8EV3M8024743	



Vehicle details	
Manufacturer / Type / Model / Equipment	
Opel Astra 1.5 D Start/Stop Sports Tourer Edition	
Vehicle Identification number	W0VBD8EV3M8024743
Mileage (Read)	98,109 km
First registration	27 Aug 2021
Number of holders	1
Next periodical technical inspection	01/2027
(Report not on hand)	
Power / Engine displacement	90 kw / 1,496 ccm
Fuel type / Cylinder	Diesel / 3
Gearbox / Number of gears	Manual / 6
Type of drive	Front drive
Type of vehicle	Station wagon
Colour / colour code	Argonsilber Metallic
Doors / Seats	5 / 5
Upholstery type	Cloth
Colour of upholstery	Black-Anthracite



Vehicle details

Maintenance booklet / proof	digital proof / complete	Next maintenance in	27 %
Last maintenance on / at	05/2024 at 85,710 km		
Key is / should be	2 / 2	FZG documents	ZB#2 (B) was available (copy), ZB#1 (S) was not available
		Letter No.	GA247947
Previous damage / Accident	None detectable	Repainting	None detectable
Inspection conditions	conditional: light/moisture/dirt	Lifting equipment / pit	No
Test drive	Not possible	Engine function test	Not possible
Manufacturer key number/ type code number	1844 / ALL 00233		
Emission standard	EURO6;WLTP;AP;PI/CI; M, N1 I	Fine dust sticker	
Permitted total weight	1,945 kg	Empty weight	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	205/55 R16 94H	Winter tyres on Light alloy	Dunlop	5mm / 5mm
2)	205/55 R16 91H	Winter tyres on Light alloy	Goodyear	5mm / 5mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	205/55 R16 91V	Summer tyres on Steel rim with wheel cover	Continental	3mm / 3mm
2)	205/55 R16 91V	Summer tyres on Steel rim with wheel cover	Continental	4mm / 4mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 12/2025		

Legend: Tread depth information for tires on the left is in the first place, for tires on the right is in the second place on the axle in the direction of travel



Equipment

Standard equipment

- 2 ignition keys
- Airbag for driver and passenger side
- Airbag: Head airbags 1st and 2nd row of seats outside
- Anti-lock braking system (ABS)
- Exterior mirrors for driver and passenger side electrically adjustable and heated
- Brake light, third
- Roof rails black
- Diesel particulate filter (DPF)
- Electronic Stability Program Plus (ESP Plus)
- Speed controller with limiter
- Back window, heater
- Interior lighting, front and rear
- Air conditioning
- trunk lighting
- Front headrests
- LED daytime running lights
- Steering column, height and length adjustable
- Sliding center armrest, front
- Pedals: Disengaging safety pedals
- Quickheat rapid heating system
- Radio: Multimedia radio with 7" touchscreen color display
- Tire pressure monitoring system
- Rear seat backrest folds forward in a 60:40 ratio
- Seat belts: Three-point seat belts on all seats
- Visual equipment
- Start/Stop system
- Traction Control (TC) Plus
- Immobiliser
- Central locking with radio remote control and interior switches
- Storage compartments
- Airbag: Chest-pelvis side airbag for driver and front passenger side
- Automatic activation of the hazard warning lights
- Hill Start Assist
- On-board computer
- Roof design line, above in black
- Decorative strips Antelao Sand/Polar Silver
- tachometer
- Electric windows front and rear
- Transmission: 6-speed manual transmission
- Rear window wiper
- Instruments, black, with high-gloss chrome rings, 3.5" driver information display
- Headrests (3) rear
- Load compartment cover
- Steering wheel: leather steering wheel
- Lighting equipment
- Parking pilot, rear parking aid
- Upholstery: Cloth
- Radio: Digital radio reception DAB/DAB+/DMB-R
- Tire repair kit
- Wheels: Designer wheels, 6.5 J x 16 with tires 205/55 R16
- Power steering
- Safety net for luggage compartment
- Seats: Comfort seats, front
- 12V socket in the center console
- Pre-installation for ISOFIX child seat restraint system
- Heat-insulating glazing, green tinted and windshield

Extra equipment

- Paint finish: metallic
- Radio: Multimedia Navigation (Multimedia Radio, 7" color touchscreen display with USB port, hands-free system, voice control, Bluetooth audio streaming, smartphone integration via Apple CarPlay and Android Auto, navigation system with integrated memory, road maps for over 30 European countries, 2D and 3D map display, dynamic route guidance via map and/or arrow display and announcement, dynamic route guidance via the extended Traffic Message Channel (TMCpro))



Brief expert findings

Documents submitted	At the time of the inspection, the registration certificate Part 2 (letter) was available, but the registration certificate Part 1 (certificate) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was verified during the inspection by the undersigned.
Inspection	A proper visual inspection of the paintwork and bodywork was only possible to a limited extent due to insufficient lighting conditions/wetness or dirt. No lifting equipment or pit was available for examining the vehicle. Therefore, inspection of the vehicle's underside was only possible to a limited extent.
Test drive	The conduction of a test drive with the described vehicle was impossible to do under the given conditions.
Engine function test	An engine test run could not be performed. This is due to the following reason: Motorschaden

Value reducing factors

No.	Component group	Description
1	Trim / covers	Floor mats - Holes - Replace
2	Interior	Interior - Soiled - Clean
3	Roof	Roof (Korrosion) - Stone chips - Smart repair
4	Side panel - rear right side	Side panel - Scratched - Smart repair
5	Door - rear left side	Door - Scratched - Smart repair
6	Door - rear right side	Door - Scratched - Smart repair
7	Body	Body - Glued / labelled - De-glue / neutralise
8	Instrument panel	Centre console - front - Scratched - Replace
9	Braking system	Brake discs and pads - rear (Tragbild mangelhaft) - Corrosion - Replace
10	Braking system	Brake discs and brake pads - front (Tragbild mangelhaft) - Corrosion - Replace
11	Front bumper	Front bumper (Steinschlag) - Scratched - Repair and paint
12	Vehicle glazing	Windscreen (Rissbildung) - Stone chips - Replace
13	Bonnet	Bonnet (Korrosion) - Stone chips - Repair and paint
14	Engine	Engine - Non-operational - Replace

Wear and tear

No.	Component group	Description
1	Trim / covers	Boot lid - interior trim - Scratched - No deduction
2	Rear bumper	Rear bumper - Scratched - No deduction
3	Headlight	Headlight - left side - Stone chips - No deduction
4	Headlight	Headlight - right side - Stone chips - No deduction
5	Body	Body (Flugrost) - Soiled - No deduction
6	Interior	Interior - Scratch(es) - No deduction
7	Body	Body (oberflächlich) - Scratch(es) - No deduction
8	Side panel - rear right side	Sill - Scratched - No deduction
9	Door - front left side	Door (Kratzer) - Stone chips - No deduction

The vehicle shows signs of wear commensurate with its age and use.



Order/Scope of order

The order was placed to prepare a sales report for the vehicle described. This includes the following:

- Description of core relevant information about the vehicle
- Documentation of equipment features
(Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of previous damage, unrepaired previous damage, repainting
- a brief visual or functional inspection of the equipment details if possible.
(Functional tests of driver assistance systems are not included in the scope of services!)
- a photo documentation of the vehicle

Basis for the order

This product is based on the Alphabet Fuhrpark GmbH guidelines for vehicle returns and valuations. The expert makes the explicit findings in each individual case objectively within the framework of the specified standards based on his or her own expertise.

The vehicle inspection takes place in a disassembled state.

Damage or defects that can only be detected during disassembly/diagnosis work or through advanced knowledge remain within the scope of the prognosis risk. An extended risk exists for concealed defects caused by fraudulent deception and not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted according to the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which in their nature and severity slightly exceed normal use but do not constitute unacceptable damage will be documented and identified under signs of use if necessary.

Damage or defects that can no longer be attributed to normal use or wear and tear according to the underlying standard are listed in the product under value-reducing factors.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

Apparently, no repaired previous damage could be found on the vehicle.

Comments

Unterbodenbesichtigung nicht möglich-Mehrkosten können entstehen.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view ([Online link](#))



Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres



Figure 13: Documents



Figure 14: Additional tyres




Figure 15: Navigation



Figure 16: Misc.



Figure 17: Misc.



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.




Figure 24: Misc.




Figure 25: Misc.




Figure 26: Misc.



Figure 27: Misc.




Figure 28: Misc.




Figure 29: Misc.



Figure 30: Misc.




Figure 31: Misc.



Figure 32: Misc.




Figure 33: Misc.



Figure 34: Misc.



Figure 35: Misc.




Figure 36: Misc.



Figure 37: Misc.



Figure 38: Misc.



Figure 39: Misc.



Damage 1: Trim / covers: Floor mats - Holes - Replace



Damage 1: Trim / covers: Floor mats - Holes - Replace



Damage 2: Interior: Interior - Soiled - Clean



Damage 2: Interior: Interior - Soiled - Clean



Damage 2: Interior: Interior - Soiled - Clean




Damage 3: Roof: Roof (Korrosion) - Stone chips - Smart repair



Damage 3: Roof: Roof (Korrosion) - Stone chips - Smart repair



Damage 3: Roof: Roof (Korrosion) - Stone chips - Smart repair



Damage 3: Roof: Roof (Korrosion) - Stone chips - Smart repair



Damage 4: Side panel - rear right side: Side panel - Scratched - Smart repair




Damage 4: Side panel - rear right side: Side panel - Scratched - Smart repair



Damage 4: Side panel - rear right side: Side panel - Scratched - Smart repair




Damage 5: Door - rear left side: Door - Scratched - Smart repair



Damage 5: Door - rear left side: Door - Scratched - Smart repair



Damage 6: Door - rear right side: Door - Scratched - Smart repair



Damage 6: Door - rear right side: Door - Scratched - Smart repair



Damage 7: Body: Body - Glued / labelled - De-glue / neutralise



Damage 7: Body: Body - Glued / labelled - De-glue / neutralise



Damage 7: Body: Body - Glued / labelled - De-glue / neutralise



Damage 7: Body: Body - Glued / labelled - De-glue / neutralise



Damage 7: Body: Body - Glued / labelled - De-glue / neutralise



Damage 7: Body: Body - Glued / labelled - De-glue / neutralise



Damage 7: Body: Body - Glued / labelled - De-glue / neutralise



Damage 7: Body: Body - Glued / labelled - De-glue / neutralise



Damage 7: Body: Body - Glued / labelled - De-glue / neutralise



Damage 7: Body: Body - Glued / labelled - De-glue / neutralise



Damage 8: Instrument panel: Centre console - front - Scratched - Replace



Damage 8: Instrument panel: Centre console - front - Scratched - Replace



Damage 9: Braking system: Brake discs and pads - rear (Tragbild mangelhaft) - Corrosion - Replace



Damage 9: Braking system: Brake discs and pads - rear (Tragbild mangelhaft) - Corrosion - Replace



Damage 9: Braking system: Brake discs and pads - rear (Tragbild mangelhaft) - Corrosion - Replace



Damage 9: Braking system: Brake discs and pads - rear (Tragbild mangelhaft) - Corrosion - Replace



Damage 10: Braking system: Brake discs and brake pads - front (Tragbild mangelhaft) - Corrosion - Replace



Damage 10: Braking system: Brake discs and brake pads - front (Tragbild mangelhaft) - Corrosion - Replace




Damage 11: Front bumper: Front bumper (Steinschlag) - Scratched - Repair and paint




Damage 11: Front bumper: Front bumper (Steinschlag) - Scratched - Repair and paint



Damage 11: Front bumper: Front bumper (Steinschlag) - Scratched - Repair and paint



Damage 11: Front bumper: Front bumper (Steinschlag) - Scratched - Repair and paint



Damage 11: Front bumper: Front bumper (Steinschlag) - Scratched - Repair and paint



Damage 11: Front bumper: Front bumper (Steinschlag) - Scratched - Repair and paint



Damage 12: Vehicle glazing: Windscreen (Rissbildung) - Stone chips - Replace



Damage 12: Vehicle glazing: Windscreen (Rissbildung) - Stone chips - Replace



Damage 12: Vehicle glazing: Windscreen (Rissbildung) - Stone chips - Replace




Damage 13: Bonnet: Bonnet (Korrosion) - Stone chips - Repair and paint



Damage 13: Bonnet: Bonnet (Korrosion) - Stone chips - Repair and paint



Damage 13: Bonnet: Bonnet (Korrosion) - Stone chips - Repair and paint




Damage 13: Bonnet: Bonnet (Korrosion) - Stone chips - Repair and paint



Damage 14: Engine: Engine - Non-operational - Replace



Damage 14: Engine: Engine - Non-operational - Replace



Damage 14: Engine: Engine - Non-operational - Replace



Damage 14: Engine: Engine - Non-operational - Replace



Damage 14: Engine: Engine - Non-operational - Replace



Damage 14: Engine: Engine - Non-operational - Replace



Damage 14: Engine: Engine - Non-operational - Replace



Wear and tear 9: Door - front left side: Door (Kratzer) - Stone chips - No deduction



Wear and tear 9: Door - front left side: Door (Kratzer) - Stone chips - No deduction



Wartungshistorie

(gemäß Auftraggeber Informationen)

Fahrgestellnummer: W0VBD8EV3M8024743
Hersteller / Modell: OPEL OPEL Astra 1.5 D Start/Stop Sports Tourer Edition

Datum	KM-Stand	Beschreibung
09.07.2025	98.108	Kompression prüfen; Reparatur Sonstiges; Systemtest/Eigendiagnose
14.01.2025	87.666	AU
27.12.2024	87.666	Kraftstofffilter ern; Reparatur Sonstiges; Systemtest/Eigendiagnose; Turbolader ern
17.05.2024	85.710	Bremsklötze vorne; Bremsscheiben vorne; Kraftstofffilter ern; Luftfiltereinsatz ern; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges
24.11.2022	39.826	Bremsinspektion vo + hi; Bremse Sonstiges; Bremsklötze hinten; Bremsklötze vorne; Bremsscheiben vorne; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges