

Expertise

Protocol number: 41665924
Order No. / Reference: 25215176
Inspection date: 24 Sept 2025

Vehicle details

Type of vehicle

Manufacturer: Opel

Model: Astra 1.5 D Start/Stop Sports Tourer Business Edition

VIN: W0VBD8EV8N8042303





Manufacturer / Type / Model / Equipment		
Opel Astra 1.5 D Start/Stop Sports Tourer Business Edition		
Vehicle Identification number	W0VBD8EV8N8042303	
Mileage (Read)	36,095 km	
First registration	15 Aug 2022	
Number of holders	1	
Power / Engine displacement	90 kw / 1,496 ccm	
Fuel type / Cylinder	Diesel / 3	
Gearbox / Number of gears	Manual / 6	
Type of drive	Front drive	

Station wagon

Colour / colour code

Doors / Seats

Upholstery type

Colour of upholstery

Argonsilber Metallic

5 / 5

Cloth

Black-Grey

Continental



5mm / 5mm

Vehicle details			
Maintenance booklet / proof	digital proof / complete	Next maintenance in	93 %
Last maintenance on / at	11/2024 at 16,381 km		
Key is / should be	2/2	FZG documents	ZB#2 (B) was available (copy), ZB#1 (S
			was not available
		Letter No.	GJ683714
Previous damage / Accident	None detectable	Repainting	None detectable
Inspection conditions	sufficient	Lifting equipment / pit	yes
Test drive	Not performed	Engine function test	Performed
Manufacturer key number/	1844 / ALL 00259		
type code number			
Emission standard	EURO6;WLTP;AP;PI/CI; M, N1 I	Fine dust sticker	
Permitted total weight	1,945 kg	Empty weight	
Tyres			
Mounted tyres			
# Tyre size	Type of tyre	Manufacture	er Tread depth

2)	205/55 R16 91V	Summer tyres on Light alloy	Continental	5mm / 5mm
Add	litional tyres			

Summer tyres on Light alloy

Tyre size Type of tyre Manufacturer Tread depth
1) 205/55 R16 91H Winter tyres on Light alloy Goodyear 6mm / 6mm
2) 205/55 R16 91H Winter tyres on Light alloy Goodyear 6mm / 6mm

Replacement

205/55 R16 91V

1)

Typ Tyre size Type of tyre Manufacturer Tread depth

Tirefit Expiration date 10/2026

Legend: Tread depth information for tires on the left is in the first place, for tires on the right is in the second place on the axle in the direction of travel



Equipment

Standard equipment

- · 2 ignition keys
- · Airbag for driver and passenger side
- · Airbag: Head airbags 1st and 2nd row of seats outside
- Anti-lock braking system (ABS)
- Exterior mirrors for driver and passenger side electrically adjustable and heated
- · Brake light, third
- · Roof rails black
- Diesel particulate filter (DPF)
- · Electronic Stability Program Plus (ESP Plus)
- · Speed controller with limiter
- · Back window, heater
- · Interior lighting, front and rear
- Air conditioning
- · trunk lighting
- · Front headrests
- · LED headlights
- · Steering column, height and length adjustable
- · Fog light
- · Upholstery: Cloth
- · Radio: Digital radio reception DAB/DAB+/DMB-R
- · Tire pressure monitoring system
- · Power steering
- · Safety net for luggage compartment
- · Start/Stop system
- · Traction Control (TC) Plus
- Immobiliser
- · Central locking with radio remote control and interior switches

- · Storage compartments
- · Airbag: Chest-pelvis side airbag for driver and front passenger side
- · Automatic activation of the hazard warning lights
- · Hill Start Assist
- · On-board computer
- · Roof design line, above in black
- Decorative strips Antelao Sand/Polar Silver
- · tachometer
- · Electric windows front and rear
- Transmission: 6-speed manual transmission
- Rear window wiper
- Instruments, black, with high-gloss chrome rings, 3.5" driver information display
- · Headrests (3) rear
- · Load compartment cover
- · LED daytime running lights
- · Lighting equipment
- · Pedals: Disengaging safety pedals
- · Quickheat rapid heating system
- · Tire repair kit
- Rear seat backrest folds forward in a 60:40 ratio
- · Seat belts: Three-point seat belts on all seats
- Visual equipment
- · 12V socket in the center console
- Pre-installation for ISOFIX child seat retention system
- · Heat-insulating glazing, green tinted and windshield

Extra equipment

- · Paint finish: metallic
- Steering wheel: Heated leather steering wheel and seat heating, multi-stage, driver and front passenger (including footwell heating in the rear)
- Parking pilot, front and rear parking aid (with acoustic warning signal when parking forwards and backwards)
- Seats: Ergonomic active seat (certified by the Campaign for Healthy Backs (AGR) Driver's seat: - Adjustable length, height, and tilt -Lumbar support electropneumatically adjustable in height and length - Extendable thigh support - Pocket on the front seat backs, driver and passenger)
- Light alloy wheels 7 J x 16 in "10-spoke" design (with 205/55 R 16 tires)
- Sliding front center armrest (with storage compartments and cup holder)
- Radio: Multimedia Navigation (Multimedia Radio, 7" color touchscreen display with USB port, hands-free system, voice control, Bluetooth audio streaming, smartphone integration via Apple CarPlay and Android Auto, navigation system with integrated memory, road maps for over 30 European countries, 2D and 3D map display, dynamic route guidance via map and/or arrow display and announcement, dynamic route guidance via the extended Traffic Message Channel (TMCpro))



|--|

Part 1 (certificate) was not. (Copy)

VIN comparison The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted

documents was verified during the inspection by the undersigned.

Inspection The inspection conditions were sufficient for the assessment of the vehicle.

Lifting equipment and a pit were available for examining the vehicle.

Test drive No test drive/maneuvering was carried out during the inspection of the vehicle.

Engine function test An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Door - front left side	Door - dent(s) - Smooth repair work
2	Rear bumper	Rear bumper - Scratch(es) - Smart repair
3	Boot lid / rear door	Boot lid - Scratch(es) - Smart repair

Wear and tear

No.	Component group	Description
1	Vehicle glazing	Windscreen - Stone chips - No deduction
2	Body	Body - Scratch(es) - No deduction
The	vehicle shows signs of wear of	commensurate with its age and use.

Order/Scope of order

The order was placed to prepare a sales report for the vehicle described. This includes the following:

- · Description of core relevant information about the vehicle
- Documentation of equipment features (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- · Documentation of previous damage, unrepaired previous damage, repainting
- a brief visual or functional inspection of the equipment details if possible.
 (Functional tests of driver assistance systems are not included in the scope of services!)
- · a photo documentation of the vehicle

TÜV SÜD Auto Partner GmbH Gutenbergstr. 13 70771 Leinfelden-Echterdingen Inspection location Hartmann Compound Professionals Arnoldschacht 9-11 44894 Bochum



Basis for the order

This product is based on the Alphabet Fuhrpark GmbH guidelines for vehicle returns and valuations. The expert makes the explicit findings in each individual case objectively within the framework of the specified standards based on his or her own expertise.

The vehicle inspection takes place in a disassembled state.

Damage or defects that can only be detected during disassembly/diagnosis work or through advanced knowledge remain within the scope of the prognosis risk. An extended risk exists for concealed defects caused by fraudulent deception and not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted according to the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which in their nature and severity slightly exceed normal use but do not constitute unacceptable damage will be documented and identified under signs of use if necessary.

Damage or defects which, according to the underlying standard, can no longer be attributed to normal use or wear and tear are listed in the product under "Depreciating Factors".

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

Apparently, no repaired previous damage could be found on the vehicle.

Comments

- Winterradsatz ist kein Bestandteil des Auslieferumfangs.





Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear





Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres





Figure 13: Documents




Figure 14: Documents




Figure 15: Documents



Figure 16: Documents



Figure 17: Documents



Figure 18: Additional tyres





Figure 19: Additional tyres



Figure 20: Navigation



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.





Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.



Damage 1: Door - front left side: Door - dent(s) - Smooth repair work



Damage 1: Door - front left side: Door - dent(s) - Smooth repair work





Damage 2: Rear bumper: Rear bumper - Scratch(es) - Smart repair



Damage 2: Rear bumper: Rear bumper - Scratch(es) - Smart repair



Damage 3: Boot lid / rear door: Boot lid - Scratch(es) - Smart repair



Damage 3: Boot lid / rear door: Boot lid - Scratch(es) - Smart repair

Wartungshistorie (gemäß Auftraggeber Informationen)



Fahrgestellnummer: W0VBD8EV8N8042303

OPEL OPEL Astra 1.5 D Start/Stop Sports Tourer Business Edition Hersteller / Modell:

Datum	KM-Stand	Beschreibung
21.11.2024	16.381	Bremsflüssigkeit; Bremsflüssigkeit ern; Kraftstofffilter ern; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges
30.08.2023	7.365	Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges