

OPEL Astra Astra 1.5 D Start/Stop Sports Tourer

BCA

VIN NO W0VBE8EU2L8039107 Registration Number U2L8039107

MOT Date

Number of Owners

Number of Keys

Odometer Reading

₩-

3 1

P2

2 89488 km

Last Service

Last Service Mileage

First Registration Date

Country First Registered

2024-12-03

87705

2020-12-07

Germany

Inspection Report Summary

| Customer | BCA Online | Report Number | P20250924155838 |
|-------------------------|-------------------------|----------------|-----------------|
| Inspection Date / Place | 2025-09-24 / BCA Berlin | Cosmetic Grade | 3 |

Vehicle Summary

| Vehicle Condition | Runner | VAT Type | Qualifying |
|--------------------|-----------------------|------------------------|---------------|
| Fuel Type | Diesel | Road Worthy | Yes |
| Colour | Black | Engine Size (cc) | 1496 |
| Engine Size | 1.5 | No of Doors | 5 |
| Body Type | Stationwagon / Estate | Drive Train | Front |
| Seat Colour | | No of Seats | 5 |
| Seat Covering Name | | Seat Covering | Cloth/Leather |
| Charging Cables | | NEDC CO2 Rating (q/km) | 90 |
| Gearbox Type | Manual | | |

Vehicle History & Documents


| Service Book Available | Present | Next Service Mileage | km |
|------------------------|---------|----------------------|----|
| Previous Usage | | Imported | No |
| Manufacturer Warrenty | | | |






























Equipment

| Tinted Glass | Airbag Status | Anti-lock braking | Cruise control |
|-----------------------------------|-------------------------------|------------------------|----------------------|
| Front parking sensors | Remote adjusting wing mirrors | Satellite navigation | Stability control |
| Electrically folding wing mirrors | Radio | USB Socket | Alloys wheels |
| Bluetooth telephone interface | e Enhanced speaker system | Parking Assistance | Reversing Camera |
| Split folding rear seats | Central locking | Leather steering wheel | Rear parking sensors |


Equipment Details

| Air Conditioning | Climate Control | Alloy Wheel Size | 16 |
|------------------|-----------------|------------------|----|
| Seat Heating | Front | | |

Wheels & Tyres

| Right Front Tyre Depth | 4 | Left Front Tyre Depth | 5 |
|------------------------|---|-----------------------|---|
| Right Rear Tyre Depth | 5 | Left Rear Tyre Depth | 5 |

Cosmetic Damage




| | Component | Damage | Comments |
|----|---------------------------|------------------------------|----------|
| 1 | Hood | Bodywork / Dent / Dent | |
| 2 | Hood | Bodywork / Dent / Dent | |
| 3 | Hood | Bodywork / Dent / Dent | |
| 4 | Hood | Bodywork / Dent / Dent | |
| 5 | Roof | Bodywork / Dent / Dent | |
| 6 | B Pillar / Center Left | Bodywork / Dent / Dent | |
| 7 | Fender / Back Left | Bodywork / Dent / Dent | |
| 8 | Corner Bumper / Back Left | Paint / Scratch / Scuff | |
| 9 | Bumper / Back | Paint / Scratch / Scuff | |
| 10 | Rim / Front Right | Out of Bodywork / Scratch | |
| 11 | Rim / Front Left | Out of Bodywork / Scratch | |
| 12 | Hood | Paint / Poor Previous Repair | |




1. Hood Bodywork / Dent / Dent -

2. Hood Bodywork / Dent / Dent -




3. Hood Bodywork / Dent / Dent -

4. Hood Bodywork / Dent / Dent -



5. Roof Bodywork / Dent / Dent -

6. B Pillar / Center Left Bodywork / Dent / Dent -



7. Fender / Back Left Bodywork / Dent / Dent -

8. Corner Bumper / Back Left Paint / Scratch / Scuff -




9. Bumper / Back Paint / Scratch / Scuff -

10. Rim / Front Right Out of Bodywork / Scratch -



11. Rim / Front Left Out of Bodywork / Scratch -

12. Hood Paint / Poor Previous Repair -



13. Fender / Back Right Paint / Scratch / Scuff -

Mechanical Condition

| Engine | | | |
|----------------------|----------|---|----------|
| Engine Starts | ② | Engine Status / EML | • |
| Engine Leak Visible | • | | |
| Equipments Test | | | |
| Central Locking | • | Audio Equipment | • |
| AC / Heating System | • | Electric Windows | • |
| Navigation System | ⊘ | Parking Sensors / Cameras Functioning | • |
| Control Lights | | | |
| ABS Warning Light | • | ESP Fault/Traction Control Malfunction Light | • |
| Airbag Warning Light | • | Oil Pressure Warning Light | • |
| Brake Warning Light | ⊘ | Power Steering Warning Light | • |
| Alternator / Battery | • | All - wheel Drive | • |
| No Dashboard Lights | • | Display Defect | ⊘ |
| Service Light | • | Tire Pressure Monitoring System | ⊘ |
| Gearbox | | | |
| Gear Box | • | | |
| Levels | | | |
| Coolant Fluid | • | Brakes Fluid | ② |

Test Drive Inspection

description.

| Steering Wheel | | | | |
|---|--------------------------------|--|----------|-------|
| Steering Noise / Anomaly | ⊘ | | | |
| Engine | | | | |
| Engine Noise | • | The Gears Scratch / Skip / Abnormal Operation | ⊘ | |
| Fume Quantity | • | Power Loss | ② | |
| Brake | | | | |
| Brake System Anomaly | ⊘ | | | |
| Clutch | | | | |
| Clutch Functioning | ⊘ | | | |
| General | | | | |
| Test Driven Status | • | | | |
| No troubles detected, good condition or correct tests, according to vehicle age and mileage Damages or malfunction detected that requires repairs by the buyer Not applicable Not tested | | | | |
| Disclaimer | | | | |
| Please also note the "UserG | Guide condition report", which | h shows the scope of the vehicle | Hear (| Cuido |

<u>User Guide</u>