



status report

customer: BCA Autoauktionen GmbH
contract number:
reference:

vehicle data

Opel Combo Life E Innovation

Vehicle identification number	W0VECYHZRKJ772710	mileage read:	135155 km
First Registration / construction year:	18.09.2019 / 2019	Visit Date / place of birth:	16.09.2025 Heidenheim
Bodywork:	pickup	Re - import:	no
Body type:	other	KBA no. :	1844//AHB
Fuel / emission class:	diesel / € 6	transmission type:	automatic
Displacement / power:	1499 ccm / 96 kW (131 PS)	Engine:	front-wheel drive
paint:	Nacht Schwarz/Noir Onyx	Number of previous owners:	2
Doors / seats:	5 / 5	number keys:	2
Next HU / AU:	- / -	cushion type:	substance
Service book available:	no	Interior Color:	black
smoking vehicle:	no	Last service km / on the:	- / -
Vehicle roadworthy:	yes	Vehicle roadworthy:	yes
Submitted vehicle documents:	For example, I (Fzg.Schein)	state outside:	3 - Average
visit condition:	-	condition inside:	3 - Average
state general:	3 - Average		

Accessories (presented to the visiting time)

GPS sat nav disk:	Fzg.Schlüssel:	Service book provided / maintained:	Last service at / on:
-	2	no / -	- / -

☒ AHK key	☒ AHK removable	☒ AHK fixed	☒ AHK swivel
☒ Fernbed . entertainment	☒ Fernbed . Auxiliary heating	☒ headphone	☒ LED headlights
☒ Load compartment cover	☒ navigation system	☒ Persenning	☒ partition net
☒ Wind Deflector	☒ Xenon headlights		

☒ **available** ☒ **not available**

Hüsges GmbH
Gießerallee 23
47877 Willich
Tel.: 02154 / 9534 0
E-Mail: gutachten@huesges-group.eu

The status report was created impartially and to the best of my knowledge. The images listed in the status report are part of the vehicle description regarding the equipment and the vehicle condition.



Hüsges Gruppe®
Die Gutachter



mounted tires

Tyre / wheel type:	Winter tires	steel
1st axis - Left / states .	Anderer	205/60/R16/92H 5 mm
1st axis - right / states .	Anderer	205/60/R16/92H 5 mm
2nd axis - Left / states .	Anderer	205/60/R16/92H 6 mm
2nd axis - right / states .	Anderer	205/60/R16/92H 6 mm
traffic Safety:	roadworthy	
spare wheel:	-	
state spare wheel:	-	

standard equipment

- | | |
|--|---|
| <ul style="list-style-type: none"> • 2nd row of seats, single seats foldable (3 seats) • Anti -lock braking system (ABS) • Electric wing mirror . adjustable and heatable • Body color door mirrors • Roof rails (silver) • Elektron . traction control • Driver assistance system Fatigue detection sensor • Driver assistance system Lane Keeping Assist • Color display (3.5 inches) • Transmission automatic - with start / stop (8-speed) • Body 5-door • Head airbag system • Steering wheel (sport / leather - 3-spoke, flattened below) with multifunction <i>Lenkrad mit Schaltwippen/-tasten</i> • Engine 1,5 Ltr. - 96 kW CDTI DPF • Wheelbase 2785 mm • Rußpartikelfilter • Sliding electrical links with window . actuated • Locking / starting system Keyless Open • Body color side moldings • Seat back folding front right • Bumper body color • Exterior body color door handles • Central locking with remote control | <ul style="list-style-type: none"> • Airbag driver / passenger side • Audio controls on steering wheel • Power side mirrors . adjustable and heated , electric. anklappbar • board computer • Off switch for headlights • Driving Assistance System Hill Start Assist (HSA , Hill Start Assist) • Vehicle assistance system emergency braking assistant • Driver assistance system Traffic sign recognition • • Tailgate with separate opening window, rear wiper system and heated rear window • 2-zone automatic climate control • Lumbar support front left seat • heated steering wheel • Parking Assist System, rear • Tire Pressure Monitoring System • • Sliding right with electric windows . actuated • Side airbags • Visibility Package <i>Nebelscheinwerfer, Abbiegelicht, Fahrassistenz-System: Fernlichtassistent, Scheibenwischer mit Regensensor, Fensterheber elektrisch vorn + hinten, Fahrzeugschlüssel (2) beide klappbar, Innenspiegel mit Abblendautomatik</i> • Start / Stop system • LED daytime running lights • Sun protection glazing behind darkened (Solar -Protect) |
|--|---|



*Außenspiegel elektr. anklappbar, Fensterheber elektrisch vorn
+ hinten, Fensterheber vorn elektr. mit Einklemmschutz*

special Features

- | | |
|---|---|
| <ul style="list-style-type: none"> • Audio navigation system Multimedia Navi Pro
6 Lautsprecher, Freisprecheinrichtung (Bluetooth) mit Sprachsteuerung, USB-Schnittstelle vorn (2-fach) • Panoramic sunroof (glass) • Heated front seats | <ul style="list-style-type: none"> • LM-rims 7x17 (10-spoke) • Rear view camera with 180 ° ambient view |
|---|---|

We remind you that the data provided were taken from the DAT database. No liability can be assumed for the completeness and correctness.

General examination

Subfloor Inspection:	Conducted limited To investigate the vehicle (ä . Lift o .) Were not lifting means even a ramp or pit available. For this reason, a visit to the vehicle's underside was limited.
Mileage plausible:	not testable not testable
reference:	
Note Road Safe:	

Farbabweichung Plastikteile

Accident injury assessment

Rep. Predamages / -height gross:	no detectable As part of a paint film thickness measuring the body outer skin no previous damage could be detected .
Layers of paint thickness measurement:	Within the tolerances At the vehicle , a resist layer thickness measurement was carried out on the body outer skin. The measured values ??were within the tolerances of original finishes . Evidence that points to a repaired accident damage or repainting carried out , were identified.
Existing collision damage:	Not established On the vehicle body shell were on visual examination found no existing accident damages (other than the usual signs of use) .
reference:	

Overview conducted technology audit					
Alternator / Generator:			in order	Battery / accumulator:	
			in order		
oil loss:			examined limited		
air conditioning:			in order	lighting system:	
			in order		
coupling:			unavailable	exhaust System:	
			examined limited		
engine running:			examined limited	shock absorber:	
			not checked		
transmission:			examined limited		

Performed testing technology	
Alternator / Generator:	The function of the alternator (generator) was tested using the charging indicator light in the instrument cluster .
Battery / accumulator:	The battery (accumulator) was examined during the inspection .
oil loss:	The vehicle could be checked only limited to oil leaks .
air conditioning:	A function of the air conditioning was found to visiting time . *Gebläse Geräusche
lighting system:	The lighting system was to tour date in order.
coupling:	The vehicle has no clutch , as it is a Autmatikgetriebe or the like.
exhaust System:	The exhaust system has been tested only restricted during the visit .
engine running:	Checking the engine running was limited. Here no audible or visual abnormalities were noted .
shock absorber:	The shocks were not examined during the inspection .
transmission:	The transmission could be examined in the context of limited test drive / pull test .
reference:	*Nutzfahrzeug typische Gebrauchsspuren und Beschädigungen.

damage



component	Damage	Rep kind
1. Heizung Gebläse Geräusche	Not okay	Carry out a fault diagnosis
2. Fahrzeug Aussen Ringsherum	Surface scratch(es)	
3. Front fender - right	Damaged	Paint
4. Outside mirror - left	Damaged	Paint
5.	Damaged	Replace
6. Front door - right	Damaged	Paint
7.	Damaged	Replace
8. Sliding door - right	Damaged	Paint
9. Sidewall - Rear - right	Damaged	Paint
10. Rear bumper	Damaged	Replace
11. Sidewall - Rear - Left	Damaged	Refurbish and paint
12. Sliding door - left	Damaged	Paint
13. Outside mirror - left	Damaged	Paint
14. Front door - left	Damaged	Refurbish and paint
15.	Damaged	Replace
16.	Damaged	Replace
17. motor insulation	Damaged	Replace
18. maintenance	Due	Replace
19. proof of maintenance	Missing	Replace

The expert points out that the vehicle in addition to age to the damage listed in the report and may have a high mileage -related wear , as in normal use are inevitable (small bumps , dents , scratches) and thus is not entitled to change or reduction .

There shall be no liability for any defect and / or remained hidden damage in terms of electronics and mechanics accepted ,r\nand for fraudulent misrepresentation and concealed defects .

photographic record



front Left



front Right



rear Left



rear Right



inside



inside



trunk



instrument cluster



mileage



filler cap



rims



rims



rims



rims



engine compartment



service book



Others



Navigation system



3. Front fender - right



3. Front fender - right



3. Front fender - right



4. Outside mirror - left



4. Outside mirror - left



5.



6. Front door - right



6. Front door - right



6. Front door - right



6. Front door - right



7.



8. Sliding door - right



8. Sliding door - right



8. Sliding door - right



9. Sidewall - Rear - right



9. Sidewall - Rear - right



9. Sidewall - Rear - right



10. Rear bumper



10. Rear bumper



10. Rear bumper



10. Rear bumper



11. Sidewall - Rear - Left



11. Sidewall - Rear - Left



11. Sidewall - Rear - Left



12. Sliding door - left



12. Sliding door - left




12. Sliding door - left



12. Sliding door - left



13. Outside mirror - left



13. Outside mirror - left




14. Front door - left




14. Front door - left



14. Front door - left



14. Front door - left



15.



15.



15.



16.



16.



17. motor insulation



17. motor insulation



17. motor insulation



17. motor insulation