



Hüsges Gruppe®
Die Gutachter

status report

customer: Bank 11, Neuss
contract number: 1075725230-INSO
reference:

vehicle data

Opel Mokka X Ultimate Start/Stop 4x4

Vehicle identification number	W0VJD7EM4JB548611	mileage read:	104599 km
First Registration / construction year:	04.12.2017 / 2017	Visit Date / place of birth:	25.09.2025 Dahlwitz-Hoppegarten
Bodywork:	cars	Re - import:	unknown
Body type:	hatchback	KBA no. :	1844//AAS
Fuel / emission class:	gasoline / € 6	transmission type:	automatic
Displacement / power:	1399 ccm / 112 kW (152 PS)	Engine:	four-wheel
paint:	Argon Silber/Ice Silver (M2)	Number of previous owners:	2
Doors / seats:	5 / 5	number keys:	2
Next HU / AU:	- / -	cushion type:	leather
Service book available:	no	Interior Color:	red
smoking vehicle:	no	Last service km / on the:	- / -
Vehicle roadworthy:	yes	Vehicle roadworthy:	no
Submitted vehicle documents:	Eg II (veh - letter)	state outside:	3 - Average
visit condition:	-	condition inside:	2 - Good
state general:	3 - Average		

Accessories (presented to the visiting time)

GPS sat nav disk:	Fzg.Schlüssel:	Service book provided / maintained:	Last service at / on:
-	2	no / -	- / -
☒ Fernbed . Auxiliary heating	☒ partition net	☒ Wind Deflector	☒ AHK fixed
☒ AHK removable	☒ AHK swivel	☒ AHK key	☒ Fernbed . entertainment
☒ headphone	☒ Load compartment cover	☒ LED headlights	☒ navigation system
☒ Persenning	☒ Xenon headlights		

☒ **available**

☒ **not available**

Hüsges GmbH
Ein Unternehmen der Hüsges Gruppe
Bankverbindung
Sparkasse Krefeld
Kto.-Nr. 1048206 · BLZ 320 500 00

Gießerallee 23
47877 Willich
Tel.: 02154 / 9534 0
Fax: 02154 / 9534 1025
Email:
info@huesges-gruppe.de



Rechtsform: Gesellschaft
mit beschränkter Haftung
Sitz: Willich
Registergericht: Krefeld HRB
Steuer-Nr.: 102/5821/0943

Geschäftsführung:
Arndt Hüsges
Dipl.- Ing. (FH) Bernd Hüsges

Hüsges GmbH
Gießerallee 23
47877 Willich
Tel.: 02154 / 9534 0
E-Mail: gutachten@huesges-group.eu

The status report was created impartially and to the best of my knowledge. The images listed in the status report are part of the vehicle description regarding the equipment and the vehicle condition.



Hüsges Gruppe®
Die Gutachter



mounted tires		
Tyre / wheel type:	summer tires	aluminum
1st axis - Left / states .	Continental	225/45/R19/92W 3 mm
1st axis - right / states .	Continental	225/45/R19/92W 3 mm
2nd axis - Left / states .	Continental	225/45/R19/92W 4 mm
2nd axis - right / states .	Continental	225/45/R19/92W 4 mm
traffic Safety:	roadworthy	
spare wheel:	Notrad	
state spare wheel:	-	

standard equipment	
• 3rd brake light • Ambient lighting dashboard • Drive all-wheel drive • Audio controls on steering wheel • Outside temperature display • board computer • roof antenna • Rev counter • Off switch for headlights • Elektron . Stability Program (ESP) • Color display (4.2 inches) • Window trim Stainless Steel / Chrome • front camera <i>Fahrassistenz-System: Verkehrszeichenerkennung,</i> <i>Fahrassistenz-System: Abstandswarner, Fahrassistenz-System: Spurhalteassistent</i> • Cargo net / bag on the front seat back • Transmission automatic - with start / stop (6-speed) • Body 5-door • Truck bed cover • Motor 1,4 Ltr. - 112 kW 16V SIDI Turbo • Fog Lights • Premium Package Leader <i>Elektro-Paket, Außenspiegel elektr. verstell- und heizbar, elektr. anklappbar, Parkpilotsystem vorn und hinten, Steckdose (12V-Anschluß) in Mittelkonsole, Komfort-Paket, Mittellarmlehne vorn, Armlehne vorn links, Klimaautomatik 2-Zonen, Winter-Paket, Sitzheizung vorn, Lenkrad heizbar, Mittellarmlehne hinten, Sitzbezug / Polsterung: Leder, Ergonomiesitz vorn links, Ergonomiesitz vorn rechts, Kopfstützen hinten (3-fach)</i> • Tire Pressure Monitoring System	• Airbag driver / passenger side • Anti -lock braking system (ABS) • Audio navigation system Navi 900 Europa Touch • Body color door mirrors • Bi-LED Spotlight with adaptive light distribution (AFL) <i>Fahrassistenz-System: Fernlichtassistent, Abbiegelicht, Heckleuchten LED</i> • Brake Assist (HBA) • Roof rails (silver) • Ecoflex • Electrical Fast heating (Quickheat) • Driving Assistance System Hill Start Assist (HSA , Hill Start Assist) • Electric windows front + rear • handsfree Bluetooth • Windscreen Solar Reflect (heat- resistant) • Cruise control system (cruise control) • Isofix admissions for child seat in back seat • Head airbag system • Steering wheel (leather) • Multimedia interface (USB / AUX-IN) • OnStar SOS Service • Wheelbase 2555 mm • Spare tire in driving tires (steel) • Rear seat split / folding • Locking / starting system Keyless Open • Side moldings black • Visibility Package <i>Fahrassistenz-System: Fernlichtassistent, Scheibenwischer mit Regensensor, Innenspiegel mit Abblendautomatik,</i>

• Rear View Camera • Low emissions Euro 6 emission standards • Side airbags • Power steering speed-dependent • Front left seat height adjustable • Start / Stop system • • Warning system for safety , passenger side • immobilizer • Sun protection glazing behind darkened (Solar -Protect)	<i>Sonnenblenden mit Spiegel (beleuchtet)</i> • Sound-System BOSE • LED daytime running lights • Exterior door handles body color with chrome insert • Warning system for seat belt , driver's side • Wärmeschutzverglasung • Central locking with remote control
---	---

special Features	
• DAB tuner (digital radio reception) • Metallic / mineral effect spraying	• LM rims 7,5x19 (5 double spokes) • Sliding / tilt sunroof electric (glass)

We remind you that the data provided were taken from the DAT database. No liability can be assumed for the completeness and correctness.

General examination	
Subfloor Inspection:	Conducted limited To investigate the vehicle (ä . Lift o .) Were not lifting means even a ramp or pit available. For this reason, a visit to the vehicle's underside was limited.
Mileage plausible:	not testable not testable
reference:	
Note Road Safe:	

Farbabweichung Plastikteile

Accident injury assessment	
Rep. Predamages / -height gross:	Expertly repaired On a vehicle coating thickness measurement on the body outer skin were noted repaired previous damage in the frames that were repaired and apparently without disassembly of components without residual traces accident . If there is an impairment of the observed accident before it was taken into account in if conducted vehicle valuation.
Layers of paint thickness measurement:	Out of tolerance At the vehicle , a resist layer thickness measurement was carried out on the body



outer skin. The measured values ??were outside the tolerances of original finishes .

Existing collision damage:

-

-

reference:

Overview conducted technology audit					
Alternator / Generator:		examined limited	Battery / accumulator:		examined limited
oil loss:		examined limited			
air conditioning:		not possible	lighting system:		examined limited
coupling:		unavailable	exhaust System:		examined limited
engine running:		Out of order	shock absorber:		examined limited
transmission:		examined limited			

Performed testing technology	
Alternator / Generator:	The function of the alternator (generator) was tested using the charging indicator light in the instrument cluster .
Battery / accumulator:	The battery (accumulator) could be considered limited during the visit .
oil loss:	The vehicle could be checked only limited to oil leaks .
air conditioning:	The air conditioning could not be checked during the inspection . **Due to weather conditions not possible examination.
lighting system:	The Lichtanlage could be considered limited to the tour date .
coupling:	The vehicle has no clutch , as it is a Automatikgetriebe or the like.
exhaust System:	The exhaust system has been tested only restricted during the visit .
engine running:	A field test of the engine had to acoustic or visual defects for visiting time .
shock absorber:	The shock absorber could be tested only restricted during the visit .
transmission:	The transmission could be examined in the context of limited test drive / pull test .
reference:	*

damage



component	Damage	Rep kind
1. Front door - right	Subsequently painted	acceptable
2. Front fender - right	Subsequently painted	acceptable
3. proof of maintenance	Missing	Replace
4. maintenance	Missing	Replace
5. motor	Error message	Carry out a fault diagnosis
6. motor insulation	Damaged	Replace
7. tailgate trim	Not okay	Carry out a fault diagnosis
8. Rear bumper	Scratch(es)	Paint
9. tailgate	Scratch(es)	Paint
10. TürEinstieg Hinten - Rechts	Scratch(es)	Paint
11. roof	Delle	Smart repair
12. tire front - right	Damaged	Smart repair
13. Front fender - left	Scratch(es)	Replace
14. Front bumper	Scratch(es)	Paint
15. Rear door - left	Scratch(es)	Paint
16. Steering wheel (leather)	chipped paint	Paint
17. Door Rear - right	Scratch(es)	Smart repair
18. Sidewall - Rear - right	Scratch(es)	Smart repair
19. Door Rear - right	Scratch(es)	Paint
20. Sidewall - Rear - right	Scratch(es)	Paint
21. Steering wheel (leather)	Damaged	Replace
22. Door Rear - right	Scratch(es)	Paint
23. Sidewall - Rear - right	Scratch(es)	Paint

The expert points out that the vehicle in addition to age to the damage listed in the report and may have a high mileage -related wear , as in normal use are inevitable (small bumps , dents , scratches) and thus is not entitled to change or reduction .

There shall be no liability for any defect and / or remained hidden damage in terms of electronics and mechanics accepted ,r\nand for fraudulent misrepresentation and concealed defects .

photographic record



front Left



front Right



rear Left



rear Right



inside



inside



trunk



instrument cluster



mileage



filler cap



rims



rims




rims



rims



engine compartment



service book



Others



Navigation system



1. Front door - right



2. Front fender - right



6. motor



7. motor insulation



8. tailgate trim



9. Rear bumper



9. Rear bumper



10. tailgate



11.



12. Türeinstieg Hinten - Rechts



12. Türeinstieg Hinten - Rechts



13. roof




14. tire front - right



15.



16.



17. Front fender - left



18.



19. Front bumper




19. Front bumper



20. Rear door - left



21. Steering wheel (leather)



22. Door Rear - right



23. Sidewall - Rear - right