



Hüsge Gruppe®
Die Gutachter

status report

customer: Opel Grosskunden/FSL/Free2Move
contract number:
reference:

vehicle data

Opel Movano B Kasten/Kombi HKa L2H2 3,5t

Vehicle identification number	W0VMR8605MB250217	mileage read:	140371 km
First Registration / construction year:	08.06.2021 / 2019	Visit Date / place of birth:	02.09.2025 Heidenheim
Bodywork:	transporter	Re - import:	no
Body type:	van	KBA no. :	1844//AKM
Fuel / emission class:	diesel / € 6	transmission type:	manual transmission
Displacement / power:	2299 ccm / 100 kW (136 PS)	Engine:	front-wheel drive
paint:	Mineral/Polar Weiss (055P)	Number of previous owners:	2
Doors / seats:	4 / 3	number keys:	2
Next HU / AU:	05.2025 / 05.2025	cushion type:	substance
Service book available:	yes	Interior Color:	gray
smoking vehicle:	yes	Last service km / on the:	77767 / 19.05.2023
Vehicle roadworthy:	yes	Vehicle roadworthy:	yes
Submitted vehicle	-	state outside:	3 - Average
documents:		condition inside:	3 - Average
visit condition:	-		
state general:	3 - Average		

Accessories (presented to the visiting time)

GPS sat nav disk:	Fzg.Schlüssel:	Service book provided / maintained:	Last service at / on:
-	2	yes / -	77767 / 19.05.2023

☒ AHK key	☒ AHK removable	☒ AHK fixed	☒ AHK swivel
☒ Fernbed . entertainment	☒ Fernbed . Auxiliary heating	☒ headphone	☒ LED headlights
☒ Load compartment cover	☒ navigation system	☒ Persenning	☒ partition net
☒ Wind Deflector	☒ Xenon headlights		

☒ **available**

☒ **not available**

Hüsge GmbH
Ein Unternehmen der Hüsge Gruppe
Bankverbindung
Sparkasse Krefeld
Kto.-Nr. 1048206 · BLZ 320 500 00

Gießerallee 23
47877 Willich
Tel.: 02154 / 9534 0
Fax: 02154 / 9534 1025
Email:
info@huesges-gruppe.de



Rechtsform: Gesellschaft
mit beschränkter Haftung
Sitz: Willich
Registergericht: Krefeld HRB
Steuer-Nr.: 102/5821/0943

Geschäftsführung:
Arndt Hüsge
Dipl.- Ing. (FH) Bernd Hüsge

Hüsges GmbH
Gießerallee 23
47877 Willich
Tel.: 02154 / 9534 0
E-Mail: gutachten@huesges-group.eu

The status report was created impartially and to the best of my knowledge. The images listed in the status report are part of the vehicle description regarding the equipment and the vehicle condition.



Hüsges Gruppe®
Die Gutachter



mounted tires

Tyre / wheel type:	All season tires	Steel with wheel cover
1st axis - Left / states .	Anderer	225/65/16/112/110R 6.6 mm
1st axis - right / states .	Anderer	225/65/16/112/110R 6.6 mm
2nd axis - Left / states .	Anderer	225/65/16/112/110R 4.9 mm
2nd axis - right / states .	Anderer	225/65/16/112/110R 4.9 mm
traffic Safety:	roadworthy	
spare wheel:	vorhanden	
state spare wheel:	Vollwertig	

standard equipment

- | | |
|--|--|
| <ul style="list-style-type: none"> • Anti- lock braking system (ABS) • Power side mirrors . adjustable and heated • Driving assistance system Crosswind Assistant • Generator 185 A • Rear wing doors without glazing (opening angle 180 degrees) • pollen filter • Karosserievariante vehicle length L2 • Fuel tank 80 liters . • Steering column (steering wheel) adjustable • Facelift • Wheelbase 3682 mm
<i>Radstand mittellang</i> • Sliding load / passenger compartment right • Steel rims 6,5x16 • Central locking with remote control selective | <ul style="list-style-type: none"> • Drive Front Wheel Drive • Single tires on 2nd axle / rear axle • Electric windows front • Transmission 6-speed • High roof H2, Perm. Total weight of 3.5 t • Body / Structure box high room • Karosserievariante high roof (H2) • Cargo space partition cpl. • Headlamp leveling • • Low-emission according to the Euro 6d-TEMP emissions standard • Visibility Package
<i>Einschaltautomatik für Fahrlicht, Scheibenwischer mit Regensensor</i> • LED daytime running lights • Perm. Total weight of 3.5 t |
|--|--|

special Features

- | | |
|--|--|
| <ul style="list-style-type: none"> • Airbag Driver / passenger side • Edition package
<i>Audio-Navigationssystem Navi 50 IntelliLink Pro (DAB+), Parkpilotsystem, Geschwindigkeits-Regelanlage (Tempomat), Bordcomputer, Laderaumtrennwand geräuschedämmend, Klimaanlage, Innenraumfilter: Pollenfilter, Sitze im Fahrerhaus: Fahrersitz Komfort, Sitze im Fahrerhaus: Beifahrerdoppelsitz multifunktional, Fensterheber elektrisch vorn, Handschuhfach ausziehbar (FlexTray), Ausziehbares Tablett und Getränkehalter, Beifahrerseite, Verzurrrösen Laderaum seitlich, Radvollabdeckungen</i> • Luggage room lighting LED • Light package 1 | <ul style="list-style-type: none"> • All-weather / all-season tires • • Wood floor in the cargo area • Spare wheel |
|--|--|

*Nebelscheinwerfer, Einschaltautomatik für Fahrlicht,
 Scheibenwischer mit Regensensor*

We remind you that the data provided were taken from the DAT database. No liability can be assumed for the completeness and correctness.

General examination

Subfloor Inspection:	not possible A visit to the underside of your vehicle could not be performed. Hoist or lifting means not available .
Mileage plausible:	not testable not testable
reference:	
Note Road Safe:	

Accident injury assessment

Rep. Predamages / -height gross:	no detectable As part of a paint film thickness measuring the body outer skin no previous damage could be detected .
Layers of paint thickness measurement:	Within the tolerances At the vehicle , a resist layer thickness measurement was carried out on the body outer skin. The measured values ??were within the tolerances of original finishes . Evidence that points to a repaired accident damage or repainting carried out , were identified.
Existing collision damage:	Not established On the vehicle body shell were on visual examination found no existing accident damages (other than the usual signs of use) .
reference:	

Overview conducted technology audit					
Alternator / Generator:			examined limited	Battery / accumulator:	
			in order		
oil loss:			in order		
air conditioning:			in order	lighting system:	
			in order		
coupling:			examined limited	exhaust System:	
			examined limited		
engine running:			in order	shock absorber:	
			not checked		
transmission:			examined limited		

Performed testing technology	
Alternator / Generator:	The function of the alternator (generator) was tested using the charging indicator light in the instrument cluster .
Battery / accumulator:	The battery (accumulator) was examined during the inspection .
oil loss:	The vehicle was inspected during the visit to an oil leak .
air conditioning:	A function of the air conditioning was found to visiting time .
lighting system:	The lighting system was to tour date in order.
coupling:	The clutch could be tested only limited within the test drive / pull test .
exhaust System:	The exhaust system has been tested only restricted during the visit .
engine running:	A field test of the engine was performed.
shock absorber:	The shocks were not examined during the inspection .
transmission:	The transmission could be examined in the context of limited test drive / pull test .
reference:	*Nutzfahrzeug typische Gebrauchsspuren und Beschädigungen.

damage



	component	Damage	Rep kind
1.	Fahrerkabine	Dirty	
2.	Sitzbezug Fahrersitz	Worn	Replace
3.	hood	Sticker	
4.	Front door - right	Sticker	
5.	Sliding door - right	Sticker	
6.	Sidewall - Rear - right	Sticker	
7.	Sidewall - Rear - right	Damaged	Refurbish and paint
8.	Schutzleiste rechts Seitenwand	Damaged	Replace
9.	tailgate	Sticker	
10.	Sidewall - Rear - Left	Sticker	
11.	Front door - left	Sticker	
12.	Einstiegleiste Laderaum hinten	Breakage	Replace
13.	maintenance	Due	Replace

The expert points out that the vehicle in addition to the age- damage listed in the report and may have a high mileage -related wear , as in normal use are inevitable (small bumps , dents , scratches) .

There shall be no liability for any defect and / or remained hidden damage in terms of electronics and mechanics accepted ,\r\nand for fraudulent misrepresentation and concealed defects .

photographic record



front Left



front Right



rear Left



rear Right



inside



trunk



instrument cluster



mileage



filler cap



rims



rims



rims



rims



engine compartment



service book



Others



Navigation system



Navigation system



1. Fahrerkabine

Dirty



1. Fahrerkabine

Dirty



1. Fahrerkabine

Dirty



1. Fahrerkabine

Dirty



1. Fahrerkabine

Dirty



2. Sitzbezug Fahrersitz

Worn



2. Sitzbezug Fahrersitz

Worn



3. hood

Sticker



3. hood

Sticker



4. Front door - right

Sticker



5. Sliding door - right

Sticker



5. Sliding door - right

Sticker



6. Sidewall - Rear - right

Sticker



7. Sidewall - Rear - right

Damaged



7. Sidewall - Rear - right

Damaged



7. Sidewall - Rear - right

Damaged



7. Sidewall - Rear - right

Damaged



8. Schutzleiste rechts Seitenwand

Damaged



8. Schutzleiste rechts Seitenwand

Damaged



8. Schutzleiste rechts Seitenwand

Damaged



9. tailgate

Sticker



9. tailgate

Sticker



10. Sidewall - Rear - Left

Sticker



10. Sidewall - Rear - Left

Sticker



11. Front door - left

Sticker



11. Front door - left

Sticker



12. Einstiegleiste Laderaum hinten

Breakage



12. Einstiegleiste Laderaum hinten

Breakage



12. Einstiegleiste Laderaum hinten

Breakage



12. Einstiegleiste Laderaum hinten

Breakage