


Vehicle details

VIN	W0VMRLS00 JB145038	Brand	OPEL	Maintenance date	-
Licence Plate	V5-16-LV	Model	MOVANO L2H2 2.3CDTI 125kW EU6 Tecshift 3.5T 4d	Maintenance mileage	-
Registration date	28/02/2018	Year	2018	Exterior Color	White Solid
Odometer	177 664 km	Engine size	2299	interior Color	Grey
Fuel	Diesel	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Automatic	CO2	-
Doors	4	Gears	-		

Inspection Details

Inspection date	06/10/2025	Inspection loc.	Dekra Ayvens
-----------------	------------	-----------------	--------------



Generic equipment

Manual air-conditioning	✓
Cruise control	✓
Automatic Gearbox	✓
Tow	✓
Central locking	✓
Electric windows	✓
Park Distance Control	✓
Audio System	✓

Removable element


Spare wheel (wheel & tyre)	✓
----------------------------	---

Technical Document

Spare key	✓
Remote key	✓

Tyres

Winter kit

Bridgestone 225/65/16 Winter 7.0 mm		Bridgestone 225/65/16 Winter 7.0 mm	
Bridgestone 225/65/16 Winter 6.0 mm		Bridgestone 225/65/16 Winter 6.0 mm	

Exterior

2		Part Position Damages Severity Repair mode	Windscreen - Stone impact - For info	3		Part Position Damages Severity Repair mode	Bonnet - Rusty Diameter (mm) > 4 Lumpsum repair
4		Part Position Damages Severity Repair mode	Bumper Front Broken - Replace	5		Part Position Damages Severity Repair mode	Sill Right Dent & Chips Diameter (mm) > 20 Repair
6		Part Position Damages Severity Repair mode	Door Front right Dented Diameter (mm) > 20 Smart Repair	7		Part Position Damages Severity Repair mode	Door moulding Front right Scratched Length (cm) > 10 Repair
8		Part Position Damages Severity Repair mode	Wing moulding Front right Scratched Length (cm) > 10 Repair	9		Part Position Damages Severity Repair mode	Door moulding Right Scratched Length (cm) > 10 Repair
10		Part Position Damages Severity Repair mode	Lower door Right Dent & Chips Diameter (mm) > 20 Repair	11		Part Position Damages Severity Repair mode	Wing moulding Back right Scratched Length (cm) > 10 Repair
12		Part Position Damages Severity Repair mode	Door Back right Dented Diameter (mm) > 20 Smart Repair				

Interior damage

1		Part Position Damages Severity Repair mode	Fabric seat Front left Perforated - Smart Repair
---	---	--	--