



status report

customer: BCA Autoauktionen GmbH
report Number: 0000001244679-EN18

vehicle data

Opel Grandland (X) GS Line

Vehicle identification number	W0VZCYHZXP6011164	mileage read:	34195 km
First Registration / construction year:	25.04.2023 / 2022	Visit Date / place of birth:	26.06.2025 Heidenheim
Bodywork:	cars	Re - import:	unknown
Body type:	hatchback	KBA no. :	1844//AHG
Fuel / emission class:	diesel / € 6	transmission type:	automatic
Displacement / power:	1499 ccm / 96 kW (131 PS)	Engine:	front-wheel drive
paint:	Jade Weiss/Arktis Weiss	Number of previous owners:	1
Doors / seats:	5 / 5	number keys:	2
Next HU / AU:	- / -	cushion type:	substance
Service book available:	yes	Interior Color:	black
smoking vehicle:	no	Last service km / on the:	15436 / 25.06.2024
Vehicle roadworthy:	yes	Vehicle roadworthy:	yes
Submitted vehicle	-	state outside:	3 - Average
documents:			
visit condition:	in the parking garage	condition inside:	3 - Average
state general:	3 - Average		

Accessories (presented to the visiting time)

GPS sat nav disk:	Fzg.Schlüssel:	Service book provided / maintained:	Last service at / on:
Hard Disk Drive	2	yes / -	15436 / 25.06.2024

☒ AHK key	☒ AHK removable	☒ AHK fixed	☒ AHK swivel
☒ Fernbed . entertainment	☒ Fernbed . Auxiliary heating	☒ headphone	☒ LED headlights
☒ Load compartment cover	☒ navigation system	☒ Persenning	☒ partition net
☒ Wind Deflector	☒ Xenon headlights		

☒ **available** ☒ **not available**

Hüsges GmbH
Gießerallee 23
47877 Willich
Tel.: 02154 / 9534 0
E-Mail: gutachten@huesges-group.eu

The status report was created impartially and to the best of my knowledge. The images listed in the status report are part of the vehicle description regarding the equipment and the vehicle condition.



Hüsges Gruppe®
Die Gutachter



mounted tires		
Tyre / wheel type:	Winter tires	aluminum
1st axis - Left / states .	Goodyear	225/55/R18/102V 5.5 mm
1st axis - right / states .	Goodyear	225/55/R18/102V 5.5 mm
2nd axis - Left / states .	Goodyear	225/55/R18/102V 5.5 mm
2nd axis - right / states .	Goodyear	225/55/R18/102V 5.5 mm
traffic Safety:	roadworthy	
spare wheel:	nicht vorhanden	
state spare wheel:	-	

standard equipment	
• Airbag driver / passenger side • Ambient lighting door trim • Drive Front Wheel Drive • Power side mirrors . adjustable and heated , electric. anklappbar • board computer • DAB tuner (digital radio reception) • Roof rails black, high-gloss • Elektron . Stability Program Plus (ESP) <i>Elektron. Stabilitäts-Programm (ESP)</i> • Ergonomics front left seat <i>Lendenwirbelstütze Sitz vorn links, elektr. verstellbar</i> • Driving Assistance System Hill Start Assist (HSA , Hill Start Assist) • Driver assistance system Traffic sign recognition • Parking brake electrically • Transmission automatic - with start / stop (8-speed) • Rearview mirror with auto dip • Isofix admissions for child seat in back seat • 2-zone automatic climate control • Steering wheel (sport / leather - 3-spoke, flattened below) with multifunction • Front reading lights (2) • model refinement • MP3 interface for mobile phone / cell phone • aluminum pedals • Tire Pressure Monitoring System • Rear View Camera <i>Parkpilotsystem vorn und hinten, Außenspiegel elektr. anklappbar</i> • Windscreen wipers with rain sensor	• Ambient lighting center console • Anti -lock braking system (ABS) • Audio controls on steering wheel • Bluetooth Audio-Streaming • Brake Assist (HBA) • Roof, design version (black) • Off switch for headlights • Elektron . traction control • Driver assistance system distance warning • • Electric windows front + rear • Windscreen sound-absorbing • LED Taillights • Isofix seats for child seat on front passenger seat • Body 5-door • Head airbag system • Reading lights in the rear • LM rims • Engine 1,5 Ltr. - 96 kW CDTI DPF • Parking Assist System, rear • Wheelbase 2675 mm • Rußpartikelfilter • Low in emissions according to the Euro 6e emissions standard • • Sun visors with mirrors (illuminated) • Socket (12V) port in center console • Exterior door handles body color with chrome insert • USB interface • Sun protection glazing behind darkened (Solar -Protect)

- Side airbags
- Start / Stop system
- LED daytime running lights
- Skid plate look, front and rear (Black)
- immobilizer
- Central locking with remote control

special Features

- | | |
|--|---|
| <ul style="list-style-type: none"> • Audio navigation system Multimedia Navi Pro (10" display) • Ergonomics front right seat
<i>Ergonomiesitz vorn links, Lendenwirbelstütze Sitz vorn links, elektr. verstellbar, Lendenwirbelstütze Sitz vorn rechts, elektr. verstellbar</i> • Special paint Brilliant | <ul style="list-style-type: none"> • Design Package
<i>Dach schwarz lackiert, Außenspiegel schwarz lackiert, Dachreling schwarz, hochglänzend</i> • Driving Assistance System Autonomous
Emergency Brake Assist with Front Collision Warning and Pedestrian Detection
<i>Fahrassistenz-System: Notbrems-Assistent, Fahrassistenz-System: Frontkollisionswarnung, Fahrassistenz-System: Müdigkeitserkennungs-Sensor, Fahrassistenz-System: aktiver Spurhalteassistent (Lenkunterstützung)</i> • Winter package
<i>Frontscheibe heizbar (ThermaTec), Sitzheizung vorn, Lenkrad heizbar, Rücksitzlehnen umklappbar FlexFold</i> |
|--|---|

We remind you that the data provided were taken from the DAT database. No liability can be assumed for the completeness and correctness.

General examination

Mileage plausible: not testable
not testable

reference:

Note Road Safe:

Accident injury assessment

Rep. Predamages / -height gross:	no detectable As part of a paint film thickness measuring the body outer skin no previous damage could be detected .
Layers of paint thickness measurement:	Within the tolerances At the vehicle , a resist layer thickness measurement was carried out on the body outer skin. The measured values ??were within the tolerances of original finishes . Evidence that points to a repaired accident damage or repainting carried out , were identified.
Existing collision damage:	Not established

On the vehicle body shell were on visual examination found no existing accident damages (other than the usual signs of use) .

reference:

Overview conducted technology audit

coupling:	 unavailable	engine running:	 examined limited
transmission:	 examined limited		

Performed testing technology

coupling:	The vehicle has no clutch , as it is a Autmatikgetriebe or the like.
engine running:	Checking the engine running was limited. Here no audible or visual abnormalities were noted .
transmission:	The transmission could be examined in the context of limited test drive / pull test .
reference:	*Fahrzeug war zum Zeitpunkt der Begutachtung Verschmutz/Nass/Vereist/Zugeparkt oder wurde bei unzureichender bzw schlechter Beleuchtung besichtigt.Manche Bereiche waren unter Umständen verdeckt oder zugesagt.Unter Umständen waren nicht alle Fahrzeugsysteme und Ausstattung prüfbar.Versteckte Schäden oder Schadenserweiterung möglich.

damage



	component	Damage	Rep kind
1.	maintenance	Due	Replace
2.	motor insulation		Replace
3.			Replace
4.	roof	Scratch(es)	Smart repair
5.	Door trim Front - right	Scratch(es)	Smart repair
6.	Trunk Flooring	Missing	Replace

The expert points out that the vehicle in addition to the age- damage listed in the report and may have a high mileage -related wear , as in normal use are inevitable (small bumps , dents , scratches) .

There shall be no liability for any defect and / or remained hidden damage in terms of electronics and mechanics accepted ,r\nand for fraudulent misrepresentation and concealed defects .

photographic record



front Left



front Right



rear Left



rear Right



inside



trunk



instrument cluster



mileage



filler cap



rims




rims




rims




rims




VIN



service book




Others



interior rear



Navigation system




Drivers side + Steering Wheel + center console



1. maintenance

Due



1. maintenance

Due



2. motor insulation



2. motor insulation



3.



4. roof
 Scratch(es)



4. roof
 Scratch(es)



5. Door trim Front - right
 Scratch(es)



5. Door trim Front - right
 Scratch(es)



5. Door trim Front - right
 Scratch(es)



6. Trunk Flooring
 Missing