



status report

customer: Bank 11, Neuss
contract number: 965626031
reference:

vehicle data

Opel Insignia B Sports Tourer Edition

Vehicle identification number	W0VZM8EN2M1011263	mileage read:	32616 km
First Registration / construction year:	15.02.2021 / 2020	Visit Date / place of birth:	26.08.2025 Dorfmark
Bodywork:	cars	Re - import:	no
Body type:	hatchback	KBA no. :	1844//AME
Fuel / emission class:	diesel / € 6	transmission type:	6 speed manual transmission
Displacement / power:	1496 ccm / 90 kW (122 PS)	Engine:	front-wheel drive
paint:	black	Number of previous owners:	-
Doors / seats:	5 / 5	number keys:	2
Next HU / AU:	- / -	cushion type:	substance
Service book available:	yes	Interior Color:	black
smoking vehicle:	no	Last service km / on the:	31787 / 24.10.2024
Vehicle roadworthy:	yes	Vehicle roadworthy:	yes
Submitted vehicle documents:	For example, I (Fzg.Schein)	state outside:	2 - Good
visit condition:	-	condition inside:	2 - Good
state general:	2 - Good		

Accessories (presented to the visiting time)

GPS sat nav disk:	Fzg.Schlüssel:	Service book provided / maintained:	Last service at / on:
-	2	yes / -	31787 / 24.10.2024
<input checked="" type="checkbox"/> AHK key	<input checked="" type="checkbox"/> AHK removable	<input checked="" type="checkbox"/> AHK fixed	<input checked="" type="checkbox"/> AHK swivel
<input checked="" type="checkbox"/> Fernbed . entertainment	<input checked="" type="checkbox"/> Fernbed . Auxiliary heating	<input checked="" type="checkbox"/> headphone	<input checked="" type="checkbox"/> LED headlights
<input checked="" type="checkbox"/> Load compartment cover	<input checked="" type="checkbox"/> navigation system	<input checked="" type="checkbox"/> Persenning	<input checked="" type="checkbox"/> partition net
<input checked="" type="checkbox"/> Wind Deflector	<input checked="" type="checkbox"/> Xenon headlights		

☒ **available**

☒ **not available**

The status report was created impartially and to the best of my knowledge. The images listed in the status report are part of the vehicle description regarding the equipment and the vehicle condition.



Hüsges Gruppe®
Die Gutachter



mounted tires		
Tyre / wheel type:	Winter tires	steel
1st axis - Left / states .	Bridgestone	225/55/R17/101V 5 mm
1st axis - right / states .	Bridgestone	225/55/R17/101V 5 mm
2nd axis - Left / states .	Bridgestone	225/55/R17/101V 5 mm
2nd axis - right / states .	Bridgestone	225/55/R17/101V 5 mm
traffic Safety:	roadworthy	
spare wheel:	-	
state spare wheel:	-	

Unmounted tires		
Tyre / wheel type:	All season tires	steel
1st axis - Left / states .	Goodyear	225/55/R17/101V 5 mm
1st axis - right / states .	Goodyear	225/55/R17/101V 5 mm
2nd axis - Left / states .	Goodyear	225/55/R17/101V 5 mm
2nd axis - right / states .	Goodyear	225/55/R17/101V 5 mm
traffic Safety:	roadworthy	

standard equipment	
<ul style="list-style-type: none"> • 3-point rear center seat belt • Anti -lock braking system (ABS) • Multimedia audio system • Body color door mirrors / black high-gloss • Brake Assist (HBA) • Roof, design execution • Electrical Fast heating (Quickheat) • Elektron . traction control • Power windows rear • Parking brake electrically • front camera <i>Fahrassistenz-System: Abstandswarner, Fahrassistenz-System: Notbrems-Assistent, Fahrassistenz-System: Frontkollisionswarnung, Fahrassistenz-System: Fußgängererkennung, Fahrassistenz-System: Spurhalteassistent</i> • Cruise control system (cruise control) • LED Taillights • Interior trim finishers Parallax • Body 5-door • 2-zone automatic climate control <i>Luftfeuchtesensor</i> • Rear headrests (3- fold) • model refinement 	<ul style="list-style-type: none"> • Airbag driver / passenger side • Drive Front Wheel Drive • Mirrors and electric folding . adjustable and heated • Bluetooth Audio-Streaming • DAB tuner (digital radio reception) • Rev counter • Elektron . Stability Program Plus (ESP) <i>Elektron. Stabilitäts-Programm (ESP)</i> • Driving Assistance System Hill Start Assist (HSA , Hill Start Assist) • Electric windows front • handsfree Bluetooth • Pedestrian protection system Active hood • Transmission 6-speed • Rear wiper with intermittent • Isofix admissions for child seat in back seat • childlock • Head airbag system • Steering wheel (leather 3-spoke) <i>Audiobedienung am Lenkrad</i> • Engine 1.5 Ltr. - 90 kW CDTI DPF CAT • Fog lights LED • Tire pressure Warner • Low pollutant according to the Euro 6d emissions

<ul style="list-style-type: none"> • MP3 interface for mobile phone / cell phone • Park Pilot system, front and rear • RuÅpartikelfilter • • Visibility Package <i>Einschaltautomatik für Fahrlicht, Fahrassistenten-System: Fernlichtassistent, Scheibenwischer mit Regensensor, Innenspiegel mit Abblendautomatik</i> • Sun visors with mirrors (illuminated) • LED daytime running lights • immobilizer 	<p>standard</p> <ul style="list-style-type: none"> • Side airbags • Smartphone interface (Apple CarPlay & Android Auto) • Steel rims 7x17 (design / structure wheel, bicolor) • Exterior body color door handles • Central locking with remote control
--	---

special Features	
<ul style="list-style-type: none"> • All-weather / all-season tires • Metallic / mineral effect spraying 	<ul style="list-style-type: none"> • Luggage compartment separation (net) <i>Sicherheitsnetz hinter Vordersitze, Vorrüstung Sicherheitsnetz hinter Vordersitze</i> • Winter package <i>Sitzheizung vorn, Lenkrad heizbar</i>

We remind you that the data provided were taken from the DAT database.\\nNo liability can be assumed for the completeness and correctness.

General examination	
Subfloor Inspection:	<p>Conducted limited</p> <p>To investigate the vehicle (ä . Lift o .) Were not lifting means even a ramp or pit available. For this reason, a visit to the vehicle's underside was limited.</p>
Mileage plausible:	<p>yes</p> <p>yes</p>
reference:	
Note Road Safe:	

Farbabweichung Plastikteile

Accident injury assessment	
Rep. Predamages / -height gross:	<p>Expertly repaired</p> <p>On a vehicle coating thickness measurement on the body outer skin were noted repaired previous damage in the frames that were repaired and apparently without disassembly of components without residual traces accident . If there is an impairment of the observed accident before it was taken into account in if conducted vehicle valuation.</p>

Layers of paint thickness

measurement:

Existing collision damage:

reference:

Out of tolerance

At the vehicle , a resist layer thickness measurement was carried out on the body outer skin. The measured values ??were outside the tolerances of original finishes .

Not established

On the vehicle body shell were on visual examination found no existing accident damages (other than the usual signs of use) .

Overview conducted technology audit

Alternator / Generator:	✓ examined limited	Battery / accumulator:	✓ examined limited
oil loss:	✓ examined limited		
air conditioning:	✓ examined limited	lighting system:	✓ examined limited
coupling:	✓ examined limited	exhaust System:	✓ examined limited
engine running:	✓ in order	shock absorber:	✓ examined limited
transmission:	✓ examined limited		

Performed testing technology

Alternator / Generator:	The function of the alternator (generator) was tested using the charging indicator light in the instrument cluster .
Battery / accumulator:	The battery (accumulator) could be considered limited during the visit .
oil loss:	The vehicle could be checked only limited to oil leaks .
air conditioning:	The air conditioning system could be tested only restricted during the visit .
lighting system:	The Lichtanlage could be considered limited to the tour date .
coupling:	The clutch could be tested only limited within the test drive / pull test .
exhaust System:	The exhaust system has been tested only restricted during the visit .
engine running:	A field test of the engine was performed.
shock absorber:	The shock absorber could be tested only restricted during the visit .
transmission:	The transmission could be examined in the context of limited test drive / pull test .
reference:	*

damage



	component	Damage	Rep kind
1.	hood	Subsequently painted	acceptable
2.	Hubcap - Rear - Left	Wear and tear	acceptable
3.	roof	Damaged	Refurbish and paint
4.	hood	Damaged	Smart repair
5.	Front bumper	Damaged	Replace
6.	Door Rear - right	Scratch(es)	Paint
7.	Rear bumper	Scratch(es)	Smart repair

The expert points out that the vehicle in addition to age to the damage listed in the report and may have a high mileage -related wear , as in normal use are inevitable (small bumps , dents , scratches) and thus is not entitled to change or reduction .

There shall be no liability for any defect and / or remained hidden damage in terms of electronics and mechanics accepted ,\r\nand for fraudulent misrepresentation and concealed defects .

photographic record



front Left



front Right



rear Left



rear Right



inside



inside



trunk



instrument cluster



mileage



filler cap



rims



rims



rims



rims



engine compartment




service book




1. hood



2. Hubcap - Rear - Left



3. roof



3. roof



3. roof



4. hood



5. Front bumper



5. Front bumper



5. Front bumper



6. Door Rear - right



6. Door Rear - right



6. Door Rear - right



7. Rear bumper



7. Rear bumper



7. Rear bumper