



status report

customer:	Opel Grosskunden/FSL/Free2Move
contract number:	
reference:	

vehicle data			
Opel Grandland GS Line			
Vehicle identification number	W0VZRHNS8N6802411	mileage read:	54285 km
∴			
First Registration / construction year:	15.06.2022 / 2022	Visit Date / place of birth:	08.09.2025 Heidenheim
Bodywork:	SUV	Re - import:	no
Body type:	Road /	KBA no. :	1844//AAN
Fuel / emission class:	gasoline / € 6	transmission type:	automatic
Displacement / power:	1199 ccm / 96 kW (131 PS)	Engine:	front-wheel drive
paint:	Rubin Rot	Number of previous owners:	1
Doors / seats:	5 / 5	number keys:	2
Next HU / AU:	- / -	cushion type:	Leather / Alcantara
Service book available:	yes	Interior Color:	black
smoking vehicle:	no	Last service km / on the:	54223 / 27.05.2025
Vehicle roadworthy:	yes	Vehicle roadworthy:	yes
Submitted vehicle	-	state outside:	2 - Good
documents:			
visit condition:	-	condition inside:	2 - Good
state general:	2 - Good		

Accessories (presented to the visiting time)			
GPS sat nav disk:	Fzg.Schlüssel:	Service book provided /	Last service at / on:
Hard Disk Drive	2	maintained:	54223 / 27.05.2025
		yes / -	
☒ AHK key	☒ AHK removable	☒ AHK fixed	☒ AHK swivel
☒ Fernbed . entertainment	☒ Fernbed . Auxiliary heating	☒ headphone	☒ LED headlights
☒ Load compartment cover	☒ navigation system	☒ Persenning	☒ partition net
☒ Wind Deflector	☒ Xenon headlights		

☒ **available**

☒ **not available**

Hüsges GmbH
Gießerallee 23
47877 Willich
Tel.: 02154 / 9534 0
E-Mail: gutachten@huesges-group.eu

The status report was created impartially and to the best of my knowledge. The images listed in the status report are part of the vehicle description regarding the equipment and the vehicle condition.



Hüsges Gruppe®
Die Gutachter



mounted tires		
Tyre / wheel type:	summer tires	original aluminum
1st axis - Left / states .	Pirelli	225/55/R18/102V 3.4 mm
1st axis - right / states .	Pirelli	225/55/R18/102V 3.4 mm
2nd axis - Left / states .	Pirelli	225/55/R18/102V 2.9 mm
2nd axis - right / states .	Pirelli	225/55/R18/102V 2.9 mm
traffic Safety:	roadworthy	
spare wheel:	nicht vorhanden	
state spare wheel:	-	

standard equipment	
• Airbag driver / passenger side • Ambient lighting door trim • Drive Front Wheel Drive • Power side mirrors . adjustable and heated , electric. anklappbar • board computer • DAB tuner (digital radio reception) • <i>Dach, Design-Ausführung (schwarz), Schriftzug Heckklappe Schwarz, Hochglanz</i> • Elektron . Stability Program Plus (ESP) <i>Elektron. Stabilitäts-Programm (ESP)</i> • Ergonomics front left seat <i>Lendenwirbelstütze Sitz vorn links, elektr. verstellbar</i> • Driving Assistance System Hill Start Assist (HSA , Hill Start Assist) • Driver assistance system Traffic sign recognition • Parking brake electrically • Transmission automatic - with start / stop (8-speed) • Rearview mirror with auto dip • Isofix admissions for child seat in back seat • 2-zone automatic climate control • Steering wheel (sport / leather - 3-spoke, flattened below) with multifunction • Front reading lights (2) • model refinement • MP3 interface for mobile phone / cell phone • Parking Assist System, rear • Wheelbase 2675 mm • Rear View Camera <i>Parkpilotsystem vorn und hinten, Außenspiegel elektr.</i>	• Ambient lighting center console • Anti -lock braking system (ABS) • Audio controls on steering wheel • Bluetooth Audio-Streaming • Brake Assist (HBA) • Roof rails black, high-gloss • Off switch for headlights • Elektron . traction control • Driver assistance system distance warning • • Electric windows front + rear • Windscreen sound-absorbing • LED Taillights • Isofix seats for child seat on front passenger seat • Body 5-door • Head airbag system • Reading lights in the rear • LM rims • • Otto Particle Filter (OPF) • aluminum pedals • Tire Pressure Monitoring System • Low pollutant according to the Euro 6d emissions standard • • Sun visors with mirrors (illuminated) • Socket (12V) port in center console • Exterior door handles body color with chrome insert • USB interface • Sun protection glazing behind darkened (Solar -Protect)

<i>anklappbar</i> • Windscreen wipers with rain sensor • Side airbags • Start / Stop system • LED daytime running lights • Skid plate look, front and rear (Black) • immobilizer • Central locking with remote control	
---	--

special Features	
• Audio navigation system Multimedia Navi Pro (10" display) • Interior leather Alcantara <i>Winter-Paket, Frontscheibe heizbar (ThermaTec), Sitzheizung vorn, Lenkrad heizbar, Rücksitzlehnen umklappbar FlexFold, Ergonomiesitz vorn links, Lendenwirbelstütze Sitz vorn links, elektr. verstellbar, Ergonomiesitz vorn rechts, Lendenwirbelstütze Sitz vorn rechts, elektr. verstellbar</i>	• Driving Assistance System Autonomous Emergency Brake Assist with Front Collision Warning and Pedestrian Detection <i>Fahrassistenz-System: Notbrems-Assistent, Fahrassistenz-System: Frontkollisionswarnung, Fahrassistenz-System: Müdigkeitserkennungs-Sensor, Fahrassistenz-System: aktiver Spurhalteassistent (Lenkunterstützung)</i> • Metallic / mineral effect spraying

We remind you that the data provided were taken from the DAT database. No liability can be assumed for the completeness and correctness.

General examination	
Subfloor Inspection:	not possible A visit to the underside of your vehicle could not be performed. Hoist or lifting means not available .
Mileage plausible:	yes yes
reference:	
Note Road Safe:	

Accident injury assessment	
Rep. Predamages / -height gross:	no detectable As part of a paint film thickness measuring the body outer skin no previous damage could be detected .
Layers of paint thickness measurement:	Within the tolerances At the vehicle , a resist layer thickness measurement was carried out on the body outer skin. The measured values ??were within the tolerances of original finishes . Evidence that points to a repaired accident damage or repainting carried out , were identified.

Existing collision damage:

Not established

On the vehicle body shell were on visual examination found no existing accident damages (other than the usual signs of use) .

reference:

Overview conducted technology audit					
Alternator / Generator:			examined limited	Battery / accumulator:	
			in order		
oil loss:			in order		
air conditioning:			in order	lighting system:	
			in order		
coupling:			unavailable	exhaust System:	
			examined limited		
engine running:			in order	shock absorber:	
			not checked		
transmission:			examined limited		

Performed testing technology	
Alternator / Generator:	The function of the alternator (generator) was tested using the charging indicator light in the instrument cluster .
Battery / accumulator:	The battery (accumulator) was examined during the inspection .
oil loss:	The vehicle was inspected during the visit to an oil leak .
air conditioning:	A function of the air conditioning was found to visiting time .
lighting system:	The lighting system was to tour date in order.
coupling:	The vehicle has no clutch , as it is a Autmatikgetriebe or the like.
exhaust System:	The exhaust system has been tested only restricted during the visit .
engine running:	A field test of the engine was performed.
shock absorber:	The shocks were not examined during the inspection .
transmission:	The transmission could be examined in the context of limited test drive / pull test .
reference:	*

damage



component	Damage	Rep kind
1. Front door - left		Smart repair
2. Rear door - left		Smart repair
3. Felge (Aluminium) hinten rechts	Scratch(es)	Paint

The expert points out that the vehicle in addition to the age- damage listed in the report and may have a high mileage -related wear , as in normal use are inevitable (small bumps , dents , scratches) .

There shall be no liability for any defect and / or remained hidden damage in terms of electronics and mechanics accepted ,r\nand for fraudulent misrepresentation and concealed defects .

photographic record



front Left



front Right



rear Left



rear Right




inside



trunk



instrument cluster



mileage



filler cap



rims



rims




rims



rims



engine compartment



service book



Others



Navigation system



1. Front door - left



1. Front door - left



1. Front door - left



2. Rear door - left



2. Rear door - left



2. Rear door - left



3. Felge (Aluminium) hinten rechts

Scratch(es)



3. Felge (Aluminium) hinten rechts

Scratch(es)