



Expertise

Protocol number: 41668859
Order No. / Reference: 25236850
Inspection date: 17 Sept 2025

Manufacturer: Opel	Model: Insignia Grand Sport 2.0 Diesel Automatik Business Elegance
VIN: W0VZT6EPXM1006904	



Vehicle details	
Manufacturer / Type / Model / Equipment	
Opel Insignia Grand Sport 2.0 Diesel Automatik Business Elegance	
Vehicle Identification number	W0VZT6EPXM1006904
Mileage (Read)	140,108 km
First registration	23 Nov 2020
Number of holders	1
Power / Engine displacement	128 kw / 1,995 ccm
Fuel type / Cylinder	Diesel / 4
Gearbox / Number of gears	Automatic / 8
Type of drive	Front drive
Type of vehicle	Saloon car
Colour / colour code	Chili Rot Metallic
Doors / Seats	5 / 5
Upholstery type	Cloth
Colour of upholstery	Black



Vehicle details

Maintenance booklet / proof	Available / complete	Next maintenance in	85 %
Key is / should be	2 / 2	FZG documents	ZB#2 (B) was available (copy), ZB#1 (S) was not available
		Letter No.	FU021956
Previous damage / Accident	Detectable	Repainting	None detectable
Inspection conditions	sufficient	Lifting equipment / pit	yes
Test drive	Not performed	Engine function test	Performed
Manufacturer key number/ type code number	1844 / AMB 00126		
Emission standard	EURO6;WLTP;AP;PI/CI; M, N1 I	Fine dust sticker	
Permitted total weight	2,220 kg	Empty weight	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	245/45 R18 100Y	Summer tyres on Light alloy	Bridgestone	3mm / 3mm
2)	245/45 R18 100Y	Summer tyres on Light alloy	Bridgestone	3mm / 3mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	225/55 R17 97H	Winter tyres on Light alloy	Continental	5mm / 5mm
2)	225/55 R17 97H	Winter tyres on Light alloy	Continental	5mm / 5mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
N	125/80 R16 97M	Summer tyres on Steel	Continental	4 mm

Legend: Tread depth information for tires on the left is in the first place, for tires on the right is in the second place on the axle in the direction of travel

Equipment

Standard equipment

- | | |
|---|--|
| <ul style="list-style-type: none"> • Storage compartments • Airbag: Head airbag front and rear outside • Ambient lighting • Hill Start Assist • tachometer • Electronic Stabilization Program (ESP - Plus) • Forward collision warning with pedestrian detection and automatic emergency braking • Transmission: 8-speed automatic transmission • Automatic climate control two zones • Headrests, rear (3 pieces) • LED headlights • LED daytime running lights including LED indicators, front and LED taillights • Center armrest, front • Package: Innovations 1 • Parking brake, electric • Upholstery: Monita fabric/premium leather look • Radio: Digital radio reception DAB+ • Radio accessories: 2 USB interfaces • Tire repair kit • Wheels: Light alloy wheels 8.5 J x 18 (multi-spoke) • Keyless locking and starting system Keyless Open & Start • Power steering • Visual equipment • Lane Keeping Assist • Start/Stop system • Traction Control (TC) Plus • Immobiliser • Central locking with radio remote control | <ul style="list-style-type: none"> • Airbag: Front airbags (multi-stage) and side airbags, driver and front passenger • Anti-lock braking system (ABS) • diesel particulate filter • Electronic brake force distribution (EBD) • Electric windows front and rear • Pedestrian protection including active bonnet • Cruise control • Child safety lock in the rear doors, manual • Front headrests • Paintwork: Metallic special color Nautic Blue • LED fog lights • Steering column height/length adjustable • Make-up mirror • Package: Charging • Park & Go with rear view camera, digital • Parking pilot, front and rear parking aid • Quickheat rapid heating system • Radio: Multimedia Navi Pro with 8" touchscreen color display • Tire pressure display • Rear seat backrest with FlexFold function, foldable in a 40:20:40 ratio • Seat belts: Three-point seat belts on all seats • Seats: Ergonomic active seat (AGR) driver and front passenger • Bumpers painted in body color • Pre-installation for ISOFIX child seat retention system • Heat-insulating glazing, green tinted • Ignition key, second, foldable |
|---|--|

Extra equipment

- | | |
|---|---|
| <ul style="list-style-type: none"> • Chassis: FlexRide Premium chassis (innovative chassis system with adaptive driving style recognition and three selectable driving modes: Standard, Sport (customizable), and Tour, including electronic damper control, speed-dependent power steering, and networking of all driving dynamics systems) | <ul style="list-style-type: none"> • Package: Winter 1 (AGR, driver and front passenger) (Seat heating, multi-stage, driver and front passenger - Heated leather steering wheel - Ergonomic active seat (AGR), driver and front passenger (length, height, and backrest angle manually adjustable, seat angle electrically adjustable, lumbar support electropneumatically adjustable in height and length, extendable thigh support manually adjustable, headrest height and angle adjustable)) |
|---|---|



Brief expert findings

Documents submitted	At the time of the inspection, the registration certificate Part 2 (letter) was available, but the registration certificate Part 1 (certificate) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was verified during the inspection by the undersigned.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and a pit were available for examining the vehicle.
Test drive	No test drive/maneuvering was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Equipment	Vehicle key - Non-operational - Perform diagnosis
2	Door - front left side	Door edge - Scratched - Smart repair
3	Sill - left side	Sill - Scratched - Smart repair
4	Mudguard - left side	Mudguard - left side - Dent / paintcoat damage - Smart repair
5	Wheel / tyres	Alloy rim - rear right side (Materialabtrag) - Damaged - Loss in value
6	Wheel / tyres	Alloy rim - front left side (Materialabtrag) - Scratched - Loss in value
7	Wheel / tyres	Alloy rim - front right side (Materialabtrag) - Damaged - Loss in value
8	Wheel / tyres	Tyres - complete set (3 Reifen, nicht fahrbereit) - Porous / cracked - Replace
9	Sill - right side	Sill - Deformed - Repair and paint
10	Rear bumper	Rear bumper - Scratched - Paint
11	Bonnet	Bonnet (Kratzer/Steinschlag) - dent(s) - Repair and paint
12	Door - front right side	Door - Dent / paintcoat damage - Repair and paint

Wear and tear

No.	Component group	Description
1	Door - rear left side	Door edge - Scratched - No deduction
2	Body	Body (oberflächlich) - Scratch(es) - No deduction
3	Vehicle glazing	Rear window - Scratch(es) - No deduction
4	Equipment	Vehicle key - Scratched - No deduction
5	Interior	Interior - Scratch(es) - No deduction
6	Vehicle glazing	Windscreen - Stone chips - No deduction

The vehicle shows signs of wear commensurate with its age and use.

Accident damages

No. Accident

- 1 Front



Order/Scope of order

The order was placed to prepare a sales report for the vehicle described. This includes the following:

- Description of core relevant information about the vehicle
- Documentation of equipment features
(*Delivery by third-party service providers*)
- Documentation of damage, defects, missing parts
- Documentation of previous damage, unrepaired previous damage, repainting
- a brief visual or functional inspection of the equipment details if possible.
(*Functional tests of driver assistance systems are not included in the scope of services!*)
- a photo documentation of the vehicle

Basis for the order

This product is based on the Alphabet Fuhrpark GmbH guidelines for vehicle returns and valuations. The expert makes the explicit findings in each individual case objectively within the framework of the specified standards based on his or her own expertise.

The vehicle inspection takes place in a disassembled state.

Damage or defects that can only be detected during disassembly/diagnosis work or through advanced knowledge remain within the scope of the prognosis risk. An extended risk exists for concealed defects caused by fraudulent deception and not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted according to the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which in their nature and severity slightly exceed normal use but do not constitute unacceptable damage will be documented and identified under signs of use if necessary.

Damage or defects which, according to the underlying standard, can no longer be attributed to normal use or wear and tear are listed in the product under "Depreciating Factors".

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

Non-repaired previous damages were found at the vehicle. The necessary repair costs are listed in the expert report or if necessary, are listed in detail in a separately enclosed repair cost calculation.

Comments

Die beigefügte Reparaturkostenkalkulation wurde nach bestem Wissen und Gewissen unter eingeschränkten Besichtigungsbedingung im demontagefreien Zustand erstellt. Es können aufgrund verdeckter Beschädigung erhebliche Mehrkosten und somit Abweichung der für den Unfall ausgewiesenen Reparaturkosten nicht ausgeschlossen werden.

Die Felgen wurden aufgrund des Alters und der Laufleistung gemindert.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view ([Online link](#))



Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres



Figure 13: Documents




Figure 14: Documents




Figure 15: Documents




Figure 16: Documents




Figure 17: Documents




Figure 18: Documents



Figure 19: Additional tyres




Figure 20: Navigation



Figure 21: Misc.




Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.



Figure 29: Misc.




Figure 30: Misc.




Figure 31: Misc.



Figure 32: Misc.




Figure 33: Misc.



Figure 34: Misc.




Figure 35: Misc.




Figure 36: Misc.




Damage 1: Equipment: Vehicle key - Non-operational - Perform diagnosis



Damage 2: Door - front left side: Door edge - Scratched - Smart repair



Damage 2: Door - front left side: Door edge - Scratched - Smart repair




Damage 3: Sill - left side: Sill - Scratched - Smart repair



Damage 3: Sill - left side: Sill - Scratched - Smart repair




Damage 4: Mudguard - left side: Mudguard - left side - Dent / paintcoat damage - Smart repair



Damage 4: Mudguard - left side: Mudguard - left side - Dent / paintcoat damage - Smart repair



Damage 4: Mudguard - left side: Mudguard - left side - Dent / paintcoat damage - Smart repair



Damage 5: Wheel / tyres: Alloy rim - rear right side (Materialabtrag) - Damaged - Loss in value



Damage 5: Wheel / tyres: Alloy rim - rear right side (Materialabtrag) - Damaged - Loss in value



Damage 5: Wheel / tyres: Alloy rim - rear right side (Materialabtrag) - Damaged - Loss in value



Damage 6: Wheel / tyres: Alloy rim - front left side (Materialabtrag) - Scratched - Loss in value



Damage 6: Wheel / tyres: Alloy rim - front left side (Materialabtrag) - Scratched - Loss in value



Damage 6: Wheel / tyres: Alloy rim - front left side (Materialabtrag) - Scratched - Loss in value



Damage 7: Wheel / tyres: Alloy rim - front right side (Materialabtrag) - Damaged - Loss in value



Damage 7: Wheel / tyres: Alloy rim - front right side (Materialabtrag) - Damaged - Loss in value



Damage 7: Wheel / tyres: Alloy rim - front right side (Materialabtrag) - Damaged - Loss in value



Damage 7: Wheel / tyres: Alloy rim - front right side (Materialabtrag) - Damaged - Loss in value



Damage 7: Wheel / tyres: Alloy rim - front right side (Materialabtrag) - Damaged - Loss in value



Damage 8: Wheel / tyres: Tyres - complete set (3 Reifen, nicht fahrbereit) - Porous / cracked - Replace



Damage 8: Wheel / tyres: Tyres - complete set (3 Reifen, nicht fahrbereit) - Porous / cracked - Replace



Damage 8: Wheel / tyres: Tyres - complete set (3 Reifen, nicht fahrbereit) - Porous / cracked - Replace




Damage 8: Wheel / tyres: Tyres - complete set (3 Reifen, nicht fahrbereit) - Porous / cracked - Replace




Damage 8: Wheel / tyres: Tyres - complete set (3 Reifen, nicht fahrbereit) - Porous / cracked - Replace




Damage 8: Wheel / tyres: Tyres - complete set (3 Reifen, nicht fahrbereit)
- Porous / cracked - Replace



Damage 9: Sill - right side: Sill - Deformed - Repair and paint




Damage 9: Sill - right side: Sill - Deformed - Repair and paint



Damage 9: Sill - right side: Sill - Deformed - Repair and paint



Damage 9: Sill - right side: Sill - Deformed - Repair and paint




Damage 9: Sill - right side: Sill - Deformed - Repair and paint



Damage 10: Rear bumper: Rear bumper - Scratched - Paint




Damage 10: Rear bumper: Rear bumper - Scratched - Paint



Damage 10: Rear bumper: Rear bumper - Scratched - Paint



Damage 11: Bonnet: Bonnet (Kratzer/Steinschlag) - dent(s) - Repair and paint




Damage 11: Bonnet: Bonnet (Kratzer/Steinschlag) - dent(s) - Repair and paint




Damage 11: Bonnet: Bonnet (Kratzer/Steinschlag) - dent(s) - Repair and paint




Damage 11: Bonnet: Bonnet (Kratzer/Steinschlag) - dent(s) - Repair and paint




Damage 11: Bonnet: Bonnet (Kratzer/Steinschlag) - dent(s) - Repair and paint




Damage 11: Bonnet: Bonnet (Kratzer/Steinschlag) - dent(s) - Repair and paint




Damage 11: Bonnet: Bonnet (Kratzer/Steinschlag) - dent(s) - Repair and paint



Damage 11: Bonnet: Bonnet (Kratzer/Steinschlag) - dent(s) - Repair and paint



Damage 12: Door - front right side: Door - Dent / paintcoat damage - Repair and paint




Damage 12: Door - front right side: Door - Dent / paintcoat damage - Repair and paint




Damage 12: Door - front right side: Door - Dent / paintcoat damage - Repair and paint




Wear and tear 6: Vehicle glazing: Windscreen - Stone chips - No deduction




Accident 1: Front



Accident 1: Front




Accident 1: Front




Accident 1: Front



Accident 1: Front




Accident 1: Front



Accident 1: Front



Accident 1: Front




Accident 1: Front




Accident 1: Front




Accident 1: Front




Accident 1: Front



Accident 1: Front



Accident 1: Front



Accident 1: Front