



Expertise

Protocol number: 41378971
Order No. / Reference: 25193247
Inspection date: 4 Sept 2025

Manufacturer: Opel	Model: Insignia Grand Sport 2.0 Diesel Automatik Business Elegance
VIN: W0VZT6GPXM1017379	



Vehicle details	
Manufacturer / Type / Model / Equipment	
Opel Insignia Grand Sport 2.0 Diesel Automatik Business Elegance	
Vehicle Identification number	W0VZT6GPXM1017379
Mileage (Read)	92,943 km
First registration	27 Jul 2021
Number of holders	1
Power / Engine displacement	128 kw / 1,995 ccm
Fuel type / Cylinder	Diesel / 4
Gearbox / Number of gears	Automatic / 8
Type of drive	Front drive
Type of vehicle	Saloon car
Colour / colour code	Onyx Black Metallic
Doors / Seats	5 / 5
Upholstery type	Cloth / leather combination
Colour of upholstery	Black



Vehicle details

Maintenance booklet / proof	digital proof / complete	Next maintenance in	29 %
Last maintenance on / at	12/2024 at 79,656 km		
Key is / should be	2 / 2	FZG documents	ZB#2 (B) was available (copy), ZB#1 (S) was not available
		Letter No.	GA202491
Previous damage / Accident	Detectable	Repainting	Detectable
Inspection conditions	sufficient	Lifting equipment / pit	yes
Test drive	Not performed	Engine function test	Performed
Manufacturer key number/ type code number	1844 / AMB 00126		
Emission standard	EURO6;WLTP;AP;PI/CI; M, N1 I	Fine dust sticker	
Permitted total weight	2,220 kg	Empty weight	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	225/55 R17 101V	Winter tyres on Light alloy	Goodyear	6mm / 6mm
2)	225/55 R17 101V	Winter tyres on Light alloy	Goodyear	7mm / 7mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	245/45 R18 100Y	Summer tyres on Light alloy	Bridgestone	3mm / 3mm
2)	245/45 R18 100Y	Summer tyres on Light alloy	Bridgestone	4mm / 4mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 04/2026		

Legend: Tread depth information for tires on the left is in the first place, for tires on the right is in the second place on the axle in the direction of travel



Equipment

Standard equipment

- Storage compartments
- Airbag: Head airbag front and rear outside
- Ambient lighting
- Exterior mirrors for driver and passenger side electrically adjustable and heated
- diesel particulate filter
- Electronic brake force distribution (EBD)
- Electric windows front and rear
- Pedestrian protection including active bonnet
- Cruise control
- Child safety lock in the rear doors, manual
- Front headrests
- LED headlights
- LED daytime running lights including LED indicators, front and LED taillights
- Center armrest, front
- Package: Innovations 1
- Parking brake, electric
- Upholstery: Monita fabric/premium leather look
- Radio: Digital radio reception DAB+
- Radio accessories: 2 USB interfaces
- Tire repair kit
- Wheels: Light alloy wheels 8.5 J x 18 (multi-spoke)
- Keyless locking and starting system Keyless Open & Start
- Power steering
- Visual equipment
- Lane Keeping Assist
- Start/Stop system
- Traction Control (TC) Plus
- Immobiliser
- Ignition key, second, foldable
- Airbag: Front airbags (multi-stage) and side airbags, driver and front passenger
- Anti-lock braking system (ABS)
- Hill Start Assist
- Brake light, third
- tachometer
- Electronic Stabilization Program (ESP - Plus)
- Forward collision warning with pedestrian detection and automatic emergency braking
- Transmission: 8-speed automatic transmission
- Automatic climate control two zones
- Headrests, rear (3 pieces)
- LED fog lights
- Steering column height/length adjustable
- Make-up mirrors in both sun visors, illuminated
- Package: Charging
- Park & Go with rear view camera, digital
- Parking pilot, front and rear parking aid
- Quickheat rapid heating system
- Radio: Multimedia Navi Pro with 8" touchscreen color display
- Tire pressure display
- Rear seat backrest with FlexFold function, foldable in a 40:20:40 ratio
- Seat belts: Three-point seat belts on all seats
- Seats: Ergonomic active seat (AGR) driver and front passenger
- Bumpers painted in body color
- Pre-installation for ISOFIX child seat retention system
- Central locking with radio remote control

Extra equipment

- Airbag: Side airbags, rear outer (rear seat belt warning for unfastened seat belts (child seat attachment system remains activated))
- Paint finish: metallic
- Solar Protect heat-insulating glazing (in the rear, heavily tinted)
- Winter package
- Package: Innovations 2 (automatic transmission) (Head-Up Display - Adaptive Cruise Control (3rd Generation), Stop & Go function - Forward Collision Warning with Pedestrian Detection and Automatic Emergency Braking, active from 4 km/h, range 150 m. If there is a risk of collision, the braking system is prepared and emergency braking / automatic emergency braking is initiated if necessary - Lane Keeping Assist - Distance Indicator - Keyless Locking and Starting System Keyless Open & Start)



Brief expert findings

Documents submitted	At the time of the inspection, the registration certificate Part 2 (letter) was available, but the registration certificate Part 1 (certificate) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was verified during the inspection by the undersigned.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and a pit were available for examining the vehicle.
Test drive	No test drive/maneuvering was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Front bumper	Front bumper - Scratch(es) - Smart repair
2	Instrument panel	Air nozzle - centre - Damaged - Replace
3	Boot lid / rear door	Boot lid - dent(s) - Smart repair
4	2nd wheel set	1 alloy rim (Materialabtrag) - Scratched - Replace
5	2nd wheel set	1 alloy rim (Materialabtrag) - Scratched - Replace
6	Side panel - rear right side	Side panel (Staubkorn und wellig) - Unprofessionally repaired - Paint
7	Sill - right side	Sill - Deformed - Repair and paint
8	Door - rear left side	Door - Deformed - Repair and paint
9	Bonnet	Bonnet (Anätzung+Dellen/Steinschläge) - Paint defect - Repair and paint

Wear and tear

No.	Component group	Description
1	Trim / covers	Boot lid - interior trim - Scratch(es) - No deduction
2	Door - front right side	Door - dent(s) - No deduction
3	Vehicle glazing	Windscreen - Stone chips - No deduction
4	Rear bumper	Rear bumper - Scratch(es) - No deduction
5	2nd wheel set	1 alloy rim - Scratch(es) - No deduction
6	Side panel - rear left side	Side panel - dent(s) - No deduction

The vehicle shows signs of wear commensurate with its age and use.

Previous damages

No.	Previous damage	Extent of damage (Net)
1	Front, Side right, Provided by user / customer, from 8 Jun 2023	4.757,09 €

Repainting

No.	Repainting
1	Mudguard - right side, Door - rear right side, Door - front right side, Professionally carried out, Invoice of repair done Non-existent
2	Side panel - rear right side, Unprofessionally carried out, Invoice of repair done Non-existent

Paint coat thickness measurement

Mudguard - right side	159 µm	Side panel - rear right side	1,510 µm
Door - rear right side	350 µm	Door - front right side	191 µm



Order/Scope of order

The order was placed to prepare a sales report for the vehicle described. This includes the following:

- Description of core relevant information about the vehicle
- Documentation of equipment features
(Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of previous damage, unrepaired previous damage, repainting
- a brief visual or functional inspection of the equipment details if possible.
(Functional tests of driver assistance systems are not included in the scope of services!)
- a photo documentation of the vehicle

Basis for the order

This product is based on the Alphabet Fuhrpark GmbH guidelines for vehicle returns and valuations. The expert makes the explicit findings in each individual case objectively within the framework of the specified standards based on his or her own expertise.

The vehicle inspection takes place in a disassembled state.

Damage or defects that can only be detected during disassembly/diagnosis work or through advanced knowledge remain within the scope of the prognosis risk. An extended risk exists for concealed defects caused by fraudulent deception and not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted according to the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which in their nature and severity slightly exceed normal use but do not constitute unacceptable damage will be documented and identified under signs of use if necessary.

Damage or defects which, according to the underlying standard, can no longer be attributed to normal use or wear and tear are listed in the product under "Depreciating Factors".

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

According to available information previous damages were repaired at the vehicle. Traces of repairs, which allow conclusions about the area of repair, were not recognizable during the inspection.

Comments

- Winterradsatz ist kein Bestandteil des Auslieferumfangs



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: interior 360° view



Figure 10: Cargo area




Figure 11: VIN



Figure 12: Mounted tyres




Figure 13: Documents



Figure 14: Documents




Figure 15: Documents



Figure 16: Additional tyres




Figure 17: Navigation



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.





Figure 24: Misc.




Damage 1: Front bumper: Front bumper - Scratch(es) - Smart repair




Damage 1: Front bumper: Front bumper - Scratch(es) - Smart repair



Damage 2: Instrument panel: Air nozzle - centre - Damaged - Replace



Damage 2: Instrument panel: Air nozzle - centre - Damaged - Replace



Damage 3: Boot lid / rear door: Boot lid - dent(s) - Smart repair



Damage 3: Boot lid / rear door: Boot lid - dent(s) - Smart repair



Damage 3: Boot lid / rear door: Boot lid - dent(s) - Smart repair



Damage 4: 2nd wheel set: 1 alloy rim (Materialabtrag) - Scratched - Replace



Damage 4: 2nd wheel set: 1 alloy rim (Materialabtrag) - Scratched - Replace



Damage 4: 2nd wheel set: 1 alloy rim (Materialabtrag) - Scratched - Replace



Damage 4: 2nd wheel set: 1 alloy rim (Materialabtrag) - Scratched - Replace



Damage 5: 2nd wheel set: 1 alloy rim (Materialabtrag) - Scratched - Replace



Damage 5: 2nd wheel set: 1 alloy rim (Materialabtrag) - Scratched - Replace



Damage 6: Side panel - rear right side: Side panel (Staubkorn und wellig) - Unprofessionally repaired - Paint



Damage 6: Side panel - rear right side: Side panel (Staubkorn und wellig) - Unprofessionally repaired - Paint



Damage 6: Side panel - rear right side: Side panel (Staubkorn und wellig) - Unprofessionally repaired - Paint



Damage 6: Side panel - rear right side: Side panel (Staubkorn und wellig) - Unprofessionally repaired - Paint



Damage 7: Sill - right side: Sill - Deformed - Repair and paint



Damage 7: Sill - right side: Sill - Deformed - Repair and paint




Damage 7: Sill - right side: Sill - Deformed - Repair and paint




Damage 7: Sill - right side: Sill - Deformed - Repair and paint



Damage 8: Door - rear left side: Door - Deformed - Repair and paint



Damage 8: Door - rear left side: Door - Deformed - Repair and paint



Damage 8: Door - rear left side: Door - Deformed - Repair and paint



Damage 8: Door - rear left side: Door - Deformed - Repair and paint



Damage 9: Bonnet: Bonnet (Anätzung+Dellen/Steinschläge) - Paint defect - Repair and paint



Damage 9: Bonnet: Bonnet (Anätzung+Dellen/Steinschläge) - Paint defect - Repair and paint



Damage 9: Bonnet: Bonnet (Anätzung+Dellen/Steinschläge) - Paint defect - Repair and paint



Damage 9: Bonnet: Bonnet (Anätzung+Dellen/Steinschläge) - Paint defect - Repair and paint




Damage 9: Bonnet: Bonnet (Anätzung+Dellen/Steinschläge) - Paint defect - Repair and paint



Damage 9: Bonnet: Bonnet (Anätzung+Dellen/Steinschläge) - Paint defect - Repair and paint



Damage 9: Bonnet: Bonnet (Anätzung+Dellen/Steinschläge) - Paint defect - Repair and paint



Damage 9: Bonnet: Bonnet (Anätzung+Dellen/Steinschläge) - Paint defect - Repair and paint




Wear and tear 5: 2nd wheel set: 1 alloy rim - Scratch(es) - No deduction



Wear and tear 5: 2nd wheel set: 1 alloy rim - Scratch(es) - No deduction



Wear and tear 6: Side panel - rear left side: Side panel - dent(s) - No deduction



Wear and tear 6: Side panel - rear left side: Side panel - dent(s) - No deduction



Repainting 1: Mudguard - right side, Door - rear right side, Door - front right side



Repainting 1: Mudguard - right side, Door - rear right side, Door - front right side



Repainting 1: Mudguard - right side, Door - rear right side, Door - front right side



Repainting 1: Mudguard - right side, Door - rear right side, Door - front right side



Repainting 1: Mudguard - right side, Door - rear right side, Door - front right side



Repainting 1: Mudguard - right side, Door - rear right side, Door - front right side



Repainting 2: Side panel - rear right side



Repainting 2: Side panel - rear right side



Wartungshistorie

(gemäß Auftraggeber Informationen)

Fahrgestellnummer: W0VZT6GPXM1017379

Hersteller / Modell: OPEL OPEL Insignia Grand Sport 2.0 Diesel Automatik Business Elegance

Datum	KM-Stand	Beschreibung
20.12.2024	79.656	AU; Bremse Sonstiges; Bremsklötze hinten; Bremsklötze vorne; Bremsscheiben hinten; Bremsscheiben vorne; HU + AU; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges
19.09.2023	58.205	Bremsflüssigkeit; Bremsflüssigkeit ern; Kraftstofffilter ern; Luftfiltereinsatz ern; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges
12.07.2022	29.424	Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges