


Vehicle details

VIN	W0VZT8EBX L1013415	Brand	OPEL	Maintenance date	-
Licence Plate	H2-52-FK	Model	Insignia Sports Tour 1.5 Turbo 121kW S;S Business	Maintenance mileage	-
Registration date	13/01/2020	Year	2020	Exterior Color	Black Metallic
Odometer	126 642 km	Engine size	1490	interior Color	Black
Fuel	Petrol	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Manual	CO2	-
Doors	5	Gears	6		

Inspection Details

Inspection date	13/01/2025	Inspection loc.	Dekra Ayvens
-----------------	------------	-----------------	--------------



Generic equipment

Automated air-conditioning	✓
Cruise control	✓
GPS system	✓
Alloy wheel rims	✓
Metallic paint	✓
Central locking	✓
Electric windows	✓
Mixed upholstery	✓
Side rails	✓
Park Distance Control	✓
Audio System	✓

Removable element


Spare wheel kit	✓
Load cover	✓

Technical Document

User manual	✓
Warranty booklet	✓
Spare key	✓
Remote key	✓
Sat Nav CD ROM Software	✓

Tyres

Winter kit



Exterior

1		Part Position Damages Severity Repair mode	Wing Front left Dent & Chips Diameter (mm) > 20 Repair	2		Part Position Damages Severity Repair mode	Door Front left Scratched Length (cm) > 10 Repair
3		Part Position Damages Severity Repair mode	Door Back left Scratched Length (cm) > 10 Repair	4		Part Position Damages Severity Repair mode	Wing Back left Scratched Length (cm) > 10 Repair
5		Part Position Damages Severity Repair mode	Bumper Back Scratched Length (cm) > 10 Repair	6		Part Position Damages Severity Repair mode	Wing Back right Scratched Length (cm) > 10 Repair
7		Part Position Damages Severity Repair mode	Door Back right Dent & Chips Diameter (mm) > 20 Repair	8		Part Position Damages Severity Repair mode	Door Front right Scratched Length (cm) > 10 Repair
9		Part Position Damages Severity Repair mode	Bumper Front right Scratched Length (cm) > 10 Repair	10		Part Position Damages Severity Repair mode	Spoiler Front Scratched Length (cm) > 10 Repair
11		Part Position Damages Severity Repair mode	Bonnet - Dent & Chips Diameter (mm) > 20 Repair	12		Part Position Damages Severity Repair mode	Roof - Dent & Chips Diameter (mm) > 20 Repair
13		Part Position Damages Severity Repair mode	Roof wind deflector Back Chemical deposit - Lumpsum repair	14		Part Position Damages Severity Repair mode	Exterior door mirror shell Front right Scratched Length (cm) > 10 Repair