

Hüsges Gruppe®
Die Gutachter

status report

customer: Opel Grosskunden/FSL/Free2Move
contract number:
reference:

vehicle data

Opel Insignia B Sports Tourer Ultimate

Vehicle identification number	W0VZT8EF5L1026639	mileage read:	44017 km
First Registration / construction year:	30.06.2020 / 2019	Visit Date / place of birth:	17.02.2025 Heidenheim
Bodywork:	cars	Re - import:	unknown
Body type:	hatchback	KBA no. :	1844//AHR
Fuel / emission class:	diesel / € 6	transmission type:	automatic
Displacement / power:	1598 ccm / 100 kW (136 PS)	Engine:	front-wheel drive
paint:	SchneeWeiss/SummitWhite /Arctic	Number of previous owners:	1
Doors / seats:	5 / 5	number keys:	2
Next HU / AU:	- / -	cushion type:	Imitation leather / fabric
Service book available:	yes	Interior Color:	black
smoking vehicle:	no	Last service km / on the:	43988 / 17.09.2024
Vehicle roadworthy:	yes	Vehicle roadworthy:	yes
Submitted vehicle documents:	-	state outside:	3 - Average
visit condition:	in the parking garage	condition inside:	3 - Average
state general:	3 - Average		

Accessories (presented to the visiting time)

GPS sat nav disk:	Fzg.Schlüssel:	Service book provided /	Last service at / on:
Hard Disk Drive	2	maintained:	43988 / 17.09.2024
		yes / -	
☒ AHK key	☒ AHK removable	☒ AHK fixed	☒ AHK swivel
☒ Fernbed . entertainment	☒ Fernbed . Auxiliary heating	☒ headphone	☒ LED headlights
☒ Load compartment cover	☒ navigation system	☒ Persenning	☒ partition net
☒ Wind Deflector	☒ Xenon headlights		

☒ **available**

☒ **not available**

Hüsges GmbH
Ein Unternehmen der Hüsges Gruppe
Bankverbindung
Sparkasse Krefeld
Kto.-Nr. 1048206 · BLZ 320 500 00

Gießerallee 23
47877 Willich
Tel.: 02154 / 9534 0
Fax: 02154 / 9534 1025
Email:
info@huesges-gruppe.de



Rechtsform: Gesellschaft
mit beschränkter Haftung
Sitz: Willich
Registergericht: Krefeld HRB
Steuer-Nr.: 102/5821/0943

Geschäftsführung:
Arndt Hüsges
Dipl.- Ing. (FH) Bernd Hüsges

The status report was created impartially and to the best of my knowledge. The images listed in the status report are part of the vehicle description regarding the equipment and the vehicle condition.



Hüsges Gruppe®
Die Gutachter



mounted tires		
Tyre / wheel type:	summer tires	polished aluminum
1st axis - Left / states .	Bridgestone	245/45/R18/100Y 4 mm
1st axis - right / states .	Bridgestone	245/45/R18/100Y 4 mm
2nd axis - Left / states .	Bridgestone	245/45/R18/100Y 5 mm
2nd axis - right / states .	Bridgestone	245/45/R18/100Y 5 mm
traffic Safety:	roadworthy	
spare wheel:	-	
state spare wheel:	-	

standard equipment	
• 3-point rear center seat belt • Adaptive cruise control system (cruise control) Autonomous emergency brake assist and front camera <i>Fahrassistenz-System: Abstandswarner</i> • Alcantara package <i>Seitenairbag hinten, Mittelarmlehne hinten, Rücksitzlehne geteilt (40:20:40), Innenausstattung: Leder Alcantara</i> • Anti -lock braking system (ABS) • Audio Navigation System Multimedia Navi Pro <i>DAB-Tuner (Radioempfang digital)</i> • Equipment package GS Line Interior <i>Pedale Aluminium, Dachhimmel schwarz, Vorrüstung Sicherheitsnetz hinter Vordersitze, Lenkrad heizbar, Lenkrad (Sport/Leder) OPC-Line, Lenkrad mit Schaltwippen/-tasten</i> • Body color door mirrors / black high-gloss • Bluetooth Audio-Streaming • Rev counter • Door sills with lettering • Elektron . traction control • Ergonomics front right seat • Driver assistance system Traffic sign recognition • Electric windows front • • Pedestrian protection system Active hood • Transmission automatic - with start / stop (6-speed) • Rear wiper with intermittent • Interior trim finishers Brushed Ice • Body 5-door • 2-zone automatic climate control <i>Luftfeuchtesensor</i>	• Storage box / storage space in the luggage compartment • Airbag driver / passenger side • Ambient lighting dashboard • Drive Front Wheel Drive • Audio controls on steering wheel • Mirrors and electric folding . adjustable and heated • B-pillars black high gloss (outside) • Brake Assist (HBA) • Easy Access-Paket <i>Ladekantenschutz (Chrom / Edelstahl), Heckklappenöffnung elektrisch, Schließ-/Startsystem Keyless Open</i> • Elektron . Stability Program Plus (ESP) <i>Elektron. Stabilitäts-Programm (ESP)</i> • Ergonomics front left seat <i>Lendenwirbelstütze Sitz vorn links, elektr. verstellbar</i> • Driving Assistance System Hill Start Assist (HSA , Hill Start Assist) • Power windows rear • Parking brake electrically • front camera <i>Fahrassistenz-System: Abstandswarner, Fahrassistenz-System: Notbrems-Assistent, Fahrassistenz-System: Frontkollisionswarnung, Fahrassistenz-System: Fußgängererkennung, Fahrassistenz-System: Spurhalteassistent</i> • Cruise control system (cruise control) • LED Taillights • • Isofix admissions for child seat in back seat • childlock

• Rear headrests (3- fold) • LM rims • MP3 interface for mobile phone / cell phone • Tires 245/45 R18 ..W • RuÃpartikelfilter • Visibility Package <i>Einschaltautomatik fr Fahrlicht, Fahrassistenz-System: Fernlichtassistent, Scheibenwischer mit Regensensor, Innenspiegel mit Abblendautomatik</i> • Sun visors with mirrors (illuminated) • Socket (12V) port in the trunk / cargo area • • <i>Leuchtweitenregelung automatisch, Fahrassistenz-System: Fernlichtassistent, Abbiegelicht</i> • Sun protection glazing behind darkened (Solar -Protect)	• Head airbag system • Radiator grille with chrome frame • Engine 1.6 ltr. - 100 kW CDTI DPF • Park Pilot system, front and rear • Tire pressure Warner • Side airbags • Smartphone interface (Apple CarPlay & Android Auto) • Start / Stop system • LED daytime running lights • Exterior body color door handles • immobilizer • Central locking with remote control
---	--

special Features	
• <i>USB-Schnittstelle hinten (2-fach), Steckdose (12V-Anschlu) im Koffer-/Laderaum, Induktionsladeschale fr Smartphone (Wireless Charging)</i> • Exclusive-Paket <i>Einstiegsleisten mit Schriftzug beleuchtet, Nebelscheinwerfer, Wrmeschutzverglasung hinten abgedunkelt (Solar-Protect), Lenkrad (Sport/Leder) OPC-Line</i> • Flexx package (Flex - Organizer) • Heated front seats • Technology package Park & Go Premium <i>Auenspiegel elektr. anklappbar, Auenspiegel elektr. verstell-, heiz- und anklappbar, mit Abblendautomatik, Parkpilotsystem vorn und hinten, Rckfahrkamera, Kamerasystem 360°, Fahrassistenz-System: Querverkehrs-Assistent Heck (Rckfahr-Assistent), Fahrassistenz-System: Totwinkel-Assistent, Fahrassistenz-System: Spurhalteassistent</i>	• Electrical Fast heating (Quickheat) • Color display (8.0 inches) • Innovations Package 2 <i>Head-up-Display, Adaptive Geschwindigkeits-Regelanlage (Tempomat) Autonomer Notbrems-Assistent und Frontkamera, Fahrassistenz-System: Abstandswarner</i> • Special varnishing snow-white • Winter Package 2 <i>Frontscheibe heizbar (ThermaTec)</i>

We remind you that the data provided were taken from the DAT database. No liability can be assumed for the completeness and correctness.

General examination	
Subfloor Inspection:	Conducted limited To investigate the vehicle ( . Lift o .) Were not lifting means even a ramp or pit

available. For this reason, a visit to the vehicle's underside was limited.

Mileage plausible: **yes**
 yes

reference:

Note Road Safe:

Accident injury assessment

Rep. Predamages / -height gross: **Expertly repaired**

On a vehicle coating thickness measurement on the body outer skin were noted repaired previous damage in the frames that were repaired and apparently without disassembly of components without residual traces accident . If there is an impairment of the observed accident before it was taken into account in if conducted vehicle valuation.

Layers of paint thickness measurement: **Out of tolerance**

At the vehicle , a resist layer thickness measurement was carried out on the body outer skin. The measured values ??were outside the tolerances of original finishes .

Existing collision damage: **Not established**

On the vehicle body shell were on visual examination found no existing accident damages (other than the usual signs of use) .

reference:

Overview conducted technology audit					
Alternator / Generator:			examined limited	Battery / accumulator:	
			examined limited		
oil loss:			examined limited		
air conditioning:			not possible	lighting system:	
			unavailable		
engine running:			examined limited		
transmission:			examined limited		
					

Performed testing technology	
Alternator / Generator:	The function of the alternator (generator) was tested using the charging indicator light in the instrument cluster .
Battery / accumulator:	The battery (accumulator) could be considered limited during the visit .
oil loss:	The vehicle could be checked only limited to oil leaks .
air conditioning:	The air conditioning could not be checked during the inspection . **Due to weather conditions not possible examination.
lighting system:	The Lichtanlage could be considered limited to the tour date .
coupling:	The vehicle has no clutch , as it is a Automatikgetriebe or the like.
exhaust System:	The exhaust system has been tested only restricted during the visit .
engine running:	Checking the engine running was limited. Here no audible or visual abnormalities were noted .
shock absorber:	The shock absorber could be tested only restricted during the visit .
transmission:	The transmission could be examined in the context of limited test drive / pull test .
reference:	*Fahrzeug war zum Zeitpunkt der Begutachtung Verschmutzt/Nass/Vereist/Zugeparkt oder wurde bei unzureichender bzw schlechter Beleuchtung Besichtigt.Manche Bereiche waren unter Umständen verdeckt oder Zugebaut. Unter Umständen waren nicht alle Fahrzeugsysteme und Ausstattungen prüfbar. Versteckte Schäden, weitere Schäden oder Schadenserweiterungen möglich. Es ist unklar ob Fahrzeug einen zweiten Radsatz besitzt. Prüfung nicht möglich. Weitere Schäden möglich.

damage



component	Damage	Rep kind
1. tailgate	Subsequently painted	acceptable
2. Sidewall - Rear - Left		Smart repair
3. rear window	Scratch(es)	Replace

The expert points out that the vehicle in addition to the age- damage listed in the report and may have a high mileage -related wear , as in normal use are inevitable (small bumps , dents , scratches) .

There shall be no liability for any defect and / or remained hidden damage in terms of electronics and mechanics accepted ,r\nand for fraudulent misrepresentation and concealed defects .

photographic record



front Left



front Right



rear Left



rear Right



inside



trunk



instrument cluster



mileage



filler cap



rims




rims




rims




rims




engine compartment



service book



Others



Navigation system




1. tailgate

Subsequently painted



2. Sidewall - Rear - Left



2. Sidewall - Rear - Left



2. Sidewall - Rear - Left



3. rear window

Scratch(es)