



status report

customer: Bank 11, Neuss
contract number: 776973330
reference:

vehicle data

Opel Insignia B Sports Tourer Business Elegance

Vehicle identification number	W0VZT8EN5M1009834	mileage read:	91350 km
First Registration / construction year:	27.11.2020 / 2020	Visit Date / place of birth:	13.05.2025 Dorfmark
Bodywork:	cars	Re - import:	no
Body type:	hatchback	KBA no. :	1844//AME
Fuel / emission class:	diesel / € 6	transmission type:	automatic
Displacement / power:	1496 ccm / 90 kW (122 PS)	Engine:	front-wheel drive
paint:	black	Number of previous owners:	Unbekannt
Doors / seats:	5 / 5	number keys:	2
Next HU / AU:	05.2026 / 05.2026	cushion type:	Imitation leather / fabric
Service book available:	yes	Interior Color:	Multicolor
smoking vehicle:	yes	Last service km / on the:	90807 / 23.04.2025
Vehicle roadworthy:	yes	Vehicle roadworthy:	no
Submitted vehicle documents:	For example, I (Fzg.Schein)	state outside:	3 - Average
visit condition:	-	condition inside:	3 - Average
state general:	3 - Average		

Accessories (presented to the visiting time)

GPS sat nav disk:	Fzg.Schlüssel:	Service book provided / maintained:	Last service at / on:
SD Card	2	yes / -	90807 / 23.04.2025

☒ AHK key	☒ AHK removable	☒ AHK fixed	☒ AHK swivel
☒ Fernbed . entertainment	☒ Fernbed . Auxiliary heating	☒ headphone	☒ LED headlights
☒ Load compartment cover	☒ navigation system	☒ Persenning	☒ partition net
☒ Wind Deflector	☒ Xenon headlights		

☒ **available** ☒ **not available**

Hüsges GmbH
Gießerallee 23
47877 Willich
Tel.: 02154 / 9534 0
E-Mail: gutachten@huesges-group.eu

The status report was created impartially and to the best of my knowledge. The images listed in the status report are part of the vehicle description regarding the equipment and the vehicle condition.



Hüsges Gruppe®
Die Gutachter



mounted tires		
Tyre / wheel type:	Winter tires	aluminum
1st axis - Left / states .	Michelin	225/55/R17/97H 2 mm
1st axis - right / states .	Michelin	225/55/R17/97H 2 mm
2nd axis - Left / states .	Nokian	225/55/R17/97H 6 mm
2nd axis - right / states .	Nokian	225/55/R17/97H 6 mm
traffic Safety:	not roadworthy	
spare wheel:	-	
state spare wheel:	-	

standard equipment	
• 3-point rear center seat belt • Ambient lighting dashboard • Drive Front Wheel Drive • Mirrors and electric folding . adjustable and heated • B-pillars black high gloss (outside) • Brake Assist (HBA) • Roof, design execution • Rev counter • Door sills with lettering • Elektron . Stability Program Plus (ESP) <i>Elektron. Stabilitäts-Programm (ESP)</i> • Ergonomics front left seat <i>Lendenwirbelstütze Sitz vorn links, elektr. verstellbar</i> • Driving Assistance System Hill Start Assist (HSA , Hill Start Assist) • Color display (8.0 inches) • Electric windows front • • Pedestrian protection system Active hood • Transmission automatic - with start / stop (8-speed) • Rear wiper with intermittent • Isofix admissions for child seat in back seat • childlock • Head airbag system • Radiator grille with chrome frame • LM rims • Engine 1.5 Ltr. - 90 kW CDTI DPF CAT • Fog lights LED • Tire pressure Warner • Low pollutant according to the Euro 6d emissions standard	• Airbag driver / passenger side • Anti -lock braking system (ABS) • Audio Navigation System Multimedia Navi Pro <i>DAB-Tuner (Radioempfang digital)</i> • Body color door mirrors / black high-gloss • Bluetooth Audio-Streaming • <i>USB-Schnittstelle hinten (2-fach), Steckdose (12V-Anschluß) im Koffer-/Laderaum, Induktionsladeschale für Smartphone (Wireless Charging)</i> • Roof rails (silver) • Easy Access-Paket <i>Ladekantenschutz (Chrom / Edelstahl), Heckklappenöffnung elektrisch, Schließ-/Startsystem Keyless Open</i> • Electrical Fast heating (Quickheat) • Elektron . traction control • Ergonomics front right seat • Driver assistance system Traffic sign recognition • Power windows rear • Parking brake electrically • front camera <i>Fahrassistentz-System: Abstandswarner, Fahrassistentz-System: Notbrems-Assistent, Fahrassistentz-System: Frontkollisionswarnung, Fahrassistentz-System: Fußgängererkennung, Fahrassistentz-System: Spurhalteassistent</i> • Cruise control system (cruise control) • LED Taillights • Interior decoration trim hexagon • Body 5-door • 2-zone automatic climate control <i>Luftfeuchtesensor</i>

• Visibility Package <i>Einschaltautomatik für Fahrlicht, Fahrassistenten-System: Fernlichtassistent, Scheibenwischer mit Regensensor, Innenspiegel mit Abblendautomatik</i> • Smartphone interface (Apple CarPlay & Android Auto) • Start / Stop system • Technology Package Park & Go <i>Rückfahrkamera (digital), Fahrassistenten-System: Querverkehrs-Assistent Heck (Rückfahr-Assistent), Fahrassistenten-System: Totwinkel-Assistent</i> • <i>Leuchtweitenregelung automatisch, Fahrassistenten-System: Fernlichtassistent, Abbiegelicht</i> • Central locking with remote control	• Rear headrests (3- fold) • Steering wheel (leather 3-spoke) <i>Audiobedienung am Lenkrad</i> • model refinement • MP3 interface for mobile phone / cell phone • Park Pilot system, front and rear • Rußpartikelfilter • Side airbags • Seat cover / upholstery fabric Monita / leather replica Morrocana, black • Sun visors with mirrors (illuminated) • LED daytime running lights • Exterior body color door handles • immobilizer
---	--

special Features	
• Trailer hitch (ball head pivots) • Winter package <i>Sitzheizung vorn</i>	• Metallic / mineral effect spraying • Sun protection glazing behind darkened (Solar -Protect)

We remind you that the data provided were taken from the DAT database. No liability can be assumed for the completeness and correctness.

General examination	
Subfloor Inspection:	not possible A visit to the underside of your vehicle could not be performed. Hoist or lifting means not available .
Mileage plausible:	not testable not testable
reference:	
Note Road Safe:	Reifen VA verschlissen

Farbabweichung Plastikteile

Accident injury assessment	
Rep. Predamages / -height gross:	no detectable As part of a paint film thickness measuring the body outer skin no previous damage could be detected .
Layers of paint thickness	Within the tolerances



measurement:	At the vehicle , a resist layer thickness measurement was carried out on the body outer skin. The measured values ??were within the tolerances of original finishes . Evidence that points to a repaired accident damage or repainting carried out , were identified.
Existing collision damage:	Not established On the vehicle body shell were on visual examination found no existing accident damages (other than the usual signs of use) .
reference:	

Overview conducted technology audit					
Alternator / Generator:			examined limited	Battery / accumulator:	
			examined limited		
oil loss:			examined limited		
air conditioning:			examined limited	lighting system:	
			examined limited		
coupling:			unavailable	exhaust System:	
			examined limited		
engine running:			examined limited	shock absorber:	
			examined limited		
transmission:			examined limited		

Performed testing technology	
Alternator / Generator:	The function of the alternator (generator) was tested using the charging indicator light in the instrument cluster .
Battery / accumulator:	The battery (accumulator) could be considered limited during the visit .
oil loss:	The vehicle could be checked only limited to oil leaks .
air conditioning:	The air conditioning system could be tested only restricted during the visit .
lighting system:	The Lichtanlage could be considered limited to the tour date .
coupling:	The vehicle has no clutch , as it is a Autmatikgetriebe or the like.
exhaust System:	The exhaust system has been tested only restricted during the visit .
engine running:	Checking the engine running was limited. Here no audible or visual abnormalities were noted .
shock absorber:	The shock absorber could be tested only restricted during the visit .
transmission:	The transmission could be examined in the context of limited test drive / pull test .
reference:	*Fahrzeug hat Alter und Laufleistungs bedingte Gebrauchsspuren innen und außen

damage



component	Damage	Rep kind
1. tailgate	Deformed (slightly)	Refurbish and paint
2. Rear bumper	Scrape	Paint
3. roof	Dented	Smart repair
4.	Worn	Replace
5.	Worn	Replace
6. Rim front - right	Scratch(es)	Paint
7. Front bumper	Damaged	Replace
8. hood	Delle	Smart repair
9. Sidewall - Rear - right	Scrape	Smart repair
10. Rim rear - right	Scratch(es)	Paint
11. exterior body	Surface scratch(es)	
12.	Wear and tear	acceptable
13.	Dirty	
14. Türeinstieg Hinten - Links	Scratch(es)	Smart repair
15. flooring	Burn hole	Smart repair
16.	Odour	Ozone treatment
17.	Scrape	Smart repair

The expert points out that the vehicle in addition to age to the damage listed in the report and may have a high mileage -related wear , as in normal use are inevitable (small bumps , dents , scratches) and thus is not entitled to change or reduction .

There shall be no liability for any defect and / or remained hidden damage in terms of electronics and mechanics accepted ,r\nand for fraudulent misrepresentation and concealed defects .

photographic record



front Left



front Right



rear Left



rear Right



inside



inside



trunk



instrument cluster



mileage



filler cap



rims



rims




rims



rims




engine compartment



service book



Others




Navigation system



1. tailgate



1. tailgate



2. Rear bumper



2. Rear bumper



2. Rear bumper



2. Rear bumper




3. roof



3. roof



3. roof



3. roof



3. roof



4.




5.



6. Rim front - right



6. Rim front - right



6. Rim front - right



7. Front bumper




7. Front bumper



7. Front bumper




8. hood



8. hood



9. Sidewall - Rear - right



9. Sidewall - Rear - right



10. Rim rear - right



10. Rim rear - right



10. Rim rear - right



11. exterior body



12.



12.



13.



13.



14. Türeinstieg Hinten - Links



14. Türeinstieg Hinten - Links



14. Türeinstieg Hinten - Links



15. flooring



15. flooring



17.



17.