


Vehicle details

VIN	W0VZX6GH8 K1075596	Brand	OPEL	Maintenance date	-
Licence Plate	14-DM-S3	Model	Insignia Grand Sport 2.0 BiTurbo 154kW GSi Exclusi	Maintenance mileage	-
Registration date	01/10/2019	Year	2019	Exterior Color	Black Metallic
Odometer	237 890 km	Engine size	1956	interior Color	Black
Fuel	Diesel	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Automatic	CO2	-
Doors	5	Gears	-		

Inspection Details

Inspection date	23/05/2025	Inspection loc.	Dekra Ayvens
-----------------	------------	-----------------	--------------



Generic equipment

Automated air-conditioning	✓
Cruise control	✓
Leather	✓
GPS system	✓
Alloy wheel rims	✓
Automatic Gearbox	✓
Heating seats	✓
Electric seats	✓
Metallic paint	✓
Central locking	✓
Electric windows	✓
Park Distance Control	✓
Audio System	✓
Led lighting	✓

Removable element

Rear parcel shelf	✓
-------------------	---


Technical Document

User manual	✓
Warranty booklet	✓
Spare key	✓
Remote key	✓

Tyres

Winter kit

Pirelli 235/45/18 Winter 3.0 mm



Pirelli 235/45/18 Winter 3.5 mm



Michelin 235/45/18 Winter 5.5 mm

Michelin 235/45/18 Winter 5.0 mm

Exterior

6



●●

Part	Alloy wheel 18"
Position	Front left
Damages	Scratched
Severity	-
Repair mode	Lumpsum repair

7



●●●

Part	Wing
Position	Front left
Damages	Dent & Chips
Severity	Diameter (mm) > 20
Repair mode	Repair

8



●●●

Part	Door
Position	Back left
Damages	Dent & Chips
Severity	Diameter (mm) > 20
Repair mode	Repair

9



●●●●

Part	Wing
Position	Back left
Damages	Dent & Chips
Severity	Diameter (mm) > 20
Repair mode	Repair


10



●●

Part	Bumper
Position	Back
Damages	Scratched
Severity	Length (cm) > 10
Repair mode	Repair

11



●●●●

Part	Wing
Position	Back right
Damages	Dented
Severity	Diameter (mm) > 20
Repair mode	Smart Repair

12



●●●●●

Part	Door
Position	Back right
Damages	Dent & Chips
Severity	Diameter (mm) > 20
Repair mode	Repair

13



●●●●●

Part	Wing
Position	Front right
Damages	Improper repair
Severity	-
Repair mode	Repair


14



●●

Part	Alloy wheel 18"
Position	Front right
Damages	Scratched
Severity	-
Repair mode	Lumpsum repair

15



●●●●

Part	Bumper
Position	Front
Damages	Scratched
Severity	Length (cm) > 10
Repair mode	Repair

16



●●

Part	Bonnet
Position	-
Damages	Scratched
Severity	-
Repair mode	Repair

17



●●●●●●●●

Part	Roof
Position	-
Damages	Hail damaged
Severity	Diameter (mm) > 20
Repair mode	Smart Repair

Interior damage

1



● ●

Part	Interior tailgate lining
Position	Down
Damages	Perforated
Severity	-
Repair mode	Replace

2



● ●

Part	Apron lining
Position	-
Damages	Perforated
Severity	-
Repair mode	Replace

3



Part	Panel lining wood/fabric
Position	Back right
Damages	Perforated
Severity	-
Repair mode	Replace

4



Part	Panel lining wood/fabric
Position	Back left
Damages	Perforated
Severity	-
Repair mode	Replace

5



Part	Steering wheel
Position	-
Damages	Worn out
Severity	-
Repair mode	For info