



Expertise

Protocol number: 38870551
Order No. / Reference: 24155659
Inspection date: 12 Mar 2025

Manufacturer: Mercedes-Benz
VIN: W1K2052131G052166

Model: C 300 de T 9G-TRONIC



Vehicle details	
Manufacturer / Type / Model / Equipment	
Mercedes-Benz C 300 de T 9G-TRONIC	
Vehicle Identification number	W1K2052131G052166
Mileage (Read)	122,720 km
First registration	5 Oct 2020
Number of holders	1
Power / Engine displacement	143 kw / 1,950 ccm
Fuel type / Cylinder	Hybr.D/E ext.aufl / 4
Gearbox / Number of gears	Automatic / 9
Type of drive	Rear drive
Type of vehicle	Station wagon
Colour / colour code	Schwarz
Doors / Seats	5 / 5
Upholstery type	Cloth
Colour of upholstery	Black-Anthracite



Vehicle details

Maintenance booklet / proof	Non-existent	Next maintenance in	0 km
Key is / should be	2 / 2	FZG documents	ZB#2 (B) was available (copy), ZB#1 (S) was not available
		LetterNo	FX668887
Previous damage / Accident	None detectable	Repainting	None detectable
Inspection conditions	Sufficient	lifting equipment / pit	yes
Test drive	Not performed	Engine function test	Performed
Manufacturer key number/ type code number	2222 / ALF 00041		
Emission standard	EURO6;WLTP;AP;PI/CI; M, N1 I	fine dust sticker	
Permitted total weight	2,480 kg	Empty weight	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	225/45 R18 95V	Winter tyres on Light alloy	Dunlop	5mm / 5mm
2)	225/40 R18 97V	Winter tyres on Light alloy	Dunlop	5mm / 5mm

Legend: Tread depth indication for left-hand tires in first place, for right-hand tires in second place on the axle in the direction of travel



Equipment

Standard equipment

- storage compartment under the loading floor
- Airbag
- Airbag: Automatic passenger airbag deactivation
- Armrest for driver and passenger foldable with compartment
- Outside mirrors left and right heated, electrically adjustable painted in body color
- Brake system with larger brake discs on the front axle
- Tachometer
- DYNAMIC SELECT
- Electronic Stability Program (ESP) with Crosswind Assist
- 4-way electric window lifter
- pedestrian protection (active bonnet)
- Transmission: Automatic 9-speed, 9G-TRONIC
- Rear window heated with timer
- Rear window wiper with interval control
- KEYLESS-GO start function
- Climate: THERMATIC automatic climate control with 2 climate zones
- Finish: Uni
- Charging cable for household socket, 5m, smooth
- Steering wheel: Multifunction sports steering wheel in black leather, 3-spoke design
- Steering: Comfort Direct Steering
- Package: AVANTGARDE Exterior
- Radio Accessories: Digital Radio
- Radio accessories: Communication module (LTE) for the use of Mercedes me connect services
- Windscreen wipers with rain sensor
- C-Class seat belts
- Seats: ISOFIX child seat attachment with Top Tether in the rear
- preparation for vehicle monitoring
- High visibility vest for drivers
- Green heat-insulating glass all around including rear window made of toughened safety glass
- ADAPTIVE BRAKE with hill start assist, pre-filling and dry braking in wet conditions
- Anti-lock braking system (ABS)
- armrest in the rear with compartment and cup holder
- ATTENTION ASSIST (the attention assistant)
- Outside temperature display
- Brake Assist, Active
- Diesel particulate filter
- Third brake light in LED technology
- ECO start-stop function
- driving light assistant
- front bumper painted in body color
- Luggage net on the side of the trunk on the left
- halogen headlights with integrated LED daytime running lights
- Interior roof fabric crystal grey
- Mechanical child safety lock for the rear doors
- instrument cluster with 2 tube-shaped round instruments
- Headrests 5-way adjustable for driver and front passenger 4-way and 2-way in the rear
- Cargo area cover including EASY-PACK safety net
- Steering column mechanically adjustable in height and length
- Mercedes-Benz emergency call system
- Upholstery: Aberdeen fabric
- Radio: Audio 20 GPS
- tire pressure monitoring system (TPMS)
- travel calculator in the multifunction display
- Service interval display ASSYST
- Seats: Rear seat backrests foldable 40/20/40 split
- Seats: Front seats electrically adjustable
- cruise control with HOLD function
- preparation for vehicle setup
- electronic immobilizer
- Central locking
- decorative elements piano lacquer look black

Extra equipment

- Trailer hitch with ESP trailer stabilization and electric release
- Package: Storage (Luggage net on the side of the trunk on the right side panel, net on the trunk floor, folding box under the loading floor, double cup holder in the center console for 2 x 500 ml (with 6-speed manual transmission), double cup holder in the center console for 2 x 750 ml (with automatic transmission), luggage net in the passenger footwell, map pockets on the back of the front seats, 2 USB ports with charging function)
- EASY-PACK tailgate (with electric operation for opening and closing and electric load compartment blind)



- Telephone accessories: multifunctional telephony (wireless connection of a compatible mobile phone to the external antenna - wireless charging for compatible mobile phones - Bluetooth and WLAN pairing wirelessly via NFC (Near Field Communication) technology)
- Package: Business PLUS (Parking package - Active parking assistant - Advanced infotainment package - Smartphone integration package - Apple CarPlay, Android Auto, media display with high-resolution media display with 10.25" diagonal, SD card navigation, live traffic preparation - Comfort package - Heated seats for driver/passenger, seat comfort package for driver/passenger: - Electric pneumatic 4-way lumbar support - Electric seat cushion inclination and mechanical seat cushion depth adjustment by 6 cm - Fuel tank with large capacity (not for 300e/de) - Light package - LED high-performance headlights, LED daytime running lights)
- TIREFIT with tire inflation compressor

Brief expert findings

Documents submitted	At the time of the inspection, the registration certificate part 2 (letter) was available, but the registration certificate part 1 (certificate) was not available. (Copy)
VIN comparison	The vehicle identification number (VIN) was read and its conformity with the documents submitted was established during the inspection by the undersigned.
Inspection	The inspection conditions were sufficient to assess the vehicle. The inspection was carried out using the lighting conditions provided by the photo system included in the report. Lifting equipment and a pit were available to examine the vehicle.
Test drive	No test drive/maneuvering was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Seat - front	Seat cover - left side - Soiled - Clean
2	Seat - front	Seat cover - right side - Soiled - Clean
3	Body	Identification plate - Missing - Replace
4	Boot lid / rear door	Boot lid - Scratched - Smart repair
5	Instrument panel	Indicator light (Batterie/Bordspannung vorhanden) - on - Perform diagnosis
6	Wheel / tyres	Tyre - front right side - Porous / cracked - Replace
7	Wheel / tyres	Tyre - rear right side - Porous / cracked - Replace
8	Misc.	Inspection / maintenance - Due - Perform
9	Bonnet	Bonnet (Sandstrahleffekt) - Stone chips - Paint
10	Side panel - rear right side	Side panel (Kratzer) - dent(s) - Repair and paint
11	Rear bumper	Rear bumper - Scratched - Paint
12	Front bumper	Front bumper (Sandstrahleffekt) - Stone chips - Paint
13	Wheel / tyres	Alloy rim - front left side (Materialabtrag) - Damaged - Replace
14	Wheel / tyres	Alloy rim - front right side (Materialabtrag) - Damaged - Replace
15	Wheel / tyres	Alloy rim - rear left side (Materialabtrag) - Damaged - Replace
16	Wheel / tyres	Alloy rim - rear right side (Materialabtrag) - Damaged - Replace
17	Vehicle glazing	Windscreen (Rissbildung) - Stone chips - Replace

Wear and tear

No.	Component group	Description
1	Headlight	Headlight - right side (Kratzer) - Stone chips - No deduction
2	Headlight	Headlight - left side (Kratzer) - Stone chips - No deduction



No.	Component group	Description
3	Body	Body (oberflächlich) - Scratch(es) - No deduction
4	Steering system	Steering wheel - Scratched - No deduction
5	Side panel - rear left side	Side panel - Scratched - No deduction
6	Trim / covers	Boot lid - interior trim - Scratched - No deduction
7	Body	A-pillar - right side - Stone chips - No deduction

The vehicle shows signs of wear consistent with its age and use.

Missing parts

Description

Wheel / tyres - Wheelset - complete (gleichwertiger Herstellerradsatz verbaut)

order/scope of the order

The order was placed to prepare a sales report on the vehicle described. This includes the following:

- Description of core relevant information about the vehicle
- Documentation of equipment features
(*delivery by third-party service providers*)
- Documentation of damage, defects, missing parts
- Documentation of previous damage, unrepaired previous damage, repainting
- a brief visual or functional inspection of the equipment details if possible.
(*Functional tests of driver assistance systems are not included in the scope of services!*)
- a photo documentation of the vehicle

Basis for the order

The basis of this product is the guideline for vehicle returns and assessments of Alphabet Fuhrpark GmbH. The expert makes the explicit findings in individual cases objectively within the framework of the specified standards based on his own expertise.

The vehicle inspection takes place in a non-disassembled condition.

Damage or defects that can only be identified during disassembly/diagnosis work or through advanced knowledge remain within the scope of the prognosis risk. An increased risk exists due to concealed defects that were caused by fraudulent deception and were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted according to the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which in their nature and severity slightly exceed normal use but do not constitute unacceptable damage will be documented and identified under signs of use if necessary.

Damage or defects which, according to the underlying standard, can no longer be attributed to normal use or wear and tear, are listed in the product under value-reducing factors.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

Neither repaired nor non-repaired previous damage to the vehicle could be determined.

Comments

- Winterradsatz ist kein Bestandteil des Auslieferumfangs.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: interior 360° view ([Online Link](#))



Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres



Figure 13: Documents



Figure 14: Navigation



Figure 15: Misc.



Figure 16: Misc.




Figure 17: Misc.



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.




Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.




Figure 27: Misc.



Damage 1: Seat - front: Seat cover - left side - Soiled - Clean



Damage 2: Seat - front: Seat cover - right side - Soiled - Clean



Damage 3: Body: Identification plate - Missing - Replace




Damage 3: Body: Identification plate - Missing - Replace



Damage 4: Boot lid / rear door: Boot lid - Scratched - Smart repair




Damage 4: Boot lid / rear door: Boot lid - Scratched - Smart repair



Damage 5: Instrument panel: Indicator light (Batterie/Bordspannung vorhanden) - on - Perform diagnosis



Damage 5: Instrument panel: Indicator light (Batterie/Bordspannung vorhanden) - on - Perform diagnosis




Damage 5: Instrument panel: Indicator light (Batterie/Bordspannung vorhanden) - on - Perform diagnosis




Damage 6: Wheel / tyres: Tyre - front right side - Porous / cracked - Replace




Damage 6: Wheel / tyres: Tyre - front right side - Porous / cracked - Replace



Damage 6: Wheel / tyres: Tyre - front right side - Porous / cracked - Replace



Damage 6: Wheel / tyres: Tyre - front right side - Porous / cracked - Replace



Damage 7: Wheel / tyres: Tyre - rear right side - Porous / cracked - Replace




Damage 7: Wheel / tyres: Tyre - rear right side - Porous / cracked - Replace




Damage 7: Wheel / tyres: Tyre - rear right side - Porous / cracked - Replace




Damage 7: Wheel / tyres: Tyre - rear right side - Porous / cracked - Replace




Damage 8: Misc.: Inspection / maintenance - Due - Perform



Damage 9: Bonnet: Bonnet (Sandstrahleffekt) - Stone chips - Paint



Damage 9: Bonnet: Bonnet (Sandstrahleffekt) - Stone chips - Paint



Damage 9: Bonnet: Bonnet (Sandstrahleffekt) - Stone chips - Paint




Damage 9: Bonnet: Bonnet (Sandstrahleffekt) - Stone chips - Paint



Damage 9: Bonnet: Bonnet (Sandstrahleffekt) - Stone chips - Paint




Damage 9: Bonnet: Bonnet (Sandstrahleffekt) - Stone chips - Paint




Damage 10: Side panel - rear right side: Side panel (Kratzer) - dent(s) - Repair and paint



Damage 10: Side panel - rear right side: Side panel (Kratzer) - dent(s) - Repair and paint




Damage 10: Side panel - rear right side: Side panel (Kratzer) - dent(s) - Repair and paint




Damage 10: Side panel - rear right side: Side panel (Kratzer) - dent(s) - Repair and paint



Damage 10: Side panel - rear right side: Side panel (Kratzer) - dent(s) - Repair and paint




Damage 10: Side panel - rear right side: Side panel (Kratzer) - dent(s) - Repair and paint



Damage 11: Rear bumper: Rear bumper - Scratched - Paint



Damage 11: Rear bumper: Rear bumper - Scratched - Paint




Damage 11: Rear bumper: Rear bumper - Scratched - Paint




Damage 11: Rear bumper: Rear bumper - Scratched - Paint




Damage 11: Rear bumper: Rear bumper - Scratched - Paint



Damage 11: Rear bumper: Rear bumper - Scratched - Paint




Damage 11: Rear bumper: Rear bumper - Scratched - Paint



Damage 12: Front bumper: Front bumper (Sandstrahleffekt) - Stone chips - Paint



Damage 12: Front bumper: Front bumper (Sandstrahleffekt) - Stone chips - Paint



Damage 12: Front bumper: Front bumper (Sandstrahleffekt) - Stone chips - Paint



Damage 12: Front bumper: Front bumper (Sandstrahleffekt) - Stone chips - Paint



Damage 13: Wheel / tyres: Alloy rim - front left side (Materialabtrag) - Damaged - Replace



Damage 13: Wheel / tyres: Alloy rim - front left side (Materialabtrag) - Damaged - Replace



Damage 13: Wheel / tyres: Alloy rim - front left side (Materialabtrag) - Damaged - Replace



Damage 14: Wheel / tyres: Alloy rim - front right side (Materialabtrag) - Damaged - Replace



Damage 14: Wheel / tyres: Alloy rim - front right side (Materialabtrag) - Damaged - Replace



Damage 14: Wheel / tyres: Alloy rim - front right side (Materialabtrag) - Damaged - Replace




Damage 15: Wheel / tyres: Alloy rim - rear left side (Materialabtrag) - Damaged - Replace



Damage 15: Wheel / tyres: Alloy rim - rear left side (Materialabtrag) - Damaged - Replace



Damage 15: Wheel / tyres: Alloy rim - rear left side (Materialabtrag) - Damaged - Replace



Damage 16: Wheel / tyres: Alloy rim - rear right side (Materialabtrag) - Damaged - Replace




Damage 16: Wheel / tyres: Alloy rim - rear right side (Materialabtrag) - Damaged - Replace




Damage 16: Wheel / tyres: Alloy rim - rear right side (Materialabtrag) - Damaged - Replace



Damage 16: Wheel / tyres: Alloy rim - rear right side (Materialabtrag) - Damaged - Replace



Damage 17: Vehicle glazing: Windscreen (Rissbildung) - Stone chips - Replace



Damage 17: Vehicle glazing: Windscreen (Rissbildung) - Stone chips - Replace



Damage 17: Vehicle glazing: Windscreen (Rissbildung) - Stone chips - Replace



Missing part 1: Wheel / tyres: Wheelset - complete (gleichwertiger Herstellerradsatz verbaut) - Missing - No deduction