

# MERCEDES-BENZ CLA CLA 250 e Shooting Brake 8G-DCT



VIN NO W1K5M8GB1PN366472 Registration Number B1PN366472

MOT Date

★ 2025-12-01

Last Service

#

**Number of Owners** 

**23:** 1

Last Service Mileage

**2** -

Number of Keys

**P**2

First Registration Date

**2**022-12-13

**Odometer Reading** 

**85322 km** 

**Country First Registered** 

Germany

## **Inspection Report Summary**

Customer	BCA Online	Report Number	P20250911101335
Inspection Date / Place	2025-09-11 / BCA Neuss	Cosmetic Grade	4

## Vehicle Summary

Vehicle Condition	Runner	VAT Type	Qualifying
Fuel Type	Plug - in Hybrid Electric Vehicle Petrol	Gearbox Type	Automatic
Colour	Black	Engine Size (cc)	1332
Engine Size	1.3	No of Doors	5
Body Type	Stationwagon / Estate	Drive Train	Front
Seat Colour		No of Seats	5
Seat Covering Name	Schwarz	Seat Covering	Cloth/Synthetic Leather
Charging Cables	Type 2	WLTP CO2 Emissions	

## Vehicle History & Documents

Service Book Available	Missing	Next Service Mileage	km
Previous Usage		Imported	No
Manufacturer Warrenty			






































# Equipment

Tow ball	Airbag Status	Anti-lock braking	Cruise control
Remote adjusting wing mirrors	Reversing Camera	Stability control	Electrically folding wing mirrors
Leather steering wheel	Rear parking sensors	USB Socket	Alloys wheels
Bluetooth telephone interface	e Front parking sensors	Remote central locking	Satellite navigation
Sunroof	Electrictailgate	Radio	


## **Equipment Details**

Tow Ball Type	Pivoted	Air Conditioning	Climate Control
Alloy Wheel Size	17	Extra Wheel / Tyre Set	Winter Tyres
Seat Heating	Front	Sunroof Type	Opening Panoramic


# Wheels & Tyres

Right Front Tyre Depth	5	Left Front Tyre Depth	5
Right Rear Tyre Depth	5	Left Rear Tyre Depth	5
Extra Wheel - 1 Tyre Depth	4	Extra Wheel - 2 Tyre Depth	4
Extra Wheel - 3 Tyre Depth	5	Extra Wheel - 4 Tyre Depth	5

## Cosmetic Damage



	Component	Damage	Comments
1	Seat / Front Left	Interior / Scratched	
2	Pillar / Back Left	Paint / Scratch / Scuff	
3	Panel Filling / Back Left	Interior / Scratched	
4	Pillar / Back Right	Paint / Scratch / Scuff	
5	Panel Filling / Back Right	Interior / Scratched	
6	Fender / Back Right	Paint / Poor Previous Repair	
7	Door / Back Right	Paint / Poor Previous Repair	
8	Roof	Paint / Chemical Damage	
9	Hood	Bodywork / Dent / Dent	
10	Door / Front Left	Bodywork / Dent / Dent	
11	Rim / Back Left	Out of Bodywork / Scratch	
12	Door / Back Right	Bodywork / Dent / Dent	



1. Seat / Front Left Interior / Scratched -

2. Pillar / Back Left Paint / Scratch / Scuff -



3. Panel Filling / Back Left Interior / Scratched -

4. Pillar / Back Right Paint / Scratch / Scuff -



5. Panel Filling / Back Right Interior / Scratched -

6. Fender / Back Right Paint / Poor Previous Repair -



7. Door / Back Right
Paint / Poor Previous Repair -

8. Roof Paint / Chemical Damage -



9. Hood Bodywork / Dent / Dent -

10. Door / Front Left Bodywork / Dent / Dent -



11. Rim / Back Left Out of Bodywork / Scratch -

12. Door / Back Right Bodywork / Dent / Dent -

#### **Mechanical Condition**

Control Lights			
Display Defect	<b>⊘</b>	ABS Warning Light	•
ESP Fault/Traction Control Malfunction Light	•	Airbag Warning Light	•
Oil Pressure Warning Light	<b>⊘</b>	Brake Warning Light	•
Power Steering Warning Light	<b>⊘</b>	Alternator / Battery	•
No Dashboard Lights	<b>②</b>	Tire Pressure Monitoring System	•
Equipments Test			
Main & Spare Keys Functioning	<b>⊘</b>	Electric Windows	<b>⊘</b>
Navigation System	<b>⊘</b>	Audio Equipment	<b>⊘</b>
Parking Sensors / Cameras Functioning	•	AC / Heating System	•
Engine			
Engine Status / EML	•	Engine Leak Visible	•
Engine Starts	•		
Gearbox			
Gear Box	•		
Hybrid/EV			
Charge Lead Condition	•	Charge Port Condition	•
Hybrid System Fault	<b>②</b>		
Levels			
Brakes Fluid	<b>⊘</b>	Coolant Fluid	<b>⊘</b>

#### **Test Drive Inspection**

description.

