



status report

customer: Bank 11, Neuss
contract number: 1034400430
reference:

vehicle data

Mercedes-Benz GLB -Klasse GLB 200

Vehicle identification number	W1N2476871W233911	mileage read:	63450 km
First Registration / construction year:	20.07.2022 / 2022	Visit Date / place of birth:	29.09.2025 Neuss
Bodywork:	SUV	Re - import:	yes
Body type:	Road /	KBA no. :	2222//AHZ
Fuel / emission class:	gasoline / € 6	transmission type:	automatic
Displacement / power:	1332 ccm / 120 kW (163 PS)	Engine:	front-wheel drive
paint:	KOSMOSSCHWARZ - METALLICLACK	Number of previous owners:	Unbekannt
Doors / seats:	5 / 7	number keys:	2
Next HU / AU:	- / -	cushion type:	Leather / fabric
Service book available:	no	Interior Color:	black
smoking vehicle:	yes	Last service km / on the:	- / -
Vehicle roadworthy:	yes	Vehicle roadworthy:	no
Submitted vehicle documents:	For example, I (Fzg.Schein)	state outside:	3 - Average
visit condition:	-	condition inside:	3 - Average
state general:	3 - Average		

Accessories (presented to the visiting time)

GPS sat nav disk:	Fzg.Schlüssel:	Service book provided / maintained:	Last service at / on:
Hard Disk Drive	2	no / -	- / -
☒ AHK key	☒ AHK removable	☒ AHK fixed	☒ AHK swivel
☒ Fernbed . entertainment	☒ Fernbed . Auxiliary heating	☒ headphone	☒ LED headlights
☒ Load compartment cover	☒ navigation system	☒ Persenning	☒ partition net
☒ Wind Deflector	☒ Xenon headlights		

☒ **available**

☒ **not available**

Hüsges GmbH
Gießerallee 23
47877 Willich
Tel.: 02154 / 9534 0
E-Mail: gutachten@huesges-group.eu

The status report was created impartially and to the best of my knowledge. The images listed in the status report are part of the vehicle description regarding the equipment and the vehicle condition.



Hüsges Gruppe®
Die Gutachter



mounted tires		
Tyre / wheel type:	summer tires	polished aluminum
1st axis - Left / states .	Pirelli	235/50/R19/99W 6 mm
1st axis - right / states .	Pirelli	235/50/R19/99W 6 mm
2nd axis - Left / states .	Pirelli	235/50/R19/99W 6 mm
2nd axis - right / states .	Pirelli	235/50/R19/99W 6 mm
traffic Safety:	roadworthy	
spare wheel:	-	
state spare wheel:	-	

standard equipment	
• Airbag deactivated • Anti- lock braking system (ABS) • Body color door mirrors • DAB tuner (digital radio reception) • Easy-entry function • Electron. Stability Program (ESP) • Driver assistance system active brake assist • • • Luggage compartment cover / shade • Infotainment-System Remote Service Plus • Keyless Go Starter System • Comfort chassis (Agility Control) • Head airbag system (Windowbag) • Light and Sight package <i>Sonnenblenden mit Spiegel (beleuchtet), Brillenfach im Dachhimmel integriert</i> • Rear center armrest • • Otto Particle Filter (OPF) • Tire Pressure Monitoring System • Rear seat backrest adjustable • Windscreen wipers with rain sensor • power steering • Start / Stop system • cruise control • USB port in the rear	• Airbag Driver / passenger side • Drive Front Wheel Drive • Pelvic airbags (pelvisbag) • Design and equipment line AMG Line <i>Styling-Paket (AMG / Exterieur), Sitz-Komfort-Paket, Kühlergrill Diamant-Optik, Dachreling (Aluminium), Innenausstattung: Zierteile Carbon-Struktur, Edelstahlpedale Sportdesign, Innenhimmel Stoff, Fußmatten AMG, Sitzbezug / Polsterung: Ledernachbildung Artico / Dinamica, Gepäcknetz / Tasche an Vordersitzlehne, Getränkehalter vorn (doppelt), Schalt-/Wählhebelgriff Leder Nappa, LM-Felgen, LM-Felgen, Lenkrad (Leder Nappa, unten abgeflacht)</i> • Off switch for headlights • Driving Assistance System Agility Select / Select Dynamic (driving mode switch) • • • Electric windows front + rear • Transmission 7 - speed dual - clutch transmission DCT • Body 5-door • Knee airbag , driver's side • Communication Module (LTE) Preparation Mercedes me connect • Steering wheel (sport) with multifunction • Mercedes- Benz emergency call system • Front center armrest with compartment • • Wheelbase 2829 mm • Rear seat backrest split / folding • Low emissions according to Euro 6d emission standard

- Side airbags (side airbag), front
- Voice control system extended functions (MBUX)
- LED daytime running lights
- Touchpad (center console)
- Central locking with remote control

special Features

- | | |
|--|--|
| <ul style="list-style-type: none"> • 3.Sitzreihe with folding bucket seats • Trailer hitch (ball head pivots) • Exterior mirrors with ambient light and projection function • Roof rails black, high gloss • Digitales Instrument Display • extinguisher • Keyless - Go package
<i>Keyless-Go Startanlage und Zentralverriegelung, Zentralverriegelung mit Fernbedienung, Keyless Go Startanlage, Heckdeckel öffnen + schliessen automatisch (Hands-Free-Access-System), Heckklappe mit automatischem Öffnungs- und Schließsystem</i> •
<i>Steckdose (12V-Anschluß) im Koffer-/Laderaum</i> • Metallic paint • Multibeam LED
<i>Fahrassistenz-System: Fernlichtassistent Adaptive plus</i> • Night package
<i>Unterfahrschutz vorn und hinten (schwarz), LM-Felgen, LM-Felgen</i> • Parking package
<i>Fahrassistenz-System: aktiver Park-Assistent, Rückfahrkamera</i> • Darkened rear side windows and rear windscreen • Heated front seats • Sound System • Vorrüstung car sharing | <ul style="list-style-type: none"> • Ambient lighting • Exterior mirrors with Blind Spot Assist • Braking system sports version • Theft protection package
<i>Diebstahl-Warnanlage + Innenraumabsicherung / Abschleppschutz</i> • Driving Assistance System Traffic Information System Live Traffic • Headliner black • Automatic air conditioning (Thermotronik) • • Center console in front with roller blind / shelf • Navigation system Hard disk navigation • Panoramic sunroof • Tyre repair kit (Tirefit) • Service system MBUX Augmented Reality for navigation • Smartphone integrated • Mirror package
<i>Außenspiegel elektr. anklappbar, Außen-/Innenspiegel mit Abblendautomatik</i> |
|--|--|

We remind you that the data provided were taken from the DAT database. No liability can be assumed for the completeness and correctness.

General examination

Subfloor Inspection: not possible
A visit to the underside of your vehicle could not be performed.

Mileage plausible:	not testable not testable
reference:	
Note Road Safe:	Batterie defekt.

Farbabweichung Plastikteile

Accident injury assessment

Rep. Predamages / -height gross:	no detectable As part of a paint film thickness measuring the body outer skin no previous damage could be detected .
Layers of paint thickness measurement:	Within the tolerances At the vehicle , a resist layer thickness measurement was carried out on the body outer skin. The measured values ??were within the tolerances of original finishes . Evidence that points to a repaired accident damage or repainting carried out , were identified.
Existing collision damage:	Not established On the vehicle body shell were on visual examination found no existing accident damages (other than the usual signs of use) .
reference:	

Overview conducted technology audit					
Alternator / Generator:			Out of order	Battery / accumulator:	
					Out of order
oil loss:			examined limited		
air conditioning:			examined limited	lighting system:	
					examined limited
coupling:			unavailable	exhaust System:	
					examined limited
engine running:			examined limited	shock absorber:	
					not possible
transmission:			examined limited		

Performed testing technology	
Alternator / Generator:	The alternator (generator) was wrong for visiting time .
Battery / accumulator:	The battery (accumulator) was discharged for visiting time .
oil loss:	**Battery deep discharge. Vehicle was bridged with a jumper.
air conditioning:	The vehicle could be checked only limited to oil leaks .
lighting system:	The air conditioning system could be tested only restricted during the visit .
coupling:	The Lichtanlage could be considered limited to the tour date .
exhaust System:	The vehicle has no clutch , as it is a Autmatikgetriebe or the like.
engine running:	The exhaust system has been tested only restricted during the visit .
shock absorber:	Checking the engine running was limited. Here no audible or visual abnormalities were noted .
transmission:	The shock absorber could not be checked during the inspection .
reference:	The transmission could be examined in the context of limited test drive / pull test .
	*Alters-, Transport- und Laufleistungsbedingte Gebrauchsspuren vorhanden. Kosten- und Schadenserweiterung möglich.

damage



	component	Damage	Rep kind
1.	Rim front - right	Damaged	Replace
2.	battery	Missing	Replace
3.	Cargo cover	Missing	Replace
4.	Blende Türe VL und HL	Scratch(es)	Replace
5.	Front door - left	Scratch(es)	Smart repair
6.	Rear bumper	Damaged	Replace
7.	Blende Stoßfänger hinten	Damaged	Replace
8.	Door Rear - right	Scratch(es)	Paint
9.	Türeinstieg Hinten - Rechts	Scrape	Refurbish and paint
10.	Front door - right		Refurbish and paint
11.	hood	Wear and tear	acceptable
12.	Windshield	Wear and tear	acceptable
13.	Front bumper	Scratch(es)	Paint
14.	proof of maintenance	Missing	Replace
15.	maintenance	Due	Replace

The expert points out that the vehicle in addition to age to the damage listed in the report and may have a high mileage -related wear , as in normal use are inevitable (small bumps , dents , scratches) and thus is not entitled to change or reduction .

There shall be no liability for any defect and / or remained hidden damage in terms of electronics and mechanics accepted ,\r\nand for fraudulent misrepresentation and concealed defects .

photographic record



front Left



front Right



rear Left



rear Right



inside



inside



trunk



instrument cluster



mileage



filler cap



rims



rims




rims




rims




engine compartment



service book



Others



Navigation system



1. Rim front - right



1. Rim front - right



3. Cargo cover



4. Blende Türe VL und HL



4. Blende Türe VL und HL



5. Front door - left



5. Front door - left



6. Rear bumper



6. Rear bumper



6. Rear bumper



6. Rear bumper



7. Blende Stoßfänger hinten



7. Blende Stoßfänger hinten



8. Door Rear - right



8. Door Rear - right



8. Door Rear - right




9. Türeinstieg Hinten - Rechts



9. Türeinstieg Hinten - Rechts




10. Front door - right



10. Front door - right




11. hood



11. hood



12. Windshield



12. Windshield



13. Front bumper



13. Front bumper