

MERCEDES-BENZ GLC GLC 300 de 4Matic 9G-TRONIC



VIN NO W1N2539111V299011 Registration Number 111V299011

MOT Date

★ 2026-04-01

Last Service

#

Number of Owners

23: 1

Last Service Mileage

2 -

Number of Keys

P2

First Registration Date

2021-04-20

Odometer Reading

102898 km

Country First Registered

Germany

Inspection Report Summary

Customer	BCA Online	Report Number	P20250530150419
Inspection Date / Place	2025-05-30 / BCA Neuss	Cosmetic Grade	3

Vehicle Summary

Vehicle Condition	Runner	VAT Type	Qualifying
Fuel Type	Plug - in Hybrid Electric Vehicle Diesel	Road Worthy	Yes
Colour	Black	Engine Size (cc)	1950
Engine Size	2.0	No of Doors	5
Body Type	SUV	Drive Train	All-Wheel-Drive permanent
Seat Colour		No of Seats	5
Seat Covering Name	Schwarz	Seat Covering	Cloth
Charging Cables	Type 2	NEDC CO2 Rating (q/km)	45
Gearbox Type	Automatic		

Vehicle History & Documents

Service Book Available	Missing	Next Service Mileage	km
Previous Usage		Imported	No
Manufacturer Warrenty			































Equipment

Tow ball	Airbag Status	Anti-lock braking	Cruise control
Digital Radio	Remote adjusting wing mirrors	Roof rails	Stability control
Electrictailgate	LED Headlamps	Rear parking sensors	USB Socket
Alloys wheels	Bluetooth telephone interface	Diesel particulate filter	Front parking sensors
Remote central locking	Satellite navigation	Electrically folding wing mirrors	Leather steering wheel

Radio


Equipment Details


Tow Ball Type	Electronic	Air Conditioning	Dual Zone Climate Control
Alloy Wheel Size	18	Seat Heating	Front

Wheels & Tyres

Right Front Tyre Depth	6	Left Front Tyre Depth	6
Right Rear Tyre Depth	6	Left Rear Tyre Depth	6

Cosmetic Damage






1. Hood Paint / Stone Chip -

2. Bumper / Front Paint / Scratch / Scuff -



3. Bumper / Front Paint / Scratch / Scuff -

4. Bumper / Front Paint / Stone Chip -




5. Door / Front Left Bodywork / Dent / Dent -

6. Bumper / Back Paint / Scratch / Scuff -




7. Bumper / Back Paint / Scratch / Scuff -

8. Tailgate Upholstery / Back Interior / Scraped -



9. Panel Filling / Back Right Interior / Scraped -

10. Door / Front Right Paint / Scratch / Scuff -



11. Panel Filling / Front Right Interior / Scraped -

Mechanical Condition

Control Lights			
Display Defect	•	Service Light	•
ABS Warning Light	•	ESP Fault/Traction Control Malfunction Light	•
Diesel Particulate Filter Light	•	Airbag Warning Light	•
Oil Pressure Warning Light	•	Brake Warning Light	•
Power Steering Warning Light	•	Alternator / Battery	•
No Dashboard Lights	•	Tire Pressure Monitoring System	•
Equipments Test			
Central Locking	•	Main & Spare Keys Functioning	•
Electric Windows	•	Navigation System	•
Audio Equipment	⊘	Parking Sensors / Cameras Functioning	•
AC / Heating System	•	Other Equipments	•
Engine			
Engine Status / EML	•	Engine Leak Visible	•
Engine Starts	•		
Gearbox			
Gear Box	⊘		
Hybrid/EV			
Charge Lead Condition	•	Charge Port Condition	•
Hybrid System Fault	•		
Levels			
Coolant Fluid	•	Brakes Fluid	NA

Test Drive Inspection

description.

Engine				
Engine Noise	•	The Gears Scratch / Skip / Abnormal Operation	•	
Fume Quantity	②	Power Loss	•	
Steering Wheel				
Steering Noise / Anomaly	•			
Brake				
Brake System Anomaly	•			
General				
Test Driven Status	•			
-	d condition or correct tests, accord etected that requires repairs by the	= = =		
Disclaimer				
Please also note the "UserG	uide condition report", which sh	ows the scope of the vehicle		Hear Cuida

User Guide