



Expertise

Protocol number: 41637072
Order No. / Reference: 25139839
Inspection date: 18 Sept 2025

Manufacturer: Mercedes-Benz
VIN: W1V44760313751299

Model: Vito 110 CDI Lang VA



Vehicle details	
Manufacturer / Type / Model / Equipment	
Mercedes-Benz Vito 110 CDI Lang VA	
Vehicle Identification number	W1V44760313751299
Mileage (Read)	65,265 km
First registration	24 Jul 2020
Number of holders	1
Next periodical technical inspection	07/2026
(Report on hand)	
Power / Engine displacement	75 kw / 1,750 ccm
Fuel type / Cylinder	Diesel / 4
Gearbox / Number of gears	Manual / 6
Type of drive	Front drive
Type of vehicle	Van
Colour / colour code	brillantsilber metallic
Doors / Seats	4 / 2
Upholstery type	Cloth
Colour of upholstery	Black



Vehicle details

Maintenance booklet / proof	digital proof / complete	Next maintenance in	319 km
Last maintenance on / at	07/2024 at 62,975 km		
Key is / should be	2 / 2	FZG documents	ZB#2 (B) was available (copy), ZB#1 (S) was not available
		Letter No.	FT695442
Previous damage / Accident	Detectable	Repainting	None detectable
Inspection conditions	sufficient	Lifting equipment / pit	yes
Test drive	Not performed	Engine function test	Performed
Manufacturer key number/ type code number	2222 / ARU 00121		
Emission standard	EURO6;WLTP;CI;PI/CI;N1 III, N2	Fine dust sticker	
Permitted total weight	2,800 kg	Empty weight	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	205/65 R16 103H	Summer tyres on Steel rim with wheel cover	Continental	6mm / 6mm
2)	205/65 R16 103H	Summer tyres on Steel rim with wheel cover	Continental	6mm / 6mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	205/65 R16 108T	Winter tyres on Steel	Continental	7mm / 7mm
2)	205/65 R16 108T	Winter tyres on Steel	Continental	9mm / 9mm

Legend: Tread depth information for tires on the left is in the first place, for tires on the right is in the second place on the axle in the direction of travel



Equipment

Standard equipment

- | | |
|---|--|
| <ul style="list-style-type: none"> • ABS, ESP, ASR, EBD, BAS • Attention Assistant • Outside temperature display • Brake light, third • Ceiling interior light • Electric window lifter driver/passenger • Seat belt warning device for driver and front passenger seats • Instrument cluster • Mercedes-Benz emergency call system • Upholstery: fabric "Tunja" black • Wheels: steel rims 6.5 J x 16 • Crosswind Assist • Front stabilizer • Cruise control • Lashing eyes in the cargo area • Maintenance interval display >>ASSYST< • Central locking with radio remote control | <ul style="list-style-type: none"> • Airbag for driver and front passenger • Exterior mirrors, manually adjustable (2) • Hill start assist • Brake lights, adaptive • diesel particulate filter • Transmission: 6-speed manual • Lockable glove box • Boot lid • Headrests (2), front • Package: BlueEFFICIENCY • Tires: 195/65 R 16 C • Key: 3-button radio remote control • Power steering • 12V socket • Partition wall continuous • Windshield washer fluid level warning light • Immobiliser |
|---|--|

Extra equipment

- | | |
|--|---|
| <ul style="list-style-type: none"> • Loading/unloading • Battery: fleece battery 12 V / 92 Ah • Comfort roof control unit • Air conditioning controlled Tempmatic • Large fuel tank, approx. 70 liters • LED light strip in the cargo area • Package: Smoker's package • Tires: 205/65 R 16 • Tire pressure monitoring • Rear view camera • Rear door double-leaf 180° without window • Key: 3-button radio remote control in conjunction with the removal of the partition wall • Seats: Comfort driver's seat • Heat-insulating glass (driver's cab) | <ul style="list-style-type: none"> • Exterior mirrors electrically adjustable and heated, left and right • Windows in rear revolving doors (with wiper-washer system) • Paint finish: metallic • Steering wheel adjustable in tilt and height • Radio: Audio 15 (high-resolution 14.7 cm (5.8") display with TFT technology - 12-key telephone keypad - RDS/single tuner and traffic information decoder (TP/TA) - Bluetooth® hands-free system - USB and Aux-in port - iPod® interface - SD memory card slot - two-way front speakers) • Seat: Lumbar support driver's seat • Seat heating on driver's side • auxiliary heater, electric |
|--|---|

Brief expert findings

Documents submitted	At the time of the inspection, the registration certificate Part 2 (letter) was available, but the registration certificate Part 1 (certificate) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was verified during the inspection by the undersigned.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and a pit were available for examining the vehicle.
Test drive	No test drive/maneuvering was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors



No.	Component group	Description
1	Door - front left side	Door edge - Scratch(es) - Smart repair
2	Door - front left side	Door - dent(s) - Smart repair
3	Boot lid / rear door	Rear door - left side - dent(s) - Smart repair
4	Door - front right side	Door - dent(s) - Smart repair
5	Body	Underbody panelling - Missing - Replace
6	Boot lid / rear door	Rear door - right side - Dent / paintcoat damage - Repair and paint
7	Sliding door, right	Sliding door - Scratch(es) - Paint
8	Vehicle glazing	Windscreen with rain sensor - Stone chips - Replace

Wear and tear

No.	Component group	Description
1	Wing mirror - left side	Cap - Scratch(es) - No deduction

The vehicle shows signs of wear commensurate with its age and use.

Missing parts

Description

Equipment - Vehicle jack
Documents - Log book

Previous damages

No.	Previous damage	Extent of damage (Net)
1	Rear, Side right, Provided by user / customer, from 25 Oct 2021	11.123,32 €

Order/Scope of order

The order was placed to prepare a sales report for the vehicle described. This includes the following:

- Description of core relevant information about the vehicle
- Documentation of equipment features
(Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of previous damage, unrepaired previous damage, repainting
- a brief visual or functional inspection of the equipment details if possible.
(Functional tests of driver assistance systems are not included in the scope of services!)
- a photo documentation of the vehicle



Basis for the order

This product is based on the guidelines for vehicle returns and valuations of light commercial vehicles from Alphabet Fuhrparkmanagement GmbH. The expert makes the explicit findings in each individual case objectively within the framework of the specified standards based on his or her own expertise.

The vehicle inspection takes place in a disassembled state.

Damage or defects that can only be detected during disassembly/diagnosis work or through advanced knowledge remain within the scope of the prognosis risk. An extended risk exists for concealed defects caused by fraudulent deception and not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted according to the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which in their nature and severity slightly exceed normal use but do not constitute unacceptable damage will be documented and identified under signs of use if necessary.

Damage or defects which, according to the underlying standard, can no longer be attributed to normal use or wear and tear are listed in the product under "Depreciating Factors".

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

According to available information previous damages were repaired at the vehicle. Traces of repairs, which allow conclusions about the area of repair, were not recognizable during the inspection.

Comments

- Winterradsatz ist kein Bestandteil des Auslieferumfangs.



ALPHABET

Figure 1: Diagonal front (left)



ALPHABET

Figure 2: Diagonal front (right)



ALPHABET

Figure 3: Diagonal rear (left)



ALPHABET

Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area



Figure 11: Cargo area



Figure 12: VIN



Figure 13: Mounted tyres



Figure 14: Documents



Figure 15: Additional tyres



Figure 16: Navigation



Figure 17: Misc.



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.




Figure 28: Misc.



Figure 29: Misc.



Figure 30: Misc.



Figure 31: Misc.



Figure 32: Misc.



Figure 33: Misc.



Damage 1: Door - front left side: Door edge - Scratch(es) - Smart repair



Damage 1: Door - front left side: Door edge - Scratch(es) - Smart repair



Damage 1: Door - front left side: Door edge - Scratch(es) - Smart repair



Damage 2: Door - front left side: Door - dent(s) - Smart repair



Damage 2: Door - front left side: Door - dent(s) - Smart repair



Damage 3: Boot lid / rear door: Rear door - left side - dent(s) - Smart repair



Damage 3: Boot lid / rear door: Rear door - left side - dent(s) - Smart repair



Damage 4: Door - front right side: Door - dent(s) - Smart repair



Damage 4: Door - front right side: Door - dent(s) - Smart repair



Damage 5: Body: Underbody panelling - Missing - Replace



Damage 6: Boot lid / rear door: Rear door - right side - Dent / paintcoat damage - Repair and paint




Damage 6: Boot lid / rear door: Rear door - right side - Dent / paintcoat damage - Repair and paint



Damage 6: Boot lid / rear door: Rear door - right side - Dent / paintcoat damage - Repair and paint



Damage 7: Sliding door, right: Sliding door - Scratch(es) - Paint




Damage 7: Sliding door, right: Sliding door - Scratch(es) - Paint



Damage 8: Vehicle glazing: Windscreen with rain sensor - Stone chips - Replace



Damage 8: Vehicle glazing: Windscreen with rain sensor - Stone chips - Replace



Damage 8: Vehicle glazing: Windscreen with rain sensor - Stone chips - Replace



Wear and tear 1: Wing mirror - left side: Cap - Scratch(es) - No deduction



Wear and tear 1: Wing mirror - left side: Cap - Scratch(es) - No deduction



Missing part 1: Equipment: Vehicle jack - Missing - Replace



Wartungshistorie

(gemäß Auftraggeber Informationen)

Fahrgestellnummer: W1V44760313751299

Hersteller / Modell: MERCEDES-BENZ MB Vito 110 CDI Lang VA

Datum	KM-Stand	Beschreibung
28.08.2024	62.975	AU; Bremse Sonstiges; Systemtest/Eigendiagnose
17.07.2024	62.975	Bremsscheiben hinten; Regelwartungsdienst
18.11.2022	49.366	Bremsscheiben vorne
29.07.2022	0	HU + AU
04.05.2022	29.031	Regelwartungsdienst